

SEPT 1982

HE 76-019-1679
E83-10258
NASA-OR-170523

Made available under NASA sponsorship
in the interest of early and wide dis-
semination of Earth Resources Survey
Program information and without liability

THEMATIC MAPPER

THEMATIC MAPPER

THEMATIC M



THE

THEMATIC MAPPER

(E83-10258) THEMATIC MAPPER FLIGHT MODEL
PRESHIPMENT REVIEW DATA PACKAGE, VOLUME 2,
PART A: SUBSYSTEM DATA Final Report
(Hughes Aircraft Co.) 276 p HC A13/MF A01



N83-26127

Unclas
CSCL 14B G3/43 00258

Prepared for
GODDARD SPACE FLIGHT CENTER
Greenbelt, Maryland 20771
CONTRACT NAS 5-24200

FLIGHT MODEL
PRESHIPMENT REVIEW
DATA PACKAGE
VOLUME II - SUBSYSTEM DATA
PART A

Article IV - 3A



HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP

BEST AVAILABLE COPY

HS 236-0019-1679



Prepared for
GODDARD SPACE FLIGHT CENTER
Greenbelt, Maryland 20771
CONTRACT NAS 5-24200

SEPT 1982

FLIGHT MODEL
PRESHIPMENT REVIEW
DATA PACKAGE
VOLUME II - SUBSYSTEM DATA
PART A

Article IV - 3A

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP

Hughes Ref No. 04896 •

THEMATIC MAPPER
FLIGHT MODEL
PRESHIPMENT REVIEW
VOLUME II
SUBSYSTEMS
TABLE OF CONTENTS

	<u>Section</u>
1.0 INTRODUCTION	1.0
2.0 SUBSYSTEMS ACCEPTANCE DATA	
Multiplexer Assembly	2.1
Multiplexer Summarized Performance	2.1.1
Multiplexer Acceptance Data	2.1.2
Scan Mirror Assembly	2.2
Scan Mirror Summary Performance	2.2.1
Scan Mirror Acceptance Data	2.2.2
Power Supply Assembly	2.3
Power Supply Summarized Performance	2.3.1
Power Supply Acceptance Data	2.3.2
Mainframe/Top Mechanical Assembly	2.4
Mainframe/Top Mechanical Summarized Performance	2.4.1
Mainframe/Top Mechanical Acceptance Data	2.4.2
Aft Optics Assembly	2.5
Aft Optics Summarized Performance	2.5.1
Aft Optics Acceptance Data	2.5.2
Focal Plane Assembly	2.6
Focal Plane Summarized Performance	2.6.1
Focal Plane Acceptance Data	2.6.2
Radiative Cooler	2.7
Radiative Cooler Summarized Performance	2.7.1
Radiative Cooler Acceptance Data	2.7.2

ORIGINAL PAGE IS
OF POOR QUALITY

THEMATIC MAPPER
FLIGHT MODEL
PRE SHIPMENT REVIEW
VOLUME II
SUBSYSTEMS

TABLE OF CONTENTS
(Continued...)

	<u>Section</u>
Radiative Cooler Door Assembly	2.8
Radiative Cooler Door Summarized Performance	2.8.1
Radiative Cooler Door Acceptance Data	2.8.2
Top Optical Assembly	2.9
Top Optical Summarized Performance	2.9.1
Top Optical Acceptance Data	2.9.2
Telescope Assembly	2.10
Telescope Summarized Performance	2.10.1
Telescope Acceptance Data	2.10.2
Relay Optics	2.11
Relay Summarized Performance	2.11.1
Relay Acceptance Data	2.11.2
Electronics Module	2.12
Electronics Summarized Performance	2.12.1
Electronics Acceptance Data	2.12.2
Cable Harness	2.13
Cable Harness Summarized Performance	2.13.1
Cable Harness Acceptance Data	2.13.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.0 Subsystems Acceptance Data

Each of the major subsystems of the Flight Model Thematic Mapper was reviewed as an entity prior to integration into the system. The intent of this section is to present for each major subsystem, acceptance data for the subsystem (test results); reference lists of the configuration status; and reference lists of Non-Conforming Material Reports, Failure Reports (with copies), and Requests for Deviation/Waiver (with copies).

The acceptance data for each subsystem (where applicable) is contained in the Appendix to this report, as referenced in the first subsection for each subsystem.

The second subsection for each subsystem contains a tabular summary of the "as designed" and "as built" configuration lists, showing all applicable drawings, specifications, or standards. (An "as built" configuration list for the total system is included in Volume I and is also included herein immediately following this page). This is followed by a listing of all items against the subsystem, with copies of NCRM's, RT's, and RD/W's.

SUMMARY
AS-BUILT CONFIGURATION LIST
TM FLIGHT S/N 003

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	51065	THEMATIC MAPPER ASSY	J	J	J	003
			4257A	4257A	4257A	
			4487A	4487A	4487A	
			4557A	4557A	4557A	
			4573A	4573A	4573A	
			4643A	4643A	4643A	
			4658A	4658A	4658A	
			D143R1	D143R1	D143R1	
			D144	D144	D144	
			D146	D146	D146	
			D148	D148	D148	
			D155	D155	D155	
			D158	D158	D158	
			D161	D161	D161	
			D162	D162	D162	
			D163	D163	D163	
			D164	D164	D164	
			D165	D165	D165	
			W166	W166	W166	
			W169	W169	W169	
			W170	W170	W170	
			W171R1	W171R1	W171R1	
			W173	W173	W173	
2	50840	MAIN FRAME ASSY	E	E	E	003
2	52347	ELECTRONICS MODULE ASSY	D	B	B	201
			4588A	4091A	4091A	
				4113A	4113A	
				4242A	4242A	
				4293A	4293A	

ORIGINAL PAGE IS
OF POOR QUALITY

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	3533003-100	MULTIPLEXER ASSY	C 43009 43074 65661 65662 W124 W125	C 43074 65661 65662 W124 W125	C 43009 43074 65661 65662 W124 W125	003
3	50869	POWER SUPPLY ASSY	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	004
3	52348	CABLE ROUTING ASSY	F 3844A	F 3844A	F 3844A	005
2	52532	OPTICAL ASSY	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	003
3	51512	AFT OPTICS ASSY	E 3646A 3925A 3959A 4585A	D 3646A 3896A 3925A 3959A 4134A	D 3646A 3896A 3925A 3959A 4134A	003

ORIGINAL PAGE IS
OF POOR QUALITY

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	50795	PRIME FOCAL PLANE ASSY	J W126	H 3934A 3968A 3982A W126	H 3934A 3968A 3982A W126	201
3	51200	RADIATIVE COOLER ASSY	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	003
4	50973	COLD FOCAL PLANE ASSY	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	201
3	51337	TELESCOPE ASSY	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	002

ORIGINAL PAGE IS
OF POOR QUALITY

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	52534	RELAY OPTICS ASSY	D 1145A 4097A	D 1145A 4097A	D 1145A 4097A	003
2	3533002-100	SCAN MIRROR ASSY	E	D 13121 13122 64358 64363 64369 64374 W020	D 13121 13122 64358 64363 64369 64374 W020	004

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.1
MULTIPLEXER

Section 2.1.1.

Multiplexer

Performance Data

The acceptance performance (test) data for the Multiplexer
is contained in Appendix A of this report (Vol IV, part A).

2.1.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.1.2

Acceptance Data

2.1.2.1

2.1.2.1
Configuration Lists

AS-BUILT CONFIGURATION LIST

MULTIPLEXER
3533003-100 S/N 3

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3533003-100	MULTIPLEXER	C 43009(R) 43074 65661 65662 W124 W125	C 43074 65661 65662 W124 W125	C 43009 43074 65661 65662 W124 W125	3
	3533003-200	MULTIPLEXER	D	D	D	
	3533003-500	MULTIPLEXER	G 65604 65670	G 65604 65670	G 65604 65670	
	3533003-600	PIN/SIGNAL LIST	B 65659	B 65659	B 65659	
	259989	GROUND & VOLTAGE BUS	A	A	A	
	3362049	WASHER	-	-	-	
	3489200	HEATSINK	-	-	-	
	3569200	CONNECTOR	-	-	-	
	3569201-2	CONNECTOR	- 43055	- 43055	- 43055	
	3569202	ALTERNATE MATL HS236	A	A	A	
	3569203	CABLE ASSY, TWINAX	C 65612 65696	C 65612 65696	C 65612 65696	
	3569204-1	CHANNEL SHIM	C	C	C	

ORIGINAL PAGE IS
OF POOR QUALITY

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569205	CABLE ASSY	B	B	B	
	3569206-2	GASKET	A 11457	A 11457	A 11457	
	3569207	SHIM, RF CONNECTOR	-	-	-	
	3569208	MULTIPLEXER	A 43003 43064 65600 65649 65674	A 43003 43064 65600 65649 65674	A 43003 43064 65600 65649 65674	
	3569209	MULTIPLEXER	A 43004 43066 43088	A 43004 43066 43088	A 43004 43066 43088	
	3569210	MULTIPLEXER	E 65673 65692	E 65673 65692	E 65673 65692	3
	3569211	WIRE LIST	F 43060 43097 65614 65660	F 43060 43097 65614 65660	F 43060 43097 65614 65660	
	3569213	COVER	D	D	D	
	3569214	COVER, TOP REAR	D 43072	D 43072	D 43072	
	3569215	TEMP COVER	B	B	B	
	3569216	CHASSIS ASSY	B	B	B	
	3569218	CHANNEL CONNECTOR PLATE	D 11428 11469(P)	D 11428	D 11428 11469	
	3569219	PLATE, REAR	C	C	C	

ORIGINAL PAGE IS
OF POOR QUALITY

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569220	PLATE CHASSIS	D 11470(P)	D	D	
	3569221	PLATE CHASSIS	B 11471(P)	B	B	
	3569222	PLATE, FRONT	D 11472(P)	D	D	
	3569223	BUS ASSY	- 11497	- 11497	- 11497	
	3569224	MODULE	F 65637 65677 65685(P) 65694 D026 D086	F 65637 65677 65694 D026 D086	F 65637 65677 65685 65694 D026 D086	
	3569225	PRINTED WIRING BOARD	D 43080	D 43080	D 43080	
	3569226	HEATSINK	C	C	C	
	3569228	PRINTED WIRING BOARD	F 11492(P) 11494 43087 D018	F 11494 43087 D018	F 11492 11494 43087 D018	
	3569229	ALTERNATE DESIGN	C 65642	C 65642	C 65642	
	3569234	MODULE	D 43010 43037 65626 65646 65668	D 43010 43037 65626 65646 65668	D 43010 43037 65626 65646 65668	3

ORIGINAL PAGE IS
OF POOR QUALITY

NO. VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569235	ALTERNATE WIRING	A 65641 65643 65676(P)	A 65641 65643	A 65641 65643	
	3569240	MODULE	E 11464(P) 43011 D014 D084	E 43011 D014 D084	E 43011 D014 D084	3
	3569241	ALTERNATE WIRING	G 65617 65627 65628 65634	G 65617 65627 65628 65634	G 65617 65627 65628 65634	
	3569247	MODULE	D 11465(P) 43012 43039 43048 D028 D083	D 43012 43039 43048 D028 D083	D 43012 43039 43048 D028 D083	3
	3569248	ALTERNATE WIRING	D 43083	D 43083	D 43083	
	3569254	MODULE	F 11466(P) 43013 43040 65603(C) D013 D082	F 43013 43040 D013 D082	F 43013 43040 65603 D013 D082	3
	3569255	ALTERNATE WIRING	H	F 43085 43090 43091 43093 43094	F 43085 43090 43091 43093 43094	3

3 ORIGINAL PAGE IS
OF POOR QUALITY

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569261	MODULE	G D012 D059 D081 D106	G D012 D059 D081 D106	G D012 D059 D081 D106	3
	3569262	ALTERNATE WIRING	E 65682(P) 65687(P) 65698	E 65698	E 65682 65687 65698	ORIGINAL PAGE IS OF POOR QUALITY
	3569264	ALTERNATE DESIGN WIRING	- 65622 65636 65693	- 65622 65636 65693	- 65622 65636 65693	
	3569268	TB ASSY	A 11420 11448(R) 11449	A 11420 11449	A 11420 11449	
	3569269	COMPONENT ASSY	B	B	B	3
	3569270	INSULATOR BOARD	A	A	A	
	3569272	MDL FILTER ASSY	B	B	B	5
	3569273	FILTER FRAME	-	-	-	
	3569277	MULTIPLEXER	A 43032 43045 43050 43058 43063	A 43032 43045 43050 43058 43063	A 43032 43045 43050 43058 43063	3
	3569278	CONVERSION UNIT	B	B	B	
	3569279	COVER	B	B	B	
	3569280	COVER	A 11444	A 11444	A 11444	


IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569282	WIRE LIST	D 43054 (R) 43061 43076	D 43061 43076	D 43054 43061 43076	
	3569283	COMPONENT BOARD ASSY	C	C	C	
	3569284	TERMINAL ASSY	A	A	A	
	3569285	ALTERNATE PARTS	- 65658 65669	- 65658 65669	- 65658 65669	
	3569290	CONNECTOR PLUG	C	C	C	
	3569291	NUT, HEXAGON	-	-	-	
	3569292	TRANSFORMER	A	A	A	
	3569293	1024 BIT-PROM	A W026	A W026	A W026	
	3569300	WIRE WRAP	D 43001 43005	D 43001 43005	D 43001 43005	
	3569301	FILTER ASSY	B	B	B	
	3569309	INDUCTOR	A	A	A	10,11, 12,24, 45,56
	3569314	INTERCONNECTION	E	E	E	
	3569315	SCHEMATIC DIAGRAM	C 65691	C 65691	C 65691	
	3569316	SCHEMATIC DIAGRAM	E 65679 65689(P)	E 65679	E 65679 65689	
	3569317	SCHEMATIC DIAGRAM	B	B	B	

ORIGINAL PAGE IS
OF POOR QUALITY

TND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3569318	SCHEMATIC DIAGRAM	E	E	E	
	3569319	SCHEMATIC DIAGRAM	D	D	D	
	3569320	SCHEMATIC DIAGRAM	C	C	C	
	3569321	SCHEMATIC DIAGRAM	D	D	D	
	3569322	SCHEMATIC DIAGRAM	C	C	C	
	3569323	SCHEMATIC DIAGRAM	D	D	D	
	3569324	SCHEMATIC DIAGRAM	E	E	E	
	3569328	INTERCONNECTION	G 65684(P) 65695	G 65695	G 65684 65695	
	3616302	CABLE	A	A	A	
	3905969	HYBRID-INPUT	A 11445 11459 11476 11477 D0010	A 11445 11459 11476 11477 D0010	A 11445 11459 11476 11477 D0010	
	3905970	SCHEMATIC DIAGRAM	B	B	B	
	3905971	HYBRID-INPUT	A	A	A	
	3905973	MICROCIRCUIT	D 11446 11460 11479 D0010	D 11446 11460 11479 D0010	D 11446 11460 11479 D0010	

ORIGINAL PAGE IS
OF POOR QUALITY

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEP. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	3905977	MICROCIRCUIT	C 65699(N) D0010	C D0010	C D0010	



 QUALITY ASSURANCE

12/17/81
 DATE



 CONFIGURATION/DATA MANAGEMENT

12/17/81
 DATE

ORIGINAL PAGE IS
 OF POOR QUALITY

2.1.2.2.

MULTIPLEXER

Listing of Liens

MULTIPLEXER

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 3569210

FLIGHT

PROTOFLIGHT

ENGINEER

Failure Report.
No.

Failure Report
No.

Failure Report
No.

FLIGHT		PROTOFLIGHT		ENGINEER	
Failure Report. No.		Failure Report No.		Failure Report No.	
Open	Closed	Open	Closed	Open	Closed
F3658- (Spare)	F0372		F0360		F0547
	F0373		F0361		F1938
F4252- (Spare)	F0374		F3062		F2755
	F0381		F0363(Void)		F5184
	F2808		F0364		
	F2812		F0365		
	F2813		F0366		
	F2814		F0367		
	F2815		F0368		
	F2816		F0369		
	F2817		F0370		
	F2818		F0371		
	F2819		F0375		
	F2820		F0376		
	F2821		F0377		
	F2822		F0378		
	F2823		F0379		
	F2824		F0380		
	F2825		F0383		
	F3657		F0384		
	F3660		F0385		
	F4253		F0386		
	F4254		F0387		
	F4255		F0388		
	F4256		F0389		
	F4257		F0390		
	F4265		F0391		
	F4266		F1919		
	F4267		F1920		
	F4268		F1921		
	F7295		F1922		
	F7296		F1923		
	F7299		F1924		
			F1925		
			F1926		
			F1927		
			F1928		

*Spare PWB
Failed at card level (3569224)

MULTIPLEXER

P/N 3569210

FLIGHT MODEL

ORIGINAL PAGE IS
OF POOR QUALITY

Failure Report Numbers

Open	Closed
F3658(Spare)	F0372
F4252(Spare)	F0373
	F0374
	F0381
	F2808
	F2812
	F2813
	F2814
	F2815
	F2816
	F2817
	F2818
	F2819
	F2820
	F2821
	F2822
	F2823
	F2824
	F2825
	F3657
	F3660
	F4253
	F4254
	F4255
	F4256
	F4257
	F4265
	F4266
	F4267
	F4268
	F7295
	F7296
	F7299

Deviation

Waivers

	Closed
	W-124
	W-125

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 037

1. PROGRAM NAME AND NUMBER <i>THOMAS MAPPER</i>		2. QLA <i>E330</i>	3. MODEL <i>PLT</i>	4. TIME OBSERVED <i>0900</i>	5. DATE OBSERVED <i>11/19/80</i>
6. HARDWARE LEVEL WHICH FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> INCARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	
8. UNIT <i>Multiplexed</i>		<i>3569210</i>		<i>3 Mac</i>	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input checked="" type="checkbox"/> MODULE <input type="checkbox"/> INCARD <input type="checkbox"/> CARD <i>A2</i>		<i>3569254</i>		<i>3 Mac</i>	
11. OTHER					
12. TEST WHICH FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROGRESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHICH FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ALTITUDE <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AIRS FOR <input type="checkbox"/> MFR <input type="checkbox"/> TYP <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Serial Data output pattern has wrong format</i>					
15. TEST PROCEDURE <i>92015-005</i>		16. ORGANIZATION <i>Regina S. Hall</i>		17. TESTING SHEET <input type="checkbox"/>	
18. VERIFICATION AND ANALYSIS <i>All wiring 3569254 implemented wrong on case pin A30. Wiring from A20 to U20-7 and U20-7 should go to U20-7, on front Assy. See item 30. For stress analysis.</i>					
19. FOLLOWING PROCEDURE MUST BE OBSERVED REPAIR/RETEST NOT REQUIRED UNLESS		18. FAILED ITEM NUMBER AND PART NUMBER <i>3569210</i>			
<i>Remove wire, reset module in unit successfully.</i>					
20. APPROVAL BY <i>RL Julian</i>		21. AUTHORIZED BY <i>RL Julian</i>		22. CONTIN. SHEET U <i>11-41 11/19/80</i>	
23. REPAIR/RETEST ACTION TAKEN <i>RETESTED THE UNIT, OUTPUT DATA FORMAT IS CORRECT</i>					
24. LIST ALL PARTS REPLACED					
PART NUMBER					
CMT SYN					
PART LOT NO.					
DATE CODE					
VFR					
PRODUCTS DEFECT					
ANALYSIS NO.					
25. REVIEW BY <i>78816</i>		26. DATE <i>8-19-80</i>		27. REVIEWED BY <i>H. Rajani</i>	
28. CAUSE AND CORRECTIVE ACTION <i>NOTE: No possibility of card stress due to this wire loop. All currents in spec. U20-7 double load current 40 ma vs spec 50 ma cone 100</i>		29. CAUSE <i>OPERATOR ERROR</i>		30. PRO. CLOSURE	
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>ALTERNATE WIRING.</i>		32. CONTINUATION SHEET USED <input type="checkbox"/>			
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> OBSOLETE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNIFORM <input type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCED <input type="checkbox"/>		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY			
36. RESPONSIBLE ENGINEER <i>RL Julian</i>		37. SPACECRAFT SYSTEMS ENGR. <i>H. A. Fournier</i>		38. DATE <i>11/21/80</i>	
39. RELIABILITY <i>15-41 11/19/80</i>		40. CUSTOMER OR SUPPLIER <i>B-6</i>		DATE	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0373

1. PROGRAM NAME AND REASON <i>NS 135 THEMATIC MAPPER</i>		2. QLA <i>E330</i>	3. MODE <i>FLT</i>	4. TIME OBSERVED <i>11:00</i>	5. DATE OBSERVED MO <i>8</i> DA <i>21</i> YR <i>8</i>
6. HARDWARE LEVEL WHERE FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION: NAME PART NUMBER SN MANUFACTURER					
8. UNIT <i>F1 MULTIPLEXER</i>		3569210		31 HAC	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IMPROVISED <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ASSOCIAT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° <input type="checkbox"/> THERMAL VAC _____ HR. AT _____ ° <input type="checkbox"/> CIRCUT <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ NEW TYPE _____ OTHER _____					
14. DESCRIPTION OF FAILURE <i>A/D REFERENCE VOLTAGES OF BANDS 1 & 5 ARE LOW. 1.985 V6 AND 1.981V. RESPECTIVELY (LIMITS ARE 2.000 ± 15 MV).</i>					
15. TEST PROCEDURE <i>TP 3205-005 PARA 3.5.1</i>		16. ORIGINATOR <i>H. Kharin</i>		17. CONTINUAL ENG'T USED ORG <i>41-41</i> DATE <i>8/2/80</i>	
18. VERIFICATION AND FAILURE ANALYSIS <i>ANALOG & DIGITAL RETURNS OF ALL ANALOG BOARDS (A5-A7, A9-A12) ARE REVERSED, I.E. ANALOG RETURN IS CONNECTED TO THEIR OWN SLOT & DIGITAL TO ANALOG.</i>					
19. <input checked="" type="checkbox"/> POLL CHECKS REQUIRED (NOT TEST REQUIRED) RECONNECT THE GROUND BRIDGE CORRECTLY PER DRAWING					
20. AUTHORIZATION <i>K. Mc</i> ORG <i>41-41</i> DATE <i>8/2/80</i> CONTINUAL ENG'T USED					
21. REPEAT TEST ACTION TAKEN <i>RETESTED THE UNIT (INPUT BUFFER DC RESPONSE) ALL REFERENCE VOLTAGES ARE IN SPEC. 2.000 ± 15 MV (BAND-6 LIMITS ARE 1.980V ± 15 MV)</i>					
22. LAST ALL PARTS REPLACED					
23. REPORT BY <i>28518</i> ORG _____ DATE <i>9/4/80</i> 24. RETESTED BY <i>M. Kharin</i> ORG <i>41-41</i> DATE <i>9/4/80</i> CONTINUAL ENG'T USED					
25. CAUSE AND CORRECTIVE ACTION <i>NO POSSIBILITY OF COMPONENT STRESS DUE TO THIS OCCURRENCE.</i>					
26. CAUSE: <i>OPERATOR ERROR</i> <i>A. H. Kharin</i> <i>E/A: OPERATOR INSTRUCTED TO VERIFY WIRING TO BLUE PRINT.</i> <i>A. H. Kharin</i>					
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
28. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> OPER. IN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/PKG ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
29. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> INCURD <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
30. RESPONSIBLE ENGINEER <i>R. L. Sullivan</i> ORG <i>41-41</i> DATE <i>11/15/80</i>		31. SPACECRAFT SYSTEM ENGR <i>M. J. ...</i> ORG <i>22-4</i> DATE <i>3/19/81</i>		32. CUSTOMER OR SUPPLIER <i>...</i> ORG <i>...</i> DATE <i>...</i>	
33. RELIABILITY <i>...</i> ORG <i>...</i> DATE <i>...</i>					

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0374

1. PROGRAM NAME AND NUMBER MS 236 THEMATIC MAPPER		2. QLA E330		3. MODEL FLT.		4. TIME OBSERVED 4:50		5. DATE OBSERVED MO 3 DA 3 YR 8			
6. HAZARD LEVEL (CHECK FAILURE WAS OBSERVED)		<input type="checkbox"/> SPACECRAFT	<input type="checkbox"/> SUBSYSTEM	<input type="checkbox"/> ASSEMBLY	<input type="checkbox"/> MODULE	<input type="checkbox"/> CARD	<input type="checkbox"/> SYSTEM	<input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> LOCAL	<input type="checkbox"/> PART
7. EQUIPMENT IDENTIFICATION: NAME PART NUMBER SYN MANUFACTURER											
8. SUBSYSTEM											
9. UNIT MULTIPLEXER 3569210 3 HAC											
10. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
11. <input type="checkbox"/> MODULE <input type="checkbox"/> LOCAL <input type="checkbox"/> CARD											
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS											
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HUMIDITY <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXES FOR <input type="checkbox"/> SIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER											
14. DESCRIPTION OF FAILURE AT INPUT BUFFER DC RESPONSE; OUTPUT READINGS OF ALL SENSORS ARE WRONG.											
15. TEST PROCEDURE TP 32015-005, PARA 3.5.3. 16. ORIGINATOR H. Khajouli ORG 141-41 DATE 19/4/80 CONTINUAL SHEET USE											
17. VERIFICATION AND FAILURE ANALYSIS AT CARD A1, SOLDERED WIRES AT PINS XA01-C6 & XA01-C7 (DC-RESTORE & DC-RESTORE BACKUP) ARE TOUCHING. THIS CAUSES THE SIGNAL TO STAY LOW AND DISABLES DC-RESTORE INPUT TO UNIT. THE TWO TOUCHING PINS CARRY MULTIPLEXER 3569210											
18. FOLLOWING REMEDIAL ACTION REQUIRED: AT DIFFERENT LEVELS (HIGH & LOW) AND PLACE SHRINK TUBING ON BOTH PINS. RETEST PER TP 32015-005, PARA. 3.5.3!											
19. AUTHORIZATION KD Wern ORG 141-41 DATE 19/4/80 CONTINUAL SHEET USE											
20. REMEDIAL ACTION TAKEN REMOVE SOLDER WIRE											
21. RETESTED OR Reworked OK per TP 32015-005, PARA. 3.5.3!											
22. LIST ALL PARTS REPLACED											
23. REVIEWED BY 81200 ORG 17/5/80 24. RETESTED BY H. Khajouli ORG 141-41 DATE 19/5/80 CONTINUAL SHEET USE											
25. CAUSE AND CORRECTIVE ACTION NOTE: NO POSSIBILITY OF PART STRESS DUE TO THIS FAILURE. SEE ITEM 18. CAUSE: WIRE WRAP PINS TOUCHING. R/A: SERVICED THE PINS AND USE CAUTION WHEN WORKING ON UNIT. H. H. Signature											
26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION											
27. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> LABORATORY											
28. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNUSUAL <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE											
29. RESPONSIBLE ENGINEER J. J. Signature ORG 141-41 DATE 11/11/78 30. SPACECRAFT SYSTEM ENGR. H. Khajouli ORG 12261 DATE 2/10/80											
31. RELIABILITY 151-41 DATE 11/11/78 32. CUSTOMER OR SUPPLIER 9A 518151											

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

DUPLICATE ORIGINAL
F 0381

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER HS236		2. CLA E330	3. MODEL FLT	4. TIME OBSERVED 01530	5. DATE OBSERVED MO 10 DA 7 YR 8
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	QTY	MANUFACTURER
8. UNIT MULTIPLEXER			3569210	3	HAC
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY A1			3569261	3	HAC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ ° _____ THERMAL VAC _____ V IS AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ M20 TYPE _____ <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE AFTER INCORPORATING SMA E.O. NO BACKUP JMA CLK OUTPUT					
15. TEST PROCEDURE 3569261		16. PARA	17. OPERATOR R. YAMAUCHI	18. DATE 10-7-80	19. CONTINUATION SHEET USE <input type="checkbox"/>
20. VERIFICATION AND FAILURE ANALYSIS PRINTED CIRCUIT DAMAGED BETWEEN RS AND QR ON FRONT ASSY. NOTE: NO POSSIBILITY OF COMPONENT DAMAGE OPEN CIRCUIT AT QR BASE CAUSES OUTPUT OF LOGIC '1' BUT DOES NOT APPL OUT-OF-SPECIFICATION VOLTAGES OR CURRENTS. ^{15. FAILED ITEM NUMBER AND PART NUMBER} 3569261					
21. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REW 20K/RETEST NOT REQUIRED BECAUSE REPAIR AS NECESSARY PER PRODUCT DESIGN INSTRUCTIONS					
21. AUTHORIZATION R. Mc		18. DATE 10-7-80	22. CONTINUATION SHEET USE <input type="checkbox"/>		
22. REWORK/RETEST ACTION TAKEN ADDED JUMPER WIRE FROM RS (BOTTOM) TO QR-BASE PER NSMR 33851P					
23. LIST ALL PARTS REPLACED					
PART NUMBER	QTY	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
27. REWORK BY 16552		ORG 49-21	DATE 10-10-80	28. REQUESTED BY U. Williams	DATE 10/15/80
29. CAUSE AND CORRECTIVE ACTION Operator error - damage either during test or rework to incorporate Jan EO. Both test operator and rework operator were cautioned.					
30. CONTINUATION SHEET USED <input type="checkbox"/>					
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		35. FAILURE TYPE <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> INDUCED		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY	
37. RESPONSIBLE ENGINEER R. L. Julian		DATE 10-4-81	DATE 6/23/81	38. SYSTEM ENGINEER Hal...	DATE 2261 8/10/82
39. RELIABILITY		ORG	DATE	40. CUSTOMER OR SUPPLIER	DATE

[Handwritten signature]
6/24

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2808

1. PROGRAM NAME AND FACILITY <i>THOMAS MARKER</i>		2. ORG <i>EP320</i>	3. COMM <i>FLT</i>	4. TIME OCCURRED <i>0930</i>	5. DATE RECEIVED <i>3 25 70</i>
6. MALFUNCTION LEVEL (CHECK ALL THAT APPLY) 6a. OCCURRED <input type="checkbox"/> 6b. SUSPECTED <input type="checkbox"/> 6c. ALARM <input type="checkbox"/> 6d. CASO <input type="checkbox"/> 6e. DETECTED <input type="checkbox"/> 6f. LOST <input type="checkbox"/> 6g. SUBSEQUENTLY <input type="checkbox"/> 6h. REPAIR <input type="checkbox"/> 6i. PART <input type="checkbox"/>					
7. SUBSYSTEMS <i>FLT</i>					
8. UNIT <i>Multi-plexer</i>		9. PART NUMBER <i>3593009-100</i>		10. LOT <i>400</i>	
11. OTHER		12. SERIAL		13. CLASS	
14. TEST INFO (CHECK ALL THAT APPLY) 14a. DEVELOPMENT <input type="checkbox"/> 14b. QUALIFICATION <input type="checkbox"/> 14c. INTRODUCTION <input type="checkbox"/> 14d. LATEST OPERATIONS <input type="checkbox"/> 14e. PRODUCTION <input checked="" type="checkbox"/> 14f. ACCEPTANCE <input type="checkbox"/> 14g. FLIGHT <input type="checkbox"/>					
15. OPERATIONAL HISTORY (CHECK ALL THAT APPLY) 15a. ACCEPT <input type="checkbox"/> 15b. REJECT <input type="checkbox"/> 15c. REWORK <input type="checkbox"/> 15d. REPAIR <input type="checkbox"/> 15e. REUSE <input type="checkbox"/> 15f. REUSE <input type="checkbox"/> 15g. REUSE <input type="checkbox"/>					
16. DESCRIPTION OF FAILURE <i>Channel 11 and 12 shorted together. B42 and B43 shorted by soldering output connector connections to PWB.</i>					
17. TEST RESULTS <i>359224</i>		18. OPERATOR <i>YAMAUCHI</i>		19. TEST CENTER <i>581</i>	
20. INVESTIGATIVE AND ANALYSIS <i>Pin B42 and A43 soldered together</i>					
21. PROCESSES (TEST RATE AND PART NUMBER) <i>359224</i>					
22. HOW FAILURE HISTORY AND REPAIRS (CHECK ALL THAT APPLY) <i>Resolder to point - Resoldered bridge and test</i>					
23. RESPONSIBILITY (CHECK ALL THAT APPLY) <i>Resolder to point removed solder bridge and test</i>					
24. ALL PARTS REPLACED <i>All parts replaced by this failure function properly. Retested OK. P/N 359224-100</i>					
25. RECORDING OF <i>19224</i>					
26. CAUSE AND CORRECTIVE ACTION <i>Removal Solder bridge 3/24/70 change workmanship in manufacture - reworked and operator cautioned</i>					
27. OCCURRENCE REPORTING (CHECK ALL THAT APPLY) <i>NONE</i>					
28. BASIC FAILURE MODES (CHECK ALL THAT APPLY) <i>DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. INCOMPLETE <input type="checkbox"/> ASY. TAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> AIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> IN-RATE <input type="checkbox"/> USER ERROR <input type="checkbox"/> SAFETY <input type="checkbox"/></i>					
29. FAILURE TYPE <i>INCORRECT</i>					
30. FAILURE CLASSIFICATION <i>CRITICAL</i>					
31. REPORTING ENGINEER <i>R. J. Sullivan</i>		32. FACTORY SYSTEM ENGINEER <i>L. J. Sullivan</i>		33. CUSTOMER OR USER <i>581C</i>	
34. DATE <i>4-1-70</i>		35. DATE <i>6/24/70</i>		36. DATE <i>6/24/70</i>	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 281

1. PROGRAM NAME AND NUMBER <i>Thermostic Mixer 42226</i>		2. CL. <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>0900</i>	5. DATE OBSERVED <i>5/28/80</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM <i>FLT</i>		NAME		PART NUMBER	MANUFACTURER
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>	<i>HAC</i>
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <i>AG</i>				<i>3569224</i>	<i>17 HAC</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST IN WHICH FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT UNDER WHICH FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MISC. AT <input type="checkbox"/> OSCILLATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> USE TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Char. 4 DC Restore, DC Level Change</i>					
15. TEST PROCEDURE <i>3569224 PARA 5.1.2.1</i>					
16. VERIFICATION AND FAILURE ANALYSIS <i>VERIFIED TO Input Buffer by Isolating output pin 40.</i>					
17. FAILED ITEM NAME AND PART NUMBER <i>HYBRID I/O. 3905969</i>					
18. FOLLOWING REPAIR/RETEST REQUIRED REPAIR/RETEST NOT REQUIRED BECAUSE <i>Replace input buffer hybrid HVI and test sub-assembly normally. Retain hybrid for failure analysis.</i>					
19. REPAIR/RETEST ACTION TAKEN <i>Replaced HVI on Front Assy</i>					
20. RETESTED BY <i>RETESTED per T.R 3569224HC Retested OK</i>					
21. LIST ALL PARTS REPLACED <i>All circuits affected by this failure function properly.</i>					
22. PART NUMBER					
<i>3905969</i>	<i>HVI</i>	<i>54525</i>	<i>HAC</i>		
23. REWORK BY <i>16690/78815</i>					
24. CAUSE AND CORRECTIVE ACTION <i>Hybrid Part malfunction - part replaced</i>					
25. PROBLEMS ENCOUNTERED <i>As possibility of stress due to this failure. Circuit has clamps which prevent excessive voltages. REFER TO FAR #8499 ATTACHED</i>					
26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
27. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
28. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
29. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
30. RESPONSIBLE ENGINEER <i>P. L. Tula</i>					
31. SPACECRAFT SYSTEM ENGR <i>H. J. ...</i>					

FAILURE ANALYSIS REPORT

F2812



HUGHES AIRCRAFT COMPANY
TECHNOLOGY SUPPORT
DIVISION

FAR No. 8499 Page 1 of 8
Program Thematic Mapper

ORIGINAL PAGE IS
OF POOR QUALITY

Date of Failure <u>3-28-80</u> Date of Receipt <u>4-17-80</u> Request No. <u>F2812</u> Ledger No. <u>J2905-71</u> CMER No. <u>28726</u>	Requesting Engineer <u>R. Julian</u> Phone _____ Bldg./MS <u>377/P314</u> CML Project Engineer <u>L. L. Ferrin</u> Phone _____ Bldg./MS <u>H2/C346</u>
---	---

DEVICE INFORMATION	
HAC P/N <u>3905969</u> Device Type <u>Hybrid</u> Vendor <u>Hughes</u> Vendor P/N <u>82577</u> Device S/N <u>525</u>	Date Code _____ Lot Number _____ Circuit Symbol _____ Unit _____ S/N _____ Module _____ S/N _____

ABSTRACT

The reported failure mode "Static DCR offset voltage of channel 4 out of specification", was verified. Also a similar failure was observed on channel 3. The failure was isolated to N-channel MOS FET transistors Q3 and Q4. Shorts between source and gate of both transistors and a short between source and substrate of Q3 were noted. Internal examination revealed smearing and scratches on both transistors. Scanning Electron Microscope examination disclosed holes under the metalizations of both transistors.

The primary cause of the failure is believed to be mechanical damage which caused the shorts either via smeared metalization or by scratches which damaged underlying oxide resulting in holes in the silicon.

<i>Edwin J. Schornstein</i>	6/24/80	<i>John D. Baker</i>	6-24-80
FAILURE ANALYST	DATE	APPROVAL	DATE

FAILURE ANALYSIS
REPORT

F 28/2



FAR No. 8499 Page 2 of 8
Program Thematic Mapper

ORIGINAL PAGE IS
OF POOR QUALITY

COMPONENT ENGINEERING TECHNICAL COMMENTARY:

HAC hybrid (analog input buffer) Part No. 3905969 was submitted for failure analysis.

Electrical tests were performed to Specification Number TS 32015-030. Parameters were within specification requirements, except for offset voltage on channel 3 and 4 which exceeded the maximum limits.

Internal examination revealed scratches and smearing of metalization on N channel MOS FET transistor Q3 & Q4 and Q1 transistor had a defect on a bonded lead.

Electrical probing confirm that Q3 was shorted from source to gate, source to substrate and gate to substrate. Q4 was also shorted from the source to the gate.

This writer is in agreement with this failure analysis report and its conclusion.

RECOMMENDATIONS:

No corrective action required by TSD

CORRECTIVE ACTION
REQUIRED BY TSD
YES NO

[Signature] 7/1/80
COMPONENT ENGINEER DATE

[Signature] 7/7/80
DATE

ORIGINAL PAGE IS
OF POOR QUALITY

F 28/2

Reported Failure Mode:

Static DCR offset voltage of channel 4 out of spec.

Available Data:

None.

Outline of Analysis:

1. External Visual Examination
2. Particle Impact Noise Test
3. Electrical Test
4. Internal Examination
5. Electrical Probe Measurements
6. Scanning Electron Microscope (SEM) Examination

Results of Analysis:

1. External Visual Examination.
 - a) Case examination disclosed no anomalies.
 - b) Markings:

<u>TOP</u>	<u>BOTTOM</u>
Hughes Logo	Hughes Logo
B2577	B2577
3905969	3905969
SER NO 525	SER NO 525

2. Particle Impact Noise Test.

No loose particles were detected.

3. Electrical Test.

The hybrid was tested in accordance with HAC ANALOG INPUT BUFFER test specification number TS32015-030 for the following parameters: 1KHz GAIN, DC offset, NOISE, 3dB Bandwidth Static DC Restoration offset voltage and power supply current at +25°C. All the parameters measured were within specified limits except for Static DC Restoration offset voltage of channel 3 and 4 which exceeded the maximum limits. Static DC Restoration voltages were measured to be as follows:

Channel 3 = -684mV should be $0 \pm 0.5mV$ maximum
Channel 4 = +136mV should be $0 \pm 0.5mV$ maximum

4. Internal Examination.

Internal examination at magnifications 194X and greater revealed the following anomalies:

- a) Scratches and smearing of metalization on N channel MOS FET transistors Q3 and Q4. (See Figures 1 through 5.
- b) A lead bonding defect on Q1 transistor. (See Figure 6).

F28/2

Results of Analysis: (continued)

5. Electrical Probe Measurements.

Electrical probing, combined with circuit isolation via lifting the source, drain, and gate leads of N-channel MOS FET transistor Q3 and Q4 of the substrate indicated the following:

- a) Source to Gate of Q3, channel 3, had a 350 ohm short.
- b) Source to Substrate of Q3, channel 3 had a 57.5K ohm short.
- c) Gate to Substrate of Q3, channel 3, had a 52.6K ohm short.
- d) Source to Gate of Q4, channel 4, had a 600 ohm short.

6. Scanning Electron Microscope (SEM) Examination.

SEM examination after metalization removal disclosed pinholes in the Source region of Q3 and Q4 and a pin hole in the gate bond pad region of Q3. (See Figures 7 through 11)

Conclusion:

The reported failure mode "Static DCR offset voltage of channel 4 out of spec." was confirmed. Also the Static DCR offset voltage of channel 3 exceeded the maximum specified limits of $0mV + 0.5mV$. The failure was isolated to N-channel MOS FET transistors Q3 and Q4, of channel 3 and 4. Electrical probing, combined with isolation indicated that the Source and Gate of both transistors were shorted. Also the Source and the Substrate of Q3 were shorted. Internal examination revealed scratches on both transistors especially under the Source and Gate bond, and in the metalization of the Source and Gate

Scanning electron microscope examination after metalization removal disclosed pinholes in the oxide under the metalization of both transistors.

Analysis disclosed mechanical damage in the form of smearing and scratches in the metalization. Smearing of the metalization may have caused a short. The scratches are believed to have damaged the underlying oxide resulting in the pinholes found during SEM examination. One or more of the pinholes may have also been the cause of a short. The primary cause of failures is believed to be mechanical damage to the Q3 and Q4 chips.

FAR. NO. 8499
PAGE 5 of 8

F2812

ORIGINAL PAGE IS
OF POOR QUALITY

Figure No. 1
Sample No. 525

Overall internal view of
the hybrid.

(4X)




Figure No. 2
Sample No. Q3

Overall view of Q3 transistor
Arrows point to the scratches
on the chip.

(194X)




Figure No. 3
Sample No. Q3

Magnified view of the anomaly
shown in Figure 2.

(1338X)



F28/2

ORIGINAL PAGE IS
OF POOR QUALITY




Figure No. 4
Sample No. Q4

Overall view of Q4 transistor.
Arrows point to the scratches
on the chip.

(194X)




Figure No. 5
Sample No. Q4

Magnified view of the anomaly
shown in Figure 4.

(1338X)




Figure No. 6
Sample No. Q1

Overall view of Q1 transistor chip
Arrow points to lead bond
anomaly.

(285X)

F 281:

ORIGINAL PAGE IS
OF POOR QUALITY




Figure No. 7
Sample No. Q3

SEM view of Q3 after metal
removal with pinholes indicated
(145X)



Figure No. 8
Sample No. Q3

Magnified view of pinhole
shown in Figure 7 Arrow B.
(7400X)




Figure No. 9
Sample No. Q3

Magnified view of the pinhole
shown in Figure 7, Arrow A.
(3700X)

ORIGINAL PAGE IS
OF POOR QUALITY

FAR. NO. 8499
PAGE 8 of 8

F2812




Figure No. 10
Sample No. Q4

SEM view of Q4 transistor after
metalization removal with pin-
hole indicated.

(142X)




Figure No. 11
Sample No. Q4

Magnified view of the pinhole
shown in Figure 10.

(700X)

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 281

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper 45236</i>		2. CLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>420</i>	5. DATE OBSERVED <i>NOV 30 1980</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM <i>FLT</i>		NAME		PART NUMBER	MANUFACTURER
8. UNIT <i>Multiplexer</i>				<i>3533 003-100</i>	<i>Hac</i>
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <i>AL</i>				<i>3569224</i>	<i>16 Hac</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN PROGRESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ASSESS <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THROTTL VAC <input type="checkbox"/> HOLD AT <input type="checkbox"/> DEC/REP <input type="checkbox"/> VIBRATION <input type="checkbox"/> ANG FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Channels 9-17 No output</i>					
15. TEST PROCEDURE <i>3569224</i>		16. ORIGINAL ORG <i>YAMAUCHI</i>	17. DATE <i>4/1/81</i>	18. CONTINUAL SHEET USE	
19. VERIFICATION AND FAILURE ANALYSIS <i>No analog mux output from HY2 of Rear Assy. Mux out stops @ 1.5V. No possibility of damage to other components. Multiple output of +2 volts is within range of A/D Converter, and operation when other Multiplexers are on was normal.</i>					
20. <input checked="" type="checkbox"/> FOLLOWING REPAIR/TEST REQUIRED REPAIR/TEST NOT REQUIRED BECAUSE <i>REPLACE HY2 and proceed with test of subassembly. Return HY2 for analysis of open output.</i>		10. FAILED ITEM NAME AND PART NUMBER <i>3905973 JN 513</i>			
21. AUTHORIZATION <i>RL Julian</i>		ORG <i>41-41</i>	DATE <i>4/21/80</i>	22. CONTINUAL SHEET USE	
23. REPAIR/TEST ACTION TAKEN <i>Replaced HY2 on REAR ASSY</i>					
24. RETEST <i>Retest OK per TP 3569224 HC</i>					
25. LIST ALL PARTS REPLACED <i>All circuits affected by this failure function properly.</i>					
23. PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	WFR	PROBABLE DEFECT
<i>3905973</i>	<i>HY2</i>	<i>SK513</i>		<i>HAC</i>	<i>Pin 57 output defective. Pin 24 OK.</i>
27. REWORK BY <i>1/1/80</i>		ORG <i>45</i>	DATE <i>1/2/80</i>	28. RETEST BY <i>R. Yamachi</i>	ORG <i>41-41</i>
29. CAUSE AND CORRECTIVE ACTION <i>Suspect Hybrid part malfunction - part replaced.</i>		DATE <i>4/23/80</i>		29. CONTINUAL SHEET USE	
30. ENGINEERING RELIABILITY <i>No possibility of component failure due to this failure.</i>					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY		33. FRG CLOSURE <i>RL Julian 1/20</i>	
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER <i>RL Julian</i>		ORG <i>41-41</i>	DATE <i>11/25/80</i>	38. SPACECRAFT SYSTEM ENGINEER <i>W. L. Lumbert - 122-61</i>	
38. RELIABILITY		ORG	DATE	39. CUSTOMER OR DATE	

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 281

1. PROGRAM NAME AND NUMBER H3236		2. CLA A230	3. MODEL F	4. TIME OBSERVED 2030	5. DATE OBSERVED MO 7 DA 8 YR 6
6. HARDWARE LEVEL WHICH FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECAM <input type="checkbox"/> PART					
7. SUBSYSTEM IDENTIFICATION: MAKE PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM F					
8. UNIT MULTIPLIER					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY A4 3533003-100 MAC					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD 3569240 S/A 3 MAC					
11. OTHER					
12. TEST MODES FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHICH FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACID <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HFS AT <input type="checkbox"/> OSCILL <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> USE TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE R1 (M11) overheating					
15. TEST PROCEDURES 3569240 PARA 18. ORIGINATOR H. COE ORG 141-91 DATE 1-28-50 <input type="checkbox"/> CONTINUA SHEET 1					
16. VERIFICATION AND FAILURE ANALYSIS (1) Value of Resistor Incorrect: Is 6.8Ω; S/B 68.0Ω per drawing (2) All wiring done incorrect: U4-1 is connected to U4-4 which connects to ground; S/B U4-11 connects to U4-4. (3) All wiring done correct					
17. <input checked="" type="checkbox"/> FAILURE REPAIR/TEST REQUIRED <input type="checkbox"/> REPAIR/TEST NOT REQUIRED BECAUSE (1) REPLACE R1 WITH CORRECT VALUE (2) REMOVE U4-11 TO U4-1 CONNECTION; ADD JUMPER FROM U4-11 TO U4-4 PER ALL WIRING (Pg. 7, Line 1, Row C)					
18. PART IDENTIFIED MAKE AND PART NUMBER 3569240					
19. AUTHORIZATION H. COE ORG 141-91 DATE 1-28-50 <input type="checkbox"/> CONTINUA SHEET 2					
20. APPROVED FOR TEST ACTION TAKEN UNW/DBA AUTHORIZED CUTS 9 JUMPS. U4-11 STAMPED 10660P ST. 7 TEST S20					
21. LIST ALL PARTS REPLACED 908661-035					
22. REPAIR BY 14609 H.F. ORG 145 DATE 1/28/50 23. RETESTED BY D. Valera ORG 91 DATE 4/24/50 <input type="checkbox"/> CONTINUA SHEET 3					
24. CAUSE AND CORRECTIVE ACTION D Assy/Fab error - wrong resistor value installed					
25. FRB CLOSURE 2) Improperly wired in manufacturing - positive control and R1 resistor replaced Since tester supply current limited and voltages & currents in spec. No possibility of stress to other components due to this failure.					
26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION SEE ATTACHED SUPPLEMENTARY SHEET					
27. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> FEAR-OUT					
28. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE <input checked="" type="checkbox"/> MAJORITY <input type="checkbox"/> SAFETY					
29. RESPONSIBLE ENGINEER K. J. Julian ORG 141-41 DATE 8/21/50 30. SPACECRAFT SYSTEM ENGINEER W. J. F. ... ORG 122-61 DATE 1/8/52					



SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

FR2814 CONT. SHEET
FR SERIAL NO. 1 A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL
CONTINUATION
SHEET(S) USED

This FR addresses an assembly error affecting resistor R1 of circuit MX11. This resistor should be wired from the +5 volt logic supply to various TTL logic inputs.

Due to manufacturing error, a 6.8Ω resistor was used instead of 68Ω, and instead of being wired to the logic inputs it was wired between +5Volts and ground, leaving the logic inputs open circuit.

This error overheated the 6.8Ω resistor, which was replaced with a properly installed 68Ω resistor. No other diodes could have been damaged by this error, since the logic inputs were left open circuited, which is an allowed operating condition. Even if the inputs had been erroneously wired to ground they would not have been damaged, since their specified input voltage range includes 0 volts.

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2815

1. PROGRAM NAME AND NUMBER HS236		2. QLA E330	3. COOL F	4. TIME OBSERVED 2040	5. DATE OBSERVED NOV 28 80
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT	<input type="checkbox"/> SUBSYSTEM	<input type="checkbox"/> ASSEMBLY	<input type="checkbox"/> MODULE
		<input type="checkbox"/> SYSTEM	<input type="checkbox"/> UNIT	<input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MICASS
		<input type="checkbox"/> CARD	<input type="checkbox"/> PART		
8. EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM F		PART NUMBER		MFG MANUFACTURER	
9. UNIT MULTIPLEXER		3533003-100		HAC	
10. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY AA		3569240		S/N 3 HAC	
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT	<input type="checkbox"/> QUALIFICATION	<input type="checkbox"/> INTEGRATION	<input type="checkbox"/> LAUNCH OPERATIONS
		<input checked="" type="checkbox"/> IN-PROCESS	<input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> P-ITEM	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT	<input type="checkbox"/> RADIATION	<input type="checkbox"/> TEMPERATURE	<input type="checkbox"/> THERMAL VAC
		<input type="checkbox"/> ESD/RFI	<input type="checkbox"/> VIBRATION	AXIS FOR _____ MIN TYPE _____	HUMIDITY _____ OTHER _____
14. DESCRIPTION OF FAILURE B34 of capacitor is connected to U24-8 (MKII)					
15. TEST PROCEDURE 7P3569240		16. ORIGINATOR A. Coe	17. ORG 91-91	18. DATE 4-8-80	19. CONTINUATION SHEET USED
20. VERIFICATION AND FAILURE ANALYSIS All wiring implemented incorrectly; B34 is connected to U24-8 by wire; S/B B34 connected to U24-14 per Alt wiring (Pg. 7, Line 2, Row C)					
21. FAILED ITEM NAME AND PART NUMBER 3569240					
22. AUTHORIZATION H. Coe					
23. FOLLOWING REMOVED/TEST REQUIRED BROWN/RED NOT REQUIRED ETC Remove wire B34 to U24-8					
24. REWORK/RETRY ACTION TAKEN All circuits affected by this failure function properly. Retest on P.P. 3569240 HAC					
25. LIST ALL PARTS REPLACED					
PART NUMBER	CYCL SYM	PART LOT NO.	DATE COGS	MFR	PROBABLE DEFECT
27. REWORK BY Hasez Hys					
28. CAUSE AND CORRECTIVE ACTION Improperly wired in manufacturing - operate cautions.		29. ORG 96	30. DATE 4/1/80	31. RETESTED BY Dr. Salya	32. ORG 91
		33. DATE 4/1/80	34. DATE 4/1/80	35. CONTINUATION SHEET USED	
36. BASIC CAUSE OF VERIFIED FAILURE					
<input type="checkbox"/> DESIGN		<input type="checkbox"/> TEST EQUIP.	<input type="checkbox"/> MFG. PROCEDURE	<input checked="" type="checkbox"/> WIRING ERROR	<input type="checkbox"/> UNKNOWN
<input type="checkbox"/> ENVIRONMENTAL		<input type="checkbox"/> TEST PROC.	<input type="checkbox"/> ASBY/PAG ERROR	<input type="checkbox"/> ROUGH HANDLING	<input type="checkbox"/> DEFECT CODE
<input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST INST-UP	<input type="checkbox"/> WORKMANSHP	<input type="checkbox"/> WEAR-OUT	
37. FAILURE TYPE <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> PRIMARY	<input type="checkbox"/> UNKNOWN	<input type="checkbox"/> NO FAILURE	38. FAILURE CLASSIFICATION <input checked="" type="checkbox"/> MAJOR
		<input type="checkbox"/> CRITICAL	<input type="checkbox"/> MINOR	<input type="checkbox"/> SAFETY	
39. RESPONSIBLE L... DATE 11/10/80					
40. SPACECRAFT... DATE 11/10/80					

567
TEST
529

Handwritten signature
3-19-81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

PR SERIAL NO. 2815
CONTINUATION SHEET LETTER A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL PR CONTINUATION SHEET(S) USED

20. Replace MX 11 U24 (SN54L73, 908929-1) due to possible overstress. No-possibi-

21. *R.L. Wilson* 41-41 11/6/80

23. Rework/Reatest action taken:

24. QA Rework

25. QA Reatest.

26. Part Replaced: /
Ckt Sym: U24 Part Lot No. Data Code Mfr.
Probable Defect: None-possible overstress but component still works.

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2816

1. PROGRAM NAME AND NUMBER 77800000000000000000 19236		2. GLA E330	3. MODEL FLT	4. TIME OBSERVED 10:00	5. DATE OBSERVED 5/14/80
6. MAJOR LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ACCESSORY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> SCAM <input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM FLT		PART NUMBER 9533003-700		S/N HAC	
8. <input type="checkbox"/> ACCESSORY <input checked="" type="checkbox"/> SUBASSEMBLY A6		PART NUMBER 3569224		S/N 14 HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> SCAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> PRODUCTION	<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> OSCILLATION	<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMPERATURE AXIS POS _____ MIN _____ TYPE _____	<input type="checkbox"/> THERMAL VAC KHZ AT _____ <input type="checkbox"/> OTHER
14. DESCRIPTION OF FAILURE Channel 9 buffer has excessive gain.					
10. TEST PROCEDURE 3569224		PART 3121	10. ORIGINATOR R. Yamawaki	ORG 41	DATE 5/14/80
18. VERIFICATION AND FAILURE ANALYSIS With output pin 21 lifted and 4V P-P in output @ -0.6V.					
23. FOLLOWING REPAIR/SYSTEM REQUIRED BEFORE/TEST NOT REQUIRED BECAUSE REPLACE INPUT BUFFER - HY3. RETURN REMOVED DEVICE FOR REPAIR AND FAILURE ANALYSIS.					
27. APPROVED BY R. Julian					
28. REPAIR/TEST ACTION TAKEN REPLACE HY3 ON FRONT ASSY.					
29. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	S/N	REMARKS
39059109	HY3	5N554		HAC	GAIN Resistor formed wrong
27. REPORT BY 48877					
28. CAUSE AND CORRECTIVE ACTION Repaired Hybrid part malfunction - part replaced The hybrid Input Buffer incorporates clamps to prevent its output voltage from going outside the permissible input range for the Analog Multiplexer hybrid. So no overstress voltage was applied to any point. No possibility of component failure due to this failure. SEE ATTACHED SUPPLEMENTARY SHEET					
32. DOCUMENT REPRESENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> DEFECTIVE PARTS	<input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE
36. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED	<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER R. Julian		ORG 41	DATE 11/25/80	39. SPACECRAFT SYSTEM ENGR. M.A. Zencovich	
		ORG 41	DATE 1/12/91	40. CUSTOMER OR DATE	



SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

FR2816 CONT. SHEET
PR SERIAL NO. LETTER
A

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

The failure reported here (excessive gain of an analog input buffer) affects only the output of the analog input buffer hybrid. The only sensitive point connected to the affected output is the corresponding analog multiplexer hybrid analog input. There is no possibility of damage to this input because the inputs are designed to withstand applied voltages of -2V to +10V, whereas the analog input buffer hybrid incorporates diode clamps which limit its output voltage range even under single failure conditions, to the range -0.7V to +3.7V.

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2817

1. PROGRAM NAME AND NUMBER H-236		2. QLA E-330		3. MODEL AF		4. TIME OCCURRED 20:00		5. DATE RECEIVED 4/30/80	
6. MALFUNCTION LEVEL, TYPE & CLASSIFICATION		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> PAYLOAD		<input type="checkbox"/> ELECTRONIC <input type="checkbox"/> MECHANICAL		<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> ELECTRICAL		<input type="checkbox"/> LOGICAL <input type="checkbox"/> MECHANICAL	
7. EXCEPTS AF		8. UNIT MULTIPLEXER		9. PART NUMBER 35633003-100		10. QUANTITY 3		11. LOCATION HAC	
12. TEST CONDITIONS		13. TEST RESULTS		14. TEST PROCEDURES		15. TEST EQUIPMENT		16. TEST FACILITIES	
17. TEST OBJECTIVE		18. TEST RESULTS		19. TEST PROCEDURES		20. TEST EQUIPMENT		21. TEST FACILITIES	
19. TEST RESULTS		20. TEST PROCEDURES		21. TEST FACILITIES		22. TEST EQUIPMENT		23. TEST FACILITIES	
24. TEST RESULTS		25. TEST PROCEDURES		26. TEST FACILITIES		27. TEST EQUIPMENT		28. TEST FACILITIES	
29. TEST RESULTS		30. TEST PROCEDURES		31. TEST FACILITIES		32. TEST EQUIPMENT		33. TEST FACILITIES	
34. TEST RESULTS		35. TEST PROCEDURES		36. TEST FACILITIES		37. TEST EQUIPMENT		38. TEST FACILITIES	
39. TEST RESULTS		40. TEST PROCEDURES		41. TEST FACILITIES		42. TEST EQUIPMENT		43. TEST FACILITIES	
44. TEST RESULTS		45. TEST PROCEDURES		46. TEST FACILITIES		47. TEST EQUIPMENT		48. TEST FACILITIES	
49. TEST RESULTS		50. TEST PROCEDURES		51. TEST FACILITIES		52. TEST EQUIPMENT		53. TEST FACILITIES	
54. TEST RESULTS		55. TEST PROCEDURES		56. TEST FACILITIES		57. TEST EQUIPMENT		58. TEST FACILITIES	
59. TEST RESULTS		60. TEST PROCEDURES		61. TEST FACILITIES		62. TEST EQUIPMENT		63. TEST FACILITIES	
64. TEST RESULTS		65. TEST PROCEDURES		66. TEST FACILITIES		67. TEST EQUIPMENT		68. TEST FACILITIES	
69. TEST RESULTS		70. TEST PROCEDURES		71. TEST FACILITIES		72. TEST EQUIPMENT		73. TEST FACILITIES	
74. TEST RESULTS		75. TEST PROCEDURES		76. TEST FACILITIES		77. TEST EQUIPMENT		78. TEST FACILITIES	
79. TEST RESULTS		80. TEST PROCEDURES		81. TEST FACILITIES		82. TEST EQUIPMENT		83. TEST FACILITIES	
84. TEST RESULTS		85. TEST PROCEDURES		86. TEST FACILITIES		87. TEST EQUIPMENT		88. TEST FACILITIES	
89. TEST RESULTS		90. TEST PROCEDURES		91. TEST FACILITIES		92. TEST EQUIPMENT		93. TEST FACILITIES	
94. TEST RESULTS		95. TEST PROCEDURES		96. TEST FACILITIES		97. TEST EQUIPMENT		98. TEST FACILITIES	
99. TEST RESULTS		100. TEST PROCEDURES		101. TEST FACILITIES		102. TEST EQUIPMENT		103. TEST FACILITIES	

10. TEST RESULTS: 3569254

11. TEST PROCEDURES: H. COE

12. TEST FACILITIES: 4/24/80

13. TEST EQUIPMENT: 4/23/80

14. TEST FACILITIES: 3569254

15. TEST FACILITIES: Add 212 & 213 Delay Lines to Assy

16. TEST FACILITIES: R. Williams

17. TEST FACILITIES: 4/24/80

18. TEST FACILITIES: 4/23/80

19. TEST FACILITIES: All circuits affected by this failure function properly.

20. TEST FACILITIES: Retested per TPL 569254 NC.

21. TEST FACILITIES: 98T

22. TEST FACILITIES: 98T

23. TEST FACILITIES: 98T

24. TEST FACILITIES: 98T

25. TEST FACILITIES: 98T

26. TEST FACILITIES: 98T

27. TEST FACILITIES: 98T

28. TEST FACILITIES: 98T

29. TEST FACILITIES: 98T

30. TEST FACILITIES: 98T

31. TEST FACILITIES: 98T

32. TEST FACILITIES: 98T

33. TEST FACILITIES: 98T

34. TEST FACILITIES: 98T

35. TEST FACILITIES: 98T

36. TEST FACILITIES: 98T

37. TEST FACILITIES: 98T

38. TEST FACILITIES: 98T

39. TEST FACILITIES: 98T

40. TEST FACILITIES: 98T

41. TEST FACILITIES: 98T

42. TEST FACILITIES: 98T

43. TEST FACILITIES: 98T

44. TEST FACILITIES: 98T

45. TEST FACILITIES: 98T

46. TEST FACILITIES: 98T

47. TEST FACILITIES: 98T

48. TEST FACILITIES: 98T

49. TEST FACILITIES: 98T

50. TEST FACILITIES: 98T

51. TEST FACILITIES: 98T

52. TEST FACILITIES: 98T

53. TEST FACILITIES: 98T

54. TEST FACILITIES: 98T

55. TEST FACILITIES: 98T

56. TEST FACILITIES: 98T

57. TEST FACILITIES: 98T

58. TEST FACILITIES: 98T

59. TEST FACILITIES: 98T

60. TEST FACILITIES: 98T

61. TEST FACILITIES: 98T

62. TEST FACILITIES: 98T

63. TEST FACILITIES: 98T

64. TEST FACILITIES: 98T

65. TEST FACILITIES: 98T

66. TEST FACILITIES: 98T

67. TEST FACILITIES: 98T

68. TEST FACILITIES: 98T

69. TEST FACILITIES: 98T

70. TEST FACILITIES: 98T

71. TEST FACILITIES: 98T

72. TEST FACILITIES: 98T

73. TEST FACILITIES: 98T

74. TEST FACILITIES: 98T

75. TEST FACILITIES: 98T

76. TEST FACILITIES: 98T

77. TEST FACILITIES: 98T

78. TEST FACILITIES: 98T

79. TEST FACILITIES: 98T

80. TEST FACILITIES: 98T

81. TEST FACILITIES: 98T

82. TEST FACILITIES: 98T

83. TEST FACILITIES: 98T

84. TEST FACILITIES: 98T

85. TEST FACILITIES: 98T

86. TEST FACILITIES: 98T

87. TEST FACILITIES: 98T

88. TEST FACILITIES: 98T

89. TEST FACILITIES: 98T

90. TEST FACILITIES: 98T

91. TEST FACILITIES: 98T

92. TEST FACILITIES: 98T

93. TEST FACILITIES: 98T

94. TEST FACILITIES: 98T

95. TEST FACILITIES: 98T

96. TEST FACILITIES: 98T

97. TEST FACILITIES: 98T

98. TEST FACILITIES: 98T

99. TEST FACILITIES: 98T

100. TEST FACILITIES: 98T

101. TEST FACILITIES: 98T

102. TEST FACILITIES: 98T

103. TEST FACILITIES: 98T

ORIGINAL PAGE IS
OF POOR QUALITY




SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2818

1. PROGRAM NAME AND NUMBER H2236		2. CLA E330		3. MODEL F		4. TIME OBSERVED 2000		5. DATE OBSERVED 5 30 80	
6. HAZARD LEVEL WHEN FAILURE OCCURRED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAS <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION									
7. SUBSYSTEM F		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT MULTIPLEXER				3532003-100		HAC			
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY A2				3569254		3		HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° _____ THERMAL VAC _____ MRL AT _____		<input type="checkbox"/> ESD/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____							
14. DESCRIPTION OF FAILURE Wiring error				BAND SEL RFL (C34) loose from					
15. TEST PROCEDURE 3569254		16. ORIGINATOR M. COE		ORG 41-41		DATE 4/20/80		17. CONTINUATION SHEET USED	
18. VERIFICATION AND FAILURE ANALYSIS ALT wiring implemented incorrectly, D34 at etched board cut & rewired instead of C34. Rechecked 5-22-80 78915									
19. NO OVERSTRESS WAS POSSIBLE.		18. FAILED ITEM NAME AND PART NUMBER 3569254							
20. FOLLOWING REPAIR/RETEST REQUIRED: REWORK BOARD TO CORRECTLY IMPLEMENT ALT wiring S45 - Line 2, S49 - Line 4. Rechecked 5-22-80 78915									
21. AUTHORIZATION R.D. Wynn		ORG 41-41		DATE 4/20/80		17. CONTINUATION SHEET USED			
22. REPAIR/RETEST ACTION TAKEN REWORK TO LINE 20. RECHECKED TO T.P. 3569254 () ALL CIRCUITS AFFECTED BY THIS FAILURE REPAIR PROPERLY. W.D.B. WILKINS 5/28/80								23. CONTINUATION SHEET USED 59 TEST 527	
24. LIST ALL PARTS REPLACED		PART NUMBER		CMT SYN		PART LOT NO.		DATE CODE	
								VFR	
								PROBABLE DEFECT	
								ANALYSIS NO.	
27. REWORK BY 78915 5-22-80		ORG 41-41		DATE 5/21/80		28. RETEST BY R. J. Jaramila		ORG 41-41	
29. CAUSE AND CORRECTIVE ACTION Improvement work in manufacturing - operator continued								33. PRE CLOSURE On possibility of component return due to this failure.	
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION - NONE								31. CONTINUATION SHEET USED	
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN		<input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING		<input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHP <input type="checkbox"/> WEAR-OUT				DEFECT CODE	
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY							
37. RESPONSIBLE ENGINEER L. J. Jaramila		ORG 41-41		DATE 4/19/80		38. SPACECRAFT SYSTEM ENGINEER N. J. Jaramila		ORG 5320	
39. RELIABILITY 11 2 11		ORG 41-41		DATE 4/19/80		40. CUSTOMER OR SUPPLIER 24		DATE 6/25/80	

ORIGINAL PAGE IS OF POOR QUALITY




**SPACE AND COMMUNICATION GROUP
FAILURE REPORT**

F 2S19

1. PROGRAM NAME AND NUMBER HS236		2. OMA 2930	3. MODEL F	4. TIME RECEIVED 19:30	5. DATE RECEIVED 5 1 60
6. RADIO FREQUENCY LEVEL (OR ANALOG) HAS OCCURRED		<input type="checkbox"/> AIRCRAFT	<input type="checkbox"/> SUBSYSTEM	<input type="checkbox"/> ASSEMBLY	<input type="checkbox"/> SIGNAL
		<input type="checkbox"/> SYSTEM	<input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> RADIOFREQUENCY	<input type="checkbox"/> MECHAN
7. IDENTIFICATION					
8. USER MURRIEXER					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> RADIOFREQUENCY AJ					
10. <input type="checkbox"/> SIGNAL <input type="checkbox"/> MECHAN <input type="checkbox"/> CASE					
11. TEST CASES (ALL TEST CASES OBSERVED)					
<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS					
<input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEMS					
12. TEST CASES (ALL TEST CASES OBSERVED)					
<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> DAMAGED <input type="checkbox"/> THERMAL/SHOCK <input type="checkbox"/> THERMAL VIB <input type="checkbox"/> VIB AT					
<input type="checkbox"/> MECHAN <input type="checkbox"/> VIBRATION <input type="checkbox"/> ALTITUDE <input type="checkbox"/> VIB					
13. IDENTIFICATION OF FAILURE ALUMINUM FRAME STIFF Spigot (CA9) IMPROPER					
14. PART NUMBER (S) 3569254					
15. OPERATOR M. COE					
16. OPERATOR AND FACILITY ADDRESS RAN SPACE JUNIT between CONNECTOR ALUMINUM (CA9) and BRACKET CR. 3d. REWORKED 92000 78918					
17. PART NUMBER (S) 3569254					
18. ALL OTHER OPERATING RECORDS RECORDED (IF NOT RECORDED, INDICATE REASON)					
REWORK SPACE JUNIT					
REWORKED 92000 78918					
19. OPERATOR H. COE					
20. OPERATOR AND FACILITY ADDRESS					
ALL repairs effected by this failure function properly. Rechecked next P.P. 3569254C OK.					
21. PART NUMBER (S) 18815 5-21-50					
22. OPERATOR AND FACILITY ADDRESS					
Improper workmanship in manufacturing - operator and inspector checked.					
23. OPERATOR AND FACILITY ADDRESS					
24. OPERATOR AND FACILITY ADDRESS					
25. OPERATOR AND FACILITY ADDRESS					
26. OPERATOR AND FACILITY ADDRESS					
27. OPERATOR AND FACILITY ADDRESS					
28. OPERATOR AND FACILITY ADDRESS					
29. OPERATOR AND FACILITY ADDRESS					
30. OPERATOR AND FACILITY ADDRESS					
31. OPERATOR AND FACILITY ADDRESS					
32. OPERATOR AND FACILITY ADDRESS					
33. OPERATOR AND FACILITY ADDRESS					
34. OPERATOR AND FACILITY ADDRESS					
35. OPERATOR AND FACILITY ADDRESS					
36. OPERATOR AND FACILITY ADDRESS					
37. OPERATOR AND FACILITY ADDRESS					
38. OPERATOR AND FACILITY ADDRESS					
39. OPERATOR AND FACILITY ADDRESS					
40. OPERATOR AND FACILITY ADDRESS					
41. OPERATOR AND FACILITY ADDRESS					
42. OPERATOR AND FACILITY ADDRESS					
43. OPERATOR AND FACILITY ADDRESS					
44. OPERATOR AND FACILITY ADDRESS					
45. OPERATOR AND FACILITY ADDRESS					
46. OPERATOR AND FACILITY ADDRESS					
47. OPERATOR AND FACILITY ADDRESS					
48. OPERATOR AND FACILITY ADDRESS					
49. OPERATOR AND FACILITY ADDRESS					
50. OPERATOR AND FACILITY ADDRESS					
51. OPERATOR AND FACILITY ADDRESS					
52. OPERATOR AND FACILITY ADDRESS					
53. OPERATOR AND FACILITY ADDRESS					
54. OPERATOR AND FACILITY ADDRESS					
55. OPERATOR AND FACILITY ADDRESS					
56. OPERATOR AND FACILITY ADDRESS					
57. OPERATOR AND FACILITY ADDRESS					
58. OPERATOR AND FACILITY ADDRESS					
59. OPERATOR AND FACILITY ADDRESS					
60. OPERATOR AND FACILITY ADDRESS					
61. OPERATOR AND FACILITY ADDRESS					
62. OPERATOR AND FACILITY ADDRESS					
63. OPERATOR AND FACILITY ADDRESS					
64. OPERATOR AND FACILITY ADDRESS					
65. OPERATOR AND FACILITY ADDRESS					
66. OPERATOR AND FACILITY ADDRESS					
67. OPERATOR AND FACILITY ADDRESS					
68. OPERATOR AND FACILITY ADDRESS					
69. OPERATOR AND FACILITY ADDRESS					
70. OPERATOR AND FACILITY ADDRESS					

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 2820

1. PROGRAM NAME AND NUMBER HS236		2. CLA E330	3. MODEL F	4. TIME OBSERVED 2015	5. DATE OBSERVED 7 9 80
6. HARDWARE LEVEL (WHEN FAILURE WAS OBSERVED)		<input type="checkbox"/> SPACECRAFT	<input type="checkbox"/> SUBSYSTEM	<input type="checkbox"/> ASSEMBLY	<input type="checkbox"/> MODULE
		<input type="checkbox"/> SYSTEM	<input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MECHAN
7. IDENTIFY ITEM IDENTIFICATION		CAGE	PART NUMBER	QTY	MARKER ACTUATOR
8. UNIT MULTIPLEXER			3533003-100		NAC
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		A1	3569261	3	NAC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHAN <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHICH FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT	<input type="checkbox"/> QUALIFICATION	<input type="checkbox"/> INTEGRATION	<input type="checkbox"/> LAUNCH OPERATIONS
		<input checked="" type="checkbox"/> INSPECTION	<input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> SYSTEM	<input type="checkbox"/>
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> ALTITUDE	<input type="checkbox"/> RADIATION	<input type="checkbox"/> TEMPERATURE	<input type="checkbox"/> THEORETICAL VAC
		<input type="checkbox"/> DURATION	<input type="checkbox"/> VIBRATION	<input type="checkbox"/> AIRS FOR	<input type="checkbox"/> MOL AT
14. DESCRIPTION OF FAILURE		ROT ON CS10 FLOWING INCORRECT (MYOR)			
15. TIME		3569261	3.3.3	COE	4741 5/7/80
16. INVESTIGATION AND FAILURE ANALYSIS		Cap C38 not installed on MYOR Bd. Rear Assy			
17. CORRECTIVE ACTION		INSTALL C38 capacitor on MYOR Bd per print (Rear Assy)			
18. AUTHORIZATION		H. COE			
19. COMMENTS		INSPECTED C38			
20. PARTS REPLACED		ALL circuits affected by this failure function properly. Replaced per TP 3569261 (NAC)			
21. FAILURE TYPE		192-2-1			
22. CAUSE AND CORRECTIVE ACTION		Improper assembly in manufacturing - operator and inspector corrected.			
23. DOCUMENTS IMPLEMENTING CORRECTIVE ACTION		No possibility of component stress due to this failure.			
24. BASIC CAUSE OF FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG PROCEDURE <input type="checkbox"/> AIRING ERROR <input type="checkbox"/> WEAR AND TEAR			
		<input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST + AG SEARCH <input type="checkbox"/> STORAGE HANDLING <input type="checkbox"/> CLIMATIC TEST			
		<input type="checkbox"/> CORRECTIVE PARTS <input type="checkbox"/> TEST SETUP <input type="checkbox"/> WORK MESSING <input type="checkbox"/> RETURN-OUT			
25. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR			
26. RESPONSIBLE ENGINEER		11/9/79 [Signature]			
27. RESPONSIBILITY		NO CUSTOMER OR SUPPLIER			

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

**SPACE AND COMMUNICATION GROUP
FAILURE REPORT**

F 2821

1. PROGRAM NAME AND NUMBER HR 236		2. QLA E330	3. MODEL F	4. TIME OBSERVED 19:50	5. DATE OBSERVED 5 14 60
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM F		NAME MULTIPLEXER		PART NUMBER 3533003-100	MANUFACTURER HAC
8. UNIT MULTIPLEXER		NAME A5		PART NUMBER 2569234	MANUFACTURER HAC
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEMS <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> EJECTION <input type="checkbox"/> VIBRATION		AXIS FOR _____ MIN TYPE _____ THERMAL VAC _____ HRS AT _____ OTHER _____			
14. DESCRIPTION OF FAILURE EXCESSIVE COMMON MODE NOISE ON BUFFER OUTPUT, channel B					
15. TEST MEASUREMENTS 3569234		PARA 5.3	16. ORIGINATOR HCAF	ORG 41	DATE 5-14-60
17. VERIFICATION AND FAILURE ANALYSIS Buffer HYBRID, HY1, suspect part. Input pins were checked together with no noticeable effect on output common mode noise. No possibility of component stress. All voltages and currents in circuit remained within design ranges.					
18. FOLLOWED REPAIR/TEST REQUIRED REPAIR/TEST NOT REQUIRED		18. FAILED ITEM NAME AND PART NUMBER 3569234			
19. ACTION REMOVE AND REPLACE INPUT BUFFER HYBRID HY1 P/N 3905769. RETEST MODULE, RETAIN HYBRID FOR FAILURE ANALYSIS					
20. REPAIR/TEST ACTION TAKEN INSTALLED 5/21/60 - 16555. Rechecked per T.P. 3562341R. All circuits affected by the PLR function properly.		21. AUTHORITY KLJulkian		ORG 41	DATE 5/18/60
22. LIST ALL PARTS REPLACED					
PART NUMBER 3905769	CMT SYM HY1	PART LOT NO. S/N 553	DATE CODE	MFR HAC	PROBABLE DEFECT
27. REPAIR BY Remove 2487		ORG 41	DATE 5/18/60	28. RETESTED BY H. Cas	ORG 41
29. CAUSE AND CORRECTIVE ACTION Suspect HYBRID component failure. Suspect Hybrid was replaced.		33. PRG CLOSURE KLJulkian 1/20/61			
32. DOCUMENT WORK IN PROGRESS CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/PAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> CORREMANSHIP <input type="checkbox"/> WEAR-OUT					
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER KLJulkian		ORG 41	DATE 4/19/60	38. SPACECRAFT SYSTEM MGR. W. E. Fendrich	ORG 5382
39. CUSTOMER OR		DATE 16/25/61			



SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

FR2821 CONT. SHEET
PR SERIAL NO. LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON
IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL PR
CONTINUATION
SHEET(S) USED

The failure reported here (noise on analog insert buffer outputs) affect only the output of the analog input buffer hybrid. The only sensitive point connected to the affected output is the corresponding analog multiplexer hybrid analog insert. There is no possibility of damage to this input because the inputs are designed to withstand applied voltage of -2V to +10V, whereas the analog input buffer hybrid incorporates diode clamps which limit its output voltage range even under single failure conditions to the range -0.7V to +3.7V.

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 282

1. PROGRAM NAME AND NUMBER <i>Thermally Mapped H3226</i>		2. QLA <i>E330</i>	3. MODEL <i>F</i>	4. TIME OBSERVED <i>1000</i>	5. DATE OBSERVED <i>MO DA 20 80</i>
6. HAZARD LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAS	<input type="checkbox"/> CARD <input type="checkbox"/> PART
7. EQUIPMENT IDENTIFICATION					
NAME					
PART NUMBER					
S/N					
MANUFACTURER					
8. UNIT <i>Multiplexer</i>					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <i>A6</i>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAS <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IMPROVED <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° _____ ° <input type="checkbox"/> ESCAPE <input type="checkbox"/> VIBRATION _____ ANIS FOR _____ MIN TYPE _____ OTHER _____					
14. DESCRIPTION OF FAILURE <i>RAIL Voltage "B" Test point reads in excess of Spec tolerance +14 to +16 Volts @ High Bus Voltage.</i>					
15. TEST PROCEDURE <i>3569224</i>		PART NO. <i>70/5.93</i>	10. ORIGINATOR <i>R-Yamachi</i>	ORG <i>414</i>	DATE <i>5/20/80</i>
16. VERIFICATION AND FAILURE ANALYSIS					
17. FOLLOWING REWORK/TEST REQUIRED ACCORDING TO TEST NOT REQUIRED BECAUSE <i>SPEC WILL BE CHANGED - LIMITS UNDER WORKING BUS VOLTAGE NOT PROPERLY CALCULATED</i>					
18. REWORK/TEST ACTION TAKEN <i>None</i>					
19. LIST ALL PARTS REPLACED					
PART NUMBER					
QTY					
PART LOT NO.					
DATE CODE					
USR					
PROBABLE DEFECT					
ANALYSIS NO.					
20. CAUSE AND CORRECTIVE ACTION <i>Test procedure limits too tight - test procedure modified to relax limits - 16.9V to 17.5V and new limits NEW LIMITS 13.9V TO 17.5V</i>					
21. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>TP 3569224/SCN1</i>					
22. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> HIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/FAB ERROR <input type="checkbox"/> POLISH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SETUP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
23. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input checked="" type="checkbox"/> INDUCED					
24. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
25. RESPONSIBLE ENGINEER <i>RJ Julian</i>		ORG <i>414</i>	DATE <i>8/7/80</i>	26. SPACECRAFT SYSTEM ENGR <i>TS/Prasad</i>	
27. RELIEVED BY		ORG <i>51-41</i>	DATE <i>8/11/80</i>	28. CUSTOMER OR SUPPLIER <i>SBRC</i>	

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 282

1. PROGRAM NAME AND NUMBER <i>THANATIC MIPPLE 4523C</i>		2. QLA <i>E330</i>	3. MODEL <i>F</i>	4. TIME OBSERVED <i>10 00</i>	5. DATE OBSERVED <i>NOV 20 80</i>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART						
7. EQUIPMENT IDENTIFICATION:						
7. EQUIPMENT NAME		PART NUMBER		ENV	MANUFACTURER	
8. UNIT <i>Multiplexer</i>		<i>3533003-100</i>		<i>F</i>	<i>HAC</i>	
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<i>A6</i>		<i>147018</i>	<i>HAC</i>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
11. OTHER						
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM						
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> ALTITUDE <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMPERATURE <i>2147</i> °E <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> WRE AT ° <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXID FOR MIN <input type="checkbox"/> TYPG <input type="checkbox"/> OTHER						
14. DESCRIPTION OF FAILURE <i>Rail Voltage "A" test point reads lower than tolerance -1.6v to -1.8v. @ 1470F</i>						
15. TEST PROCEDURE <i>3569224 9.4/5.9.4</i>		16. ORIGINAL FROM <i>R. Yamashita</i>		DATE <i>NOV 1 5/20/80</i>	CONTINUATION SHEET <input type="checkbox"/>	
18. VERIFICATION AND FAILURE ANALYSIS						
19. FAILED ITEM NAME AND PART NUMBER						
20. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>SPEL TO BE REVISED LIMIT GIVEN IS ERRONEOUS. UNIT PERFORMANCE IS CORRECT.</i>						
21. AUTHORIZATION <i>RL Julian</i> ORG <i>4141</i> DATE <i>5/20/80</i> CONTINUATION SHEET USED <input type="checkbox"/>						
22. REPORT/RETEST ACTION TAKEN <i>Done</i>						
23. LIST ALL PARTS REPLACED						
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	WFR	PROBABLE DEFECT	ANALYSIS NO.
27. REPORT BY ORG DATE 28. RETESTED BY ORG DATE CONTINUATION SHEET USED <input type="checkbox"/>						
29. CAUSE AND CORRECTIVE ACTION <i>Test procedure limits too tight - test procedure modified to relax limits - Bd only OK, and must not limit. NEW LIMITS 1.50V TO -1.90 V. (SCN 1)</i>						
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>TP 3569224/SCN1</i>						
31. BASIC CAUSE OR VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT						
32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE		33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY		34. SPACECRAFT SYSTEM ENG. ORG <i>SRC</i> DATE <i>8/11</i>		
35. RESPONSIBLE ENGINEER <i>RL Julian</i> JRC <i>4141</i> DATE <i>8/4/80</i>						

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 25

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper</i> <i>HS 236</i>		2. QLA <i>E330</i>	3. MODEL <i>F</i>	4. TIME OBSERVED <i>10 00</i>	5. DATE OBSERVED <i>8/20</i>
6. HARDWARE LEVEL <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	SN
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>	<i>F</i>
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<i>AL6</i>		<i>3569224</i>	<i>13, 14</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input type="checkbox"/>					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMPERATURE <i>133° F</i> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> WRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Fail Voltage "A" test point reads in excess of spec tolerance -1.6V to -1.8V @ +33°F</i>					
15. TEST PROCEDURE <i>3569224</i>		<i>8.5/524</i>	16. ORIGINATOR <i>R. Yoness</i>	<i>9/41</i>	<i>5/20/8</i>
17. VERIFICATION AND FAILURE ANALYSIS					
18. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>SPCL TO BE REUSED. LIMIT GIVEN ERRONEOUS. MODULE PERFORMANCE IS ABOVE</i>					
19. AUTHORIZATION <i>RL Julian</i> <i>41-41</i> <i>5/20/8</i> <input type="checkbox"/> CONT SHEET					
20. REWORK ACTIVITY ACTION TAKEN <i>None</i>					
21. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	WFR	PROBABLE DEFECT
22. REWORK BY ORG DATE 23. RETESTED BY ORG DATE <input type="checkbox"/> CONT SHEET					
24. CAUSE AND CORRECTIVE ACTION <i>Test Procedure limits too tight - test procedure modified to relax limits - 3rd party OK and meets our limits. NEW LIMITS PAGE -1.9V TO -1.5 V, SEE TP SCN1</i>					
25. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>TP 3569224/SCN1</i>					
26. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
27. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN 28. FAILURE CLASSIFICATION: <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
29. RESPONSIBLE ENGINEER <i>R. Julian</i>		ORG <i>41-41</i>	DATE <i>13/7/80</i>	30. SPACECRAFT SYSTEM ENGR <i>Frederick</i>	
31. CUSTOMER OR		DATE			

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 282

1. PROGRAM NAME AND NUMBER <i>THEMATIC MATHEM</i> <i>HS 236</i>		2. QLA <i>E330</i>	3. MODEL <i>F</i>	4. DATE OBSERVED <i>10/30</i>	5. DATE OBSERVED <i>7/16/80</i>	NO. OF <i>7</i>	ON <i>16</i>
6. HARDWARE LEVEL WHERE FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MCM'S	<input type="checkbox"/> CARD <input type="checkbox"/> PART		
6. EQUIPMENT IDENTIFICATION:							
7. SUBSYSTEM <i>PF</i>		NAME		PART NUMBER		S/N	
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>		<i>2</i>	
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <i>76</i>				<i>3569224</i>		<i>16</i>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MCM'S <input type="checkbox"/> CARD							
11. OTHER							
12. TEST WHICH FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION	<input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION	<input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHERE FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE		<input type="checkbox"/> VIBRATION	AXIS FOR	MIN	TYPE	<input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT	
14. DESCRIPTION OF FAILURE <i>Seem a input buffer has become drop in D.C. section made.</i>							
15. TEST PROCEDURE <i>3569224</i>		PARA	16. OPERATOR <i>R. Gamauchi</i>	DATE <i>7/16/80</i>	17. CONTINUATION SHEET		
18. VERIFICATION AND FAILURE ANALYSIS <i>Isolated to input buffer HX1 on front Assy</i>							
19. FAILED ITEM NAME AND PART NUMBER <i>3569224</i>							
20. FOLLOWING REPAIR/TEST REQUIRED EXCEPT TEST NOT REQUIRED BECAUSE <i>Replace HX1 on front Assy</i>							
21. RETEST TO T.P. <i>3569224</i>							
22. REPAIR/TEST ACTION TAKEN <i>Replaced HX1</i>							
23. RETEST TO T.P. <i>3569224</i>							
24. LIST ALL PARTS REPLACED		CKT SYM	PART LOT NO.	DATE CODE	USR	PROBABLE DEFECT	ANALYSIS NO.
<i>Hx1 3905969</i>		<i>HX1</i>			<i>HAC</i>		
27. REVIEWED BY <i>16612</i>		DATE <i>5/14/81</i>	28. RETESTED BY <i>R. Gamauchi</i>	DATE <i>8/12/80</i>	29. CONTINUATION SHEET		
30. CAUSE AND CORRECTIVE ACTION <i>No failure, so no corrective action required. Although the hybrid did pass subassembly test, it performed within limits allowed by the design. The specification value was intentionally chosen to maximize the performance of the devices used, and will not be changed. Passes hybrid level test</i>							
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>Subassembly (Cushier Assy) has tighter requirements. No further action is to be taken. A subassembly investigation TM-45236-7402</i>							
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION							
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/PACK ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> SHIPPING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> REAR-OUT	<input type="checkbox"/> UNKNOWN DEFECT CODE		
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR		37. SPACECRAFT SYSTEM ENGINEER <i>R. Gamauchi</i>		38. DATE <i>7/16/80</i>	
39. RELIABILITY <i>1.8 M.M.</i>		ORG <i>51-41</i>	DATE <i>7/16/80</i>	40. CUSTOMER OR SUPPLIER <i>BB</i>	DATE <i>7/16/80</i>	41. DATE <i>3/14</i>	

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Co.-pany
INTERNAL MEMORANDUM

F-2825

TO: R.J. Wilkerson
51-41

CC: See Distribution List

DATE: 13 April 1981

REF: HS 236-7402
PE 81/72

FROM: L. O'Connell
51-41

SUBJECT: Input Buffer Hybrid (P/N 3905969)
Failures

BLDG. 774 MAIL STA. 39
EXT. 4485

On February 2, 1981 the Product Effectiveness Manager for the TM Program, Mr. R.J. Wilkerson, and the author of this memo conducted a review of the manufacturing data for subject hybrids. The purpose of this review was to determine if a generic failure mode was common to the five hybrids that failed in the multiplexer.

Investigation findings are as follows:

1. Sixty-one hybrid manufacturing records were reviewed.
2. Defects in the manufacturing cycle were random with no known trend.
3. There was not a bonding process problem and all hybrids were subjected to 100% pull test.
4. Four of the five failed hybrids had a history of major rework/workmanship problems.
5. Unable to locate a reliability to process/design problem
6. All operations on the Quality History Records were complete and Air Force concurrence was on all operations and inspections as required. Some minor documentation problems were found, however they had no effect on the hardware.

In addition to the review of the Manufacturing records, as stated above, the Reliability Organization reviewed the five Failure Reports for subject Hybrids and their findings are as follows:

1. FR 1935 (S/N 523) and FR 2816 (S/N 554).

These Hybrids had excessive gain. S/N 523 was sent to Technical Services Division (TSD) for failure analysis. The failure mode "Excessive Gain" was confirmed. The cause of the failure was a shorted capacitor due to a scratch mark on the surface of the Capacitor. (Mechanical damage to the capacitor oxide caused the short).

2. FR 2812 (S/N 525)

This Hybrid failed when the DC level changed in the DC Restore Circuit. This Hybrid was sent to TSD for analysis. The failure mode "Static DCR Offset Voltage of Channel 4 out of Specification", was verified. The failure was due to shorts between MOS FET transistors Q3 and Q4. The cause of the failure was mechanical

ORIGINAL PAGE IS
OF POOR QUALITY

F2025

To: R.J. Wilkerson
Subject: Input Buffer Hybrid (P/N 3905969) Failures

Page 2
HS 236-7402

damage (smearing and scratches) that damaged the underlying oxide.

3. FR 1937 (S/N 516)

Sensor 4 of this Hybrid failed the Buffer Limit Test. It was not sent to TSD for analysis.

4. FR 2825 (S/N 520)

Sensor 2 of this Hybrid failed for Excessive Droop. It was not sent to TSD for analysis.

5. After the review of the Failure Reports, Failure Analysis Reports and Manufacturing History Records for the above (5) Hybrids, it has been concluded that there are occasions when Hybrids have been delivered with incipient failures that are not recognizable by inspection after the units are sealed.

Major rework and workmanship defects were found in the History Records of four (S/N 516, 520, 523 and 525) of the five Hybrids. This lends some credence to a correlation between failure mode and manufacturing difficulties.

Conclusions

Analysis of both the Product Effectiveness review of the Manufacturing History Records and the Reliability Review of the Failure Reports and their associated Failure Analysis Reports, the following conclusions have been reached:

1. Assuming a correlation between rework/workmanship defects, it appears that latent defects can escape the normal Hybrid In-Process Inspection and Test Techniques.

The findings and comments of the Product Effectiveness Investigative Team was communicated to the responsible Quality Assurance Section Head who has cognizance over the Hybrid Manufacturing Operation.

At this time contract quantities of subject Hybrids for the Thematic Mapper have long been delivered, however the information gained will be extremely useful for future Thematic Mapper buys and other program

2. A learning curve in the Manufacturing Process for these highly complex Hybrid circuits was in effect, as evidenced by the reduction in workmanship defects and parts replacement as the manufacturing process matured.


ORIGINAL PAGE IS
OF POOR QUALITY

F 2825

TO: R.J. Wilkerson
Subject: Input Buffer Hybrid (P/N 3905969) Failures

Page 3
HS 236-7402

3. Those Hybrids with incipient defects will fail under unit test and thus be eliminated from the system.
4. It has been concluded by the undersigned that the integrity and reliability of Thematic Mapper hardware using subject Hybrids has not been impinged.



L. O'Connell
Administrative and Reliability Manager
Thematic Mapper Program

LOC:jc

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 3657

ORIGINAL PAGE IS
OF POOR QUALITY

1 PROGRAM NAME AND NUMBER <i>Thematic Mapper HS236</i>		2 GLA <i>E330</i>		3 MODEL <i>FLT</i>		4 TIME OBSERVED <i>1215</i>		5 DATE OBSERVED MO <i>7</i> DA <i>11</i> YR <i>8</i>		
6 HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:										
7 SUBSYSTEM			NAME		PART NUMBER		S/N		MANUFACTURER	
8 UNIT <i>Multiplexer</i>					<i>3533003-100</i>		<i>3</i>		<i>HAC</i>	
9 <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
10 <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD										
11 OTHER										
12 TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS										
13 ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP _____ ° <input type="checkbox"/> THERMAL VAC _____ HRS AT _____ ° <input type="checkbox"/> OTHER										
14 DESCRIPTION OF FAILURE <i>J6 (Back-up NR2) output only. 25VAP loading differentially across J6 pins 1 and 21.</i>										
15 TEST PROCEDURE <i>32015-005</i>		16 PARA <i>3.6.2.2</i>		16 ORIGINATOR <i>Jim Anich</i>		17 ORG <i>41-41</i>		18 DATE <i>7/15/81</i>		19 CONTINUATION SHEET USED <input type="checkbox"/>
18 VERIFICATION AND FAILURE ANALYSIS <i>Isolated to U14 output driver. NO possible of other damage due to this failure. Defective part introduced only with protected circuitry in unit test station - RLS-3</i>										
19 FAILED ITEM NAME AND PART NUMBER										
20 FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>Replaced U14 on front Assy of module A1</i>										
21 REPRODUCTION <i>Jim Anich</i>										
22 CONTINUATION SHEET USED <input type="checkbox"/>										
23 REWORK/RETEST ACTION TAKEN <i>Replaced U14 on front Assy. Isolated unit P. 32015-005 para 3.6.2.2 See photographs taken 12/1/81</i>										
24 QA REVIEWED <input type="checkbox"/>										
25 TEST TEST 527										
26 LIST ALL PARTS REPLACED										
PART NUMBER		CKT SYM	PART LOT NUMBER		DATE CODE	MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMB
<i>911958-001</i>		<i>U14</i>								
27 REWORK BY <i>F.Y. 6/26/81</i>										
ORG <i>45-21</i>		DATE <i>10-20-81</i>		28 TESTED BY <i>Jim Anich</i>		ORG <i>41-41</i>		DATE <i>12/1/81</i>		29 CONTINUATION SHEET USED <input type="checkbox"/>
30 CAUSE AND CORRECTIVE ACTION <i>DEFECTIVE PART - FOR ANALYSIS & CORRECTIVE ACTION REFER TO HS 236-7786 (COPY ATTACHED)</i>										
31 FRB CLOSURE										
32 CONTINUATION SHEET USED <input type="checkbox"/>										
33 DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>HS 236-7786 (COPY ATTACHED)</i>										
34 BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP		<input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT		<input type="checkbox"/> UNKNOWN DEFECT CODE
35 FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36 FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY						
37 RESPONSIBLE ENGINEER <i>William</i>		ORG <i>41-41</i>		DATE <i>12/9/81</i>		38 SPACECRAFT SYSTEM ENGINEER <i>William</i>		ORG <i>53RC</i>		DATE <i>12/2</i>
39 RELIABILITY		ORG <i>57-41</i>		DATE <i>12/23/81</i>						

ORIGINAL PAGE IS
OF POOR QUALITY

TP 32015-005
04 SEP 1980

REVIEWED
PAGES
S-4-9
12/2/81

F365

PAGE 89

ITA SHEET



J.6.2.2 Serial Data and Bit Clock Parameters

SIGNAL	CONNECTOR	PIN NO.	SCOPE	INPUT	LOGIC "0"	LOGIC "1"	TRANSITION TIMES	
					-0.46 to -1.36V	+0.46 to +1.36V	20% to 80%	REQ: 23.5ns tr
1. Output NRZ-L Data	MX15B01T	J5-1	+					
	B01F	J5-2	-		-1.5	+1.5	2.0	2.0
2. Backup	MX15B02T	J6-1	+					
	B02F	J6-2	-		-1.5	+1.5	2.2	2.0
3. Output Bit Clock	MX15B03T	J7-1	+					
	B03F	J7-2	-		-1.5	+1.5	3.1	3.0
4. Backup	MX15B04T	J8-1	+					
	B04F	J8-2	-		-1.5	+1.5	3.2	3.0

Test passed. By 12/2/81



02 '81



QUALITY ASSURANCE

DATA SHEET

3.5.2.2 Serial Data and Bit Clock (cont).

HAC
175
521

BC 02 M

ORIGINAL PAGE IS
OF POOR QUALITY

page 90
F 3657

SIGNAL	PHASING	
	Delay from + edge of Clock #15R03	Delay from + edge of Clock #X15B01
1. Output /RZ-L Data		
#X15R01	4.0	4.0
#01F	3.9	4.0
2. #ACKUD		
#07F	4.0	3.8
3. Output Bit Clock		
#15R03		1.1
#15R04		1.0
4. #ACKUD		
#15R05	1.1	1.0

Frequency of Output Bit Clock #X15R03T: MHz
Reqs't. : 84.8141 to 84.9679 MHz

848915

* For Reference only.





Test passed by Mr. [Signature]

HAC
175
521

ORIGINAL PAGE IS
OF POOR QUALITY

F 3657

FBI WASH DC
AUG 30 1951
REC-27
11-11
527



1-4 2-1
12-2-51
REC-27
11-11
527

REC-27
11-11
527

ORIGINAL PAGE IS
OF POOR QUALITY

F3657

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company

INTERNAL MEMORANDUM

TO: G. Gritt

CC: L. Altman

DATE: 23 December 1981

REF: HS 236-7786

PE 227:81

FROM: L. O'Connell
51-41

BLDG. B-11 MAIL STA. 39

EXT. 6293


SUBJECT: Failure Report F3657

The Failure mode reported on subject Failure Report was traced to a defective output driver (P/N 911958-001). Reliability cannot submit the defective part to TSD (Technology Services Division) for Failure Analysis because the responsible Multiplexer personnel cannot locate the part.

Since the part is not available for analysis the author of this memo has taken the following actions:

1. Requested the Thematic Mapper Parts Board to research the El Segundo Receiving Inspection Records to determine if there were any previous defective output driver's (P/N 911958-001). This has been accomplished and there were no previous failures. (Refer to HS 236-7785 attached).
2. Reliability has reviewed the Verified Component Failure List and there were no previous failures.
3. Contacted the responsible Multiplexer Engineer and responsible Quality Assurance Engineer for the Multiplexer area and informed them as to the importance of impounding failed parts so they can be analyzed. In addition they were informed that it is mandatory to maintain discipline with all personnel so this type of error (and others) can be prevented on other programs as well as future programs.

Based on the investigation by both the Part's Board and Reliability (listed above) the author is confident that this is a random failure and no generic problem exists with these parts.


L. O'Connell, Manager
Administration and Reliability

LOC:jc

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

F 3657

TO: L. O'Connell;
51-41

CC: F. Carlo

DATE: 22 December 1981

REF: HS 236-7785

PE 226:81

FROM: L. Altman
51-41


BLDG. B-11 MAIL STA. 39

EXT. 6257

SUBJECT: Integrated Circuit
P/N 911958-001

Per your request, the Parts Board has researched the Parts Analysis Laboratory's (Dept. 46-31-12) records for the previous history of subject part.

These records show no problems with Integrated Circuits (P/N 911958-001).


L. Altman, Manager
Product Effectiveness
Thematic Mapper Program

LA:jc

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 366

1. PROGRAM NAME AND NUMBER <i>Testbed Alpha H5236</i>		2. SIA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1340</i>	5. DATE OBSERVED <i>MO 11 DA 10 YR 81</i>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:						
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER	
8. UNIT <i>Multiplexer</i>			<i>3523 003-100</i>	<i>3</i>	<i>HAC</i>	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
11. OTHER						
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE						
<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS						
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT						
<input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER						
14. DESCRIPTION OF FAILURE <i>Panel 1 removed & failed D.C. Regulator test - Test point apparently open in test harness or in unit</i>						
15. TEST PROCEDURE <i>TJ 23015-005</i>						
16. VERIFICATION AND FAILURE ANALYSIS <i>This test failed due to tester failure. Improperly mated connectors.</i>						
17. CONTINUA SHEET USE						
18. FAILED ITEM NAME AND PART NUMBER						
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>No rework action taken on unit</i>						
20. AUTHORITY <i>J. J. Smith</i>						
21. REWORK/RETEST ACTION TAKEN <i>See notes on page of retest report on 11/30/81</i>						
22. CONTINUA SHEET USE						
23. LIST ALL PARTS REPLACED						
PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS M
24. REWORK BY						
ORG	DATE	TESTED BY	ORG	DATE	CONTINUA SHEET USE	
		<i>J. J. Smith</i>		<i>11/30/81</i>		
25. CAUSE AND CORRECTIVE ACTION <i>CAUSE: MISMATCHED CONNECTOR. WHEN REMATED, UNIT FUNCTIONED PROPERLY. NO FAILURE, NO FURTHER CORRECTIVE ACTION REQUIRED. R.L. Julian 12/1/81</i>						
26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>Hughes Prod to MATING Manual 12/1/81</i>						
27. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT <input checked="" type="checkbox"/> UNKNOWN						
28. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE						
29. RESPONSIBLE ENGINEER <i>R.L. Julian</i>						
30. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR SAFETY						
31. CONTINUA SHEET USE						
32. SYSTEM ENGINEER <i>J. J. Smith</i>						
33. PART NUMBER OR SUPPLIER <i>3015</i>						

TEST S27

J. J. Smith
12/21

HUGHES

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 425

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINATOR	1. PROGRAM NAME AND NUMBER <i>HS236</i>		2. GRA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1500</i>	5. DATE OBSERVED <i>MO 7 DA 1 YR 8</i>	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION:		NAME	PART NUMBER	S/N	MANUFACTURER	
	7. SUBSYSTEM						
	8. UNIT <i>Multiplexer</i>			<i>3533003-100</i>	<i>3</i>	<i>Hac</i>	
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
	11. OTHER						
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS		
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP <i>+50.0 C</i>	<input type="checkbox"/> THERMAL VAC	HRS AT _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <i>Band 9 sensor 7 fails to Threshold test</i>							
ENGINEERING EVALUATION	18. TEST PROCEDURE <i>32015-005</i>		19. PARA <i>3.5.35</i>	10. ORIGINATOR <i>Jim Smith</i>	11. ORG <i>9-41</i>	12. DATE <i>7-1-81</i>	
	18. VERIFICATION AND FAILURE ANALYSIS <i>Failure was due to faulty relay in unit tester. No possibility of component damage due to this failure. Inputs protected by 15K resistors. R.T. Wilson</i>		19. FAILED ITEM NAME AND PART NUMBER				
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<i>No rework action taken on unit.</i>				
	21. AUTHORIZATION <i>Jim Smith</i>		13. ORG <i>9-41</i>	14. DATE <i>11/25/81</i>	17. CONTINUATION SHEET USE		
MANUFACTURING AND TEST	21. REWORK/RETEST ACTION TAKEN <i>See retest on Pg 414 of penalty test.</i>		24. CONTINUATION SHEET USE		25. PART TEST S26		
	22. LIST ALL PARTS REPLACED	PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	
	27. REWORK BY	ORG	DATE	26. RETESTED BY <i>Jim Smith</i>	15. ORG <i>9-41</i>	16. DATE <i>11/25/81</i>	
ENGINEERING/RELIABILITY	30. CAUSE AND CORRECTIVE ACTION <i>Cause: defective relay in test equipment. Relay replaced and successful retest conducted. R.T. NO further corrective action required.</i>		31. CONTINUATION SHEET USED		32. FRD CLOSURE		
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		31. CONTINUATION SHEET USED				
	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	<input checked="" type="checkbox"/> UNKNOWN DEFECT CODE	
	35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER <i>R.T. Wilson</i>		18. ORG <i>9-41</i>	19. DATE <i>12/1/81</i>	38. SPACECRAFT SYSTEM ENGINEER <i>Jim Smith</i>		19. ORG <i>9-41</i>	
39. RESPONSIBILITY <i>...</i>		18. ORG <i>9-41</i>	19. DATE <i>12/1/81</i>	39. CUSTOMER OR SUPPLIER <i>...</i>		20. ORG <i>...</i>	

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
25 SEQUOIA, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4254

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper HS 236</i>		2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1100</i>	5. DATE OBSERVED <i>MO 7 DA 6 YR 8</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT <i>Multiplexer</i>			<i>3533003-100</i>	<i>3</i>	<i>HAC</i>
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input checked="" type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<i>8</i> TEMP <i>ESS-C</i>	<input type="checkbox"/> THERMAL VAC	HRS AT <input type="checkbox"/> OTHER
14. DESCRIPTION OF FAILURE <i>numerous x talk errors see cont sheet.</i>					
15. TEST PROCEDURE <i>32015-005</i>		16. PARA <i>3.5.3.6</i>	17. OPERATOR <i>R. Giamarchi</i>	18. ORG <i>4-41</i>	19. DATE <i>7/14/81</i>
20. VERIFICATION AND FAILURE ANALYSIS <i>Failures verified, gear channels slightly out of specification. Grounding of failed channels indicates that analog multiplexer hybrid may be partial cause.</i>		21. FAILED ITEM NAME AND PART NUMBER <i>3533003-100</i>			
22. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<i>Replace Analog Multiplexer Hybrid Board 2 H71 and Board 7 H72. Refer to HS 236-2260 (copy attached)</i>			
23. REWORK/RETEST ACTION TAKEN <i>Replaced two 3905973 Hybrids as stated above. Retested per TP 3533003-100 para 3.5.3.6.</i>		24. AUTHORIZATION		25. ORG	26. DATE
27. LIST ALL PARTS REPLACED		28. PART NUMBER	29. CKT SYM	30. PART LOT NUMBER	31. DATE CODE
32. REWORK BY <i>67658 R.V.</i>		33. ORG <i>4-41</i>	34. DATE <i>10-20-81</i>	35. RETESTED BY <i>Giamarchi</i>	36. ORG <i>4-41</i>
37. CAUSE AND CORRECTIVE ACTION <i>Minor cross-talk between some channel pairs is an unavoidable consequence of the assembly and design used. It will not adversely affect system performance. So no design change will be undertaken.</i>		38. CONTINUATION SHEET USED			
39. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (copy attached) (attached)</i>		40. CONTINUATION SHEET USED			
41. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT	<input type="checkbox"/> TEST PROCEDURE	<input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR
42. FAILURE MODE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN	<input type="checkbox"/> NO FAILURE	43. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR	<input type="checkbox"/> WORKMANSHIP
44. RESPONSIBLE ENGINEER <i>R.L. Sullivan</i>		45. ORG <i>4-41</i>	46. DATE <i>12/9/81</i>	47. SYSTEM ENGINEER <i>J. Thomas</i>	48. ORG <i>2241</i>
49. RELIABILITY <i>See flow</i>		50. ORG <i>51-41</i>	51. DATE <i>12-10-81</i>	52. CUSTOMER OR SUPPLIER <i>IBM</i>	53. DATE

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.
F 4254
CONTINUATION SHEET LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR
CONTINUATION
SHEET(S) USED

14	7/4/81	X Talk Band and Season Failures
		1 ***
		2
		2**
		2***
		2***
		2***
		4
		6
		6
		6
		6
		7
		7
		7***
		7***

7 -> BAND 7 FAILURE CAUSE BY BAD EQUIP IN TEST EQUIP
2 -> PASSED ON RETEST AFTER REPAIR
5 -> FAILED ON RETEST - TRANSFERRED TO F-072
6 -> PASSED ON RETEST AFTER REPAIR
7 -> PASSED " " " "
8 -> PASSED " " " "
16 -> FAILED ON RETEST - SEE W124
1 " " " " "
2 " " " " "
3 " " " " "
4 " " " " "
7 " " " " "
13 " " " " "
15 -> PASSED ON RETEST AFTER REPAIR
16 -> PASSED " " " "

14	11/25/81	Band 7 minor 7 and Band 7 minor 12 failed X talk.
		15
		5/6
		07 57 (0755) (2) 93
		07 513 (07511) (2) 153

≤ 30 SEE W124 - TABLE 1
≤ 30 " " " "

* SEE W124 - TABLE 1
*** PASSED ON RETEST - THEREFORE NOT ON W124
*** PROBLEM TRACED TO BAD RELAY IN TEST EQUIPMENT
PARTS WHEN TESTED WITH REPAIRED TEST EQUIPMENT.
NOTE: PASSED AFTER REMOVAL & REPLACEMENT OF HYBRIDS
P/N 3905973 37, 512 & 502. REFER TO BLANK 23
OF THIS FR.

ORIGINAL PAGE IS
OF POOR QUALITY

4254

REQUEST FOR DEVIATION/DAIVER
(SEE 811-STD-600 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PRECEDENCE ACTIVITY OR

1. ORIGINATOR NAME AND ADDRESS
Hughes Aircraft Co, SCG, El Segundo, California

2. DEVIATION DAIVER

3. CHANGE CHANGE CRITICAL

4. DESIGNATION FOR DEVIATION/DAIVER

a. MODEL/TYPE Flight	b. WFO. CODE 82577	c. SYS. DESIG. TM	d. OPERATING CO. W124
-------------------------	-----------------------	----------------------	--------------------------

5. BASIC LINE AFFECTED
 PLAC. TIONAL ALLG-CATED PERM-LTY

6. OTHER SYSTEMS/CERTIFICATION ITEMS AFFECTED
 YES NO

7. SPECIFICATIONS AFFECTED-TEST PLAN

WFO. CODE	SPEC./ESC. NO.	REV.	WFO. CODE	REV.	WFO. CODE
a. SYSTEM					
b. ITEM					
c. TEST PLAN					

8. CHANGES AFFECTED

WFO. CODE	REV.	WFO. CODE
a. SYSTEM		
b. ITEM		
c. TEST PLAN		

9. TITLE OF DEVIATION/DAIVER
Minor Performance Discrepancies, S/N 003 Multiplexer

10. CONTRACT NO. & LINE ITEM
NAC 5-24200 L.I. 32

11. IDENTIFICATION TYPE AND RELATIONSHIP
Multiplexer

12. CLASSIFICATION OF IMPACT
 CHANGE CHANGE CRITICAL

13. EFFECT ON COST/PRICE
None

14. EFFECT ON DELIVERY SCHEDULE
18 months schedule slip is disapproved

15. EFFECT ON OPERATIONAL SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/DAIVER

The S/N 003 Multiplexer (P/N 3513003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REASONS FOR DEVIATION/DAIVER

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian REL [Signature] QA [Signature]

SYS. ENGR. [Signature] DE [Signature]

18. APPROVAL/DISAPPROVAL

[Signature] 81 12 10

19. APPROVAL/DISAPPROVAL

APPROVAL RECEIVED APPROVED DISAPPROVED

20. DEVELOPMENT ACTIVITY
NASA GSFC

21. SIGNATURE
[Signature]

ORIGINAL PAGE IS
OF POOR QUALITY

4254

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

4254

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

4254

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

4254

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8		F4266
7	13	+15			241	-0.4		F4266
6	1	+15	193	41.7	192	-0.1		F4266
6	2	+15	193	37.3				F4266
6	3	+15	193	39.1	192	-0.4		F4266
6	4	+15	193	39.3	192	-0.3		F4266
6	1	+50	128	39.8	129	-0.1		F4267
6	2	+50	128	37.0	129	-0.1		F4267
6	3	+50	128	36.8				F4267
6	4	+50	128	36.8	192	-0.1		F4267
6	1	Ambient	193	39.4	160	-0.1		F4265
6	2	Ambient	193	37.5	160	-0.5		F4265
6	3	Ambient	225	35.5	224	-0.8		F4265
6	4	Ambient	193	39.6	232	-0.2		F4265

TABLE 3. A/D CONVERSION FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

4254

TO: G. Gritt
SUBJECT: 3905973 Hybrid Crosstalk Testing

CC: L. O'Connell

DATE: 22 December 1981

REF: HS 236-2260

PE 225:81

FROM: R. Julian
41-41

BLDG. B-11 MAIL STA. 39

EXT. 6293

Two 3905973 hybrids were removed in an attempt to fix the crosstalk in Bands 2 and 7 of the S/N 3 Multiplexer. (Ref. FR No.'s F4254, F4257, and F4258). These hybrids are not being formally failure analyzed because:

1. Crosstalk is caused by a combination of the hybrids and the unit wiring, and is not observable at the hybrid level.
2. The hybrids are tested by observing output levels with an oscilloscope. Errors of the size involved (1/2% of full scale, max.) are not visible on oscilloscopes.
3. The hybrids would pass all their tests and are fully functional.

In the course of hybrid repair, we will make static measurements to see whether these hybrids are abnormal in any detectable way.

R. C. Julian

Richard C. Julian
REA, Multiplexer
Thematic Mapper Program

RCJ:jc

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
TULSA, OKLAHOMA, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY W124

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4255

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper - H5 236</i>		2. GLA <i>E330</i>		3. MODEL <i>FCT</i>		4. TIME OBSERVED <i>0920</i>		5. DATE OBSERVED <i>MO 7 DA 9 YR 81</i>							
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input checked="" type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION:															
7. SUBSYSTEM		NAME			PART NUMBER		S/N		MANUFACTURER						
8. UNIT <i>MULTIPLIER</i>					<i>3533003-100</i>		<i>3</i>		<i>HAC</i>						
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY															
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD															
11. OTHER:															
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input checked="" type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<i>TEMP 170F 170F</i> AXIS FOR		<input type="checkbox"/> THERMAL VAC		HRS AT							
14. DESCRIPTION OF FAILURE <i>Band 1 sensor 3 and Band 5 sensor 6 Failed Input Buffer Drop Test: 3/PT 3.3 MV/Sec. ALS 3 is 4.24 MV/Sec. and ALS 6 is 5.04 MV/Sec.</i>															
15. TEST PROCEDURE <i>32015-005</i>		16. PARA <i>3.5.3.3</i>		17. ORIGINATOR <i>J. J. J.</i>		18. ORG <i>H-41</i>		DATE <i>7/9/81</i>		19. CONTINUATION SHEET USED <input type="checkbox"/>					
20. VERIFICATION AND FAILURE ANALYSIS															
21. FAILED ITEM NAME AND PART NUMBER															
22. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>REFER TO WAIVER W124 (COPY ATTACHED)</i>															
23. AUTHORIZATION															
24. CONTINUATION SHEET USED <input type="checkbox"/>															
25. QA REWORK															
26. QA RETEST															
27. LIST ALL PARTS REPLACED		PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUM	
27. REWORK BY															
28. REWORK BY		ORG		DATE		28. RETESTED BY		ORG		DATE		29. CONTINUATION SHEET USED <input type="checkbox"/>			
30. CAUSE AND CORRECTIVE ACTION <i>REFER TO W124 TABLE 2</i>										31. FRB CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>										33. CONTINUATION SHEET USED <input type="checkbox"/>					
34. BASIC CAUSE OF FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN		DEFECT CODE			
35. FAILURE MODE		<input type="checkbox"/> PRIMARY <input type="checkbox"/> UNOUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE ENGINEER <i>R. J. J.</i>		ORG <i>H-41</i>		DATE <i>12/9/81</i>		38. SPECIALIST SYSTEM ENGINEER <i>J. J. J.</i>		ORG <i>2241</i>		DATE <i>12/10/81</i>					
39. RELIABILITY		ORG <i>H-41</i>		DATE <i>12-10-81</i>		40. SPECIALIST SYSTEM ENGINEER <i>J. J. J.</i>		ORG <i>H-41</i>		DATE <i>12/10/81</i>					

12/14/81

12/24/81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.
F4255
CONTINUATION SHEET LETTER
A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

ADDITIONAL FR CONTINUATION SHEETS USED

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

14 11/24/81 Band 5 Sensor 6 failed drop test. is 3.46 MV/sec
5/16 ± 3.3 MV/sec

14 11/30/81 Band 1 Sensor 3 failed drop test is 4.11 MV/sec
5/16 ± 3.3 MV/sec

Band 5 Sensor 6 failed drop test is 4.90 MV/sec
5/16 ± 3.3 MV/sec

ORIGINAL PAGE IS
OF POOR QUALITY

4255

REQUEST FOR DEVIATION/DEVIAE
(SEE MIL-STD-469 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PRECEDENCE ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Co, SCG, El Segundo, California				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> DEVIAE	
				3. <input checked="" type="checkbox"/> CHANGED <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/DEVIAE				5. BASE LINE AFFECTED	
6. MODEL/TYPE Flight	7. CFR. CODE 82577	8. SYS. DESIG. TM	9. DEVIAE NO. W124	<input type="checkbox"/> PLUG-TYPICAL	<input type="checkbox"/> ALLG-CATED
				<input type="checkbox"/> SPEC-LECT	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
9. DRAWINGS AFFECTED			10. ESTIMATE NO. & LINE ITEM		
			NAS 3-24200 L.I. 32		
11. CONFIGURATION ITEM IDENTIFICATION				12. DEFECT CLASSIFICATION	
Multiplexer				<input type="checkbox"/> CHANGED <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
13. NAME OF PART OR ASSEMBLY AFFECTED Multiplexer		14. PART NO. OR TYPE DESIG.		15. LOT NO.	
				16. QTY	
17. EFFECT ON COST/PRICE None				18. REQUIRES DEVIATION/DEVIAE <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON DELIVERY SCHEDULE 18 months schedule slip is disapproved				20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, SUPPORTABLE, ETC.	

23. DESCRIPTION OF DEVIATION/DEVIAE

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REAS FOR DEVIATION/DEVIAE

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian REL [Signature] QA [Signature]
 SYS. ENGR. [Signature] PE [Signature]

25. APPROVAL AUTHORITY AUTHORITY AND SIGNATURE

[Signature] 26. TITLE

27. APPROVAL/DISAPPROVAL

28. GOVERNMENT ACTIVITY

APPROVAL RECOMMENDED APPROVED DISAPPROVED

NASA GFCF [Signature] DATE

ORIGINAL PAGE IS
OF POOR QUALITY

4255

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

u2 5

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

U255

BAND	SENSOR	TEMPERATURE	M./SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

4255

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8		F4266
7	13	+15			241	-0.4		F4266
6	1	+15	193	41.7	192	-0.1		F4266
6	2	+15	193	37.3				F4266
6	3	+15	193	39.1	192	-0.4		F4266
6	4	+15	193	39.3	192	-0.3		F4266
6	1	+50	128	39.8	129	-0.1		F4267
6	2	+50	128	37.0	129	-0.1		F4267
6	3	+50	128	36.8				F4267
6	4	+50	128	36.8	192	-0.1		F4267
6	1	Ambient	193	39.4	160	-0.1		F4265
6	2	Ambient	193	37.5	160	-0.5		F4265
6	3	Ambient	225	35.5	224	-0.8		F4265
6	4	Ambient	193	39.6	232	-0.2		F4265

TABLE 3. A/D CONVERSION FAILURES

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4256

ORIGINATOR	1. PROGRAM NAME AND NUMBER <i>Thematic Mapper HS236</i>		2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>0900</i>	5. DATE OBSERVED MO <i>7</i> DA <i>9</i> YR <i>81</i>	
	8. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART						
	EQUIPMENT IDENTIFICATION:						
	7. SUBSYSTEM <i>Multiplexer</i>		PART NUMBER <i>3533003-100</i>		S/N <i>3</i>		MANUFACTURER <i>Hac</i>
ENGINEERING EVALUATION	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
	11. OTHER						
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM						
ENGINEERING AND TEST	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER						
	14. DESCRIPTION OF FAILURE <i>Card 1 Input 7 failed input buffer AC response and DC Restor T.C.</i>						
	15. TEST PROCEDURE <i>32015-005</i>		16. ORIGINATOR <i>Guamchi</i>	17. CONTINUATION SHEET USED <input type="checkbox"/>	18. VERIFICATION AND FAILURE ANALYSIS <i>Suspect tester failure. Verified tester failure. No possibility of component damage. Inputs to flight equipment are protected by 015 K52 resistor. RL Julian</i>		
	19. FAILED ITEM NAME AND PART NUMBER <i>3533003-100</i>						
MANUFACTURING AND TEST	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>No rework action taken on cent. relay in test fixture replaced.</i>						
	21. AUTHORIZATION <i>Guamchi</i>		22. ORG <i>41-41</i>	23. DATE <i>11-30/81</i>	24. CONTINUATION SHEET USED <input type="checkbox"/>		
	25. REWORK/RETEST ACTION TAKEN <i>See retest for pass of quality check and also pg 73 on 11/30/81</i>						
	26. LIST ALL PARTS REPLACED						
ENGINEERING/RELIABILITY	27. REWORK BY <i>Guamchi</i>		28. ORG <i>41-41</i>	29. DATE <i>11/30/81</i>	30. CONTINUATION SHEET USED <input type="checkbox"/>		
	31. CAUSE AND CORRECTIVE ACTION <i>Defective relay in test station Relay replaced and successful retest conducted. No further corrective action required.</i>						
	32. FRB CLOSURE <i>Guamchi 12/2/81</i>						
	33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <input type="checkbox"/>						
ENGINEERING/RELIABILITY	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROOM HANDLING <input type="checkbox"/> WEAR/OUT <input type="checkbox"/> UNKNOWN		35. DEFECT CODE				
	36. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN NO FAILURE		37. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		38. DEFECT CODE		
	39. RESPONSIBLE ENGINEER <i>RL Julian</i>		40. ORG <i>41-41</i>	41. DATE <i>12/1/81</i>	42. SPACECRAFT SYSTEM ENGINEER <i>RL Julian</i>		
43. APPROVED BY <i>Guamchi</i>		44. ORG <i>5171</i>	45. DATE <i>12/2/81</i>	46. APPROVED BY <i>D.B.</i>			

ORIGINAL PAGE IS
OF POOR QUALITY

W124

HUGHES

**SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT**

F 4257

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER <i>Thematic Map H5236</i>	2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1400</i>	5. DATE OBSERVED MO <i>7</i> DA <i>10</i> YR <i>81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:				
7. SUBSYSTEM	NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT <i>Multiplexer</i>		<i>3533003-100</i>	<i>3</i>	<i>HAC</i>
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
11. OTHER				
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS	<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF	<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR	<input type="checkbox"/> THERMAL VAC MIN TYPE	HRS AT
14. DESCRIPTION OF FAILURE				
<i>Numerous x-talk failures are continuing about</i>				
15. TEST PROCEDURE <i>32015-005</i>	PARA <i>35.3.6</i>	16. ORIGINATOR <i>James</i>	ORR <i>4/4</i>	DATE <i>7/10/81</i>
17. CONTINUATION SHEET USED <input checked="" type="checkbox"/>	18. VERIFICATION AND FAILURE ANALYSIS <i>Failures verified. Some channels slightly out of specification. Grounds of failed channels indicate that analog multiplexer hybrids may be partial cause.</i>	19. FAILED ITEM NAME AND PART NUMBER <i>3533003-100</i>		
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE	<i>REPLACE ANALOG MULTIPLEXER HYBRIDS BAND 2 H71 AND BAND 2 H72 REFER TO H5236-2260 (COPY ATTACHED)</i>	21. AUTHORIZATION	ORG	DATE
22. CONTINUATION SHEET USED <input type="checkbox"/>	23. REWORK/RETEST ACTION TAKEN <i>REPLACED TWO 3905973 HYBRIDS AS STATED ABOVE. RETESTED PER TP 3533003-100 PARA 35.3.6</i>			
24. QA REVIEWED <i>12/15/81</i>				
25. QA RETEST				
26. LIST ALL PARTS REPLACED	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
<i>3905973</i>	<i>H71</i>	<i>S/N 532</i>		
<i>3905973</i>	<i>H72</i>	<i>S/N 502</i>		
27. REWORK BY <i>GT/ASB RN</i>	ORG <i>45-21</i>	DATE <i>10-20-81</i>	28. RETESTED BY	ORG
29. CONTINUATION SHEET USED <input type="checkbox"/>	30. CAUSE AND CORRECTIVE ACTION <i>MINOR CROSS-TALK BETWEEN SOME CHANNEL PAIRS IS AN UNAVOIDABLE CONSEQUENCE OF THE ASSEMBLY AND DESIGN USED. IT WILL NOT ADVERSELY AFFECT SYSTEM PERFORMANCE, SO NO DESIGN CHANGES WILL BE UNDERTAKEN. C/A REFER TO W124 TABLE 1</i>	31. FAB CLOSURE		
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>				
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS	<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> NEAR-OUT	<input type="checkbox"/> UNKNOWN DEFECT CODE
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED	<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR	<input type="checkbox"/> SAFETY	
36. RESPONSIBLE ENGINEER <i>RL Julian</i>	ORG <i>41-41</i>	DATE <i>12/9/81</i>	37. SPECIALIST SYSTEM ENGINEER <i>J. Engel</i>	ORG <i>224</i>
38. RELIABILITY <i>None</i>	ORG <i>51-41</i>	DATE <i>12-10-81</i>	39. PART NUMBER OR SUPPLIER <i>NA</i>	DATE <i>12/15/81</i>

James
12/14/81



HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO. F4257
CONTINUATION SHEET LETTER A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON		ADDITIONAL FR CONTINUATION SHEET(S) USED <input checked="" type="checkbox"/>	
IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.			
14	7/10/81	The Following Band and Season Failed X Talk	
		Band	Season
		1	7 Failure caused by bad relay in Test Equip
		2	2 PASSED on retest after rework 12/1/81
		2	5 PASSED on retest after rework 12/1/81
		2	6 PASSED on retest after rework 12/1/81
		2	7 PASSED on retest after rework 12/1/81
		2	8 PASSED on retest after rework 12/1/81
		2	12 Aug 7/10/81
		4	16 PASSED on retest after rework 12/1/81
		6	17 FAILED on RE-TEST 12/1/81
		6	2 } REFER TO W124 TABLE 1
		6	3 }
		6	4 }
		7	13 PASSED on retest after rework 12/1/81
		7	16 PASSED on retest after rework 12/1/81
		Band	Season
14	12/1/81	6	1 } SEE W124 TABLE 1
		6	2 }
		6	3 }
		6	4 }

ORIGINAL PAGE IS
OF POOR QUALITY

4257

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR MIL FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PRECEDENCE ACTIVITY OR

1. ORIGINATOR NAME AND ADDRESS

Hughes Aircraft Co, SCG, El Segundo, California

DEVIATION WAIVER
 CHANGE CHANGE CORRECTIVE

3. DESIGNATION FOR DEVIATION/WAIVER

5. BASE LINE AFFECTED

6. OTHER SYSTEMS/CONFIG-
URATION ITEMS AFFECTED

6. MODEL/TYPE Flight	7. MFR. CODE 82577	8. SYS. DESIG. TM	9. DEVELOPER OR. W124	<input type="checkbox"/> PLUC- TIFIED	<input type="checkbox"/> ALLO- CATED	<input type="checkbox"/> PRODU- CT	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
-------------------------	-----------------------	----------------------	--------------------------	--	---	---------------------------------------	------------------------------	--

7. SPECIFICATIONS AFFECTED-TEST PLAN

8. DRAWINGS AFFECTED

	MFR. CODE	SPEC./DOC. NO.	REV.	MFR. CODE	CHANGE	REV.	DOC. NO.
a. SYSTEM							
b. ITEM							
c. TEST PLAN							

9. TITLE OF DEVIATION/WAIVER

Minor Performance Discrepancies, S/N 003 Multiplexer

18. CONTRACT NO. & LINE ITEM
NAS 5-24200 L.I. 32

11. IDENTIFICATION TYPE NUMBER/ARTICLE

Multiplexer

IDENTIFICATION OF ENVY

14. CR. NO. 15. EFFECT NO. 16. EFFECT CLASSIFICATION
 MINOR MAJOR CRITICAL

12. NAME OF PART OR LATEST ASSEMBLY AFFECTED

Multiplexer

13. PART NO. OR TYPE DESIGN.

17. LOT NO.

18. QTY

19. REQUIRES DEVIATION/WAIVER
 YES NO

20. EFFECT ON COST/PRICE

None

21. EFFECT ON DELIVERY SCHEDULE

18 months schedule slip is disapproved

22. EFFECT ON INTERCHANGABLE LOGISTIC SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/WAIVER

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REAS FOR DEVIATION/WAIVER

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian REL [Signature] QA [Signature]
SYS. ENGR. [Signature] PE [Signature]

25. PRODUCTION EFFECTIVITY OR SERIAL NUMBER

26. EXPIRES DATE/ACTIVITY AUTHORITY/TITLE

[Signature] 31 12 10

27. APPROVAL/DISAPPROVAL

APPROVAL DECEASED APPROVED DISAPPROVED

28. GOVERNMENT ACTIVITY

NASA GSFC

SIGNATURE

[Signature] 12/1/81

DD FORM 1694

© GPO: 1980 - 540-708/010

ORIGINAL PAGE IS
OF POOR QUALITY

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POCR QUALITY

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

4251

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.5	160	-0.5	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

TO: G. Gritt
CC: L. O'Connell
DATE: 22 December 1981
REF: HS 236-2260
PE 225:81
FROM: R. Julian
41-41
BLDG. B-11 MAIL STA. 39
EXT. 6293

SUBJECT: 3905973 Hybrid Crosstalk Testing

Two 3905973 hybrids were removed in an attempt to fix the crosstalk in Bands 2 and 7 of the S/N 3 Multiplexer. (Ref. FR No.'s F4254, F4257, and F4258). These hybrids are not being formally failure analyzed because:

1. Crosstalk is caused by a combination of the hybrids and the unit wiring, and is not observable at the hybrid level.
2. The hybrids are tested by observing output levels with an oscilloscope. Errors of the size involved ($\approx 1/2\%$ of full scale, max.) are not visible on oscilloscopes.
3. The hybrids would pass all their tests and are fully functional.

In the course of hybrid repair, we will make static measurements to see whether these hybrids are abnormal in any detectable way.

Richard C. Julian
Richard C. Julian
REA, Multiplexer
Thematic Mapper Program

RCJ:jc

HUGHES

ORIGINAL PAGE IS OF POOR QUALITY

W124

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

F 426!

HUGHES AIRCRAFT COMPANY SPACE AND COMMUNICATIONS GROUP EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER <i>THREATIC MAPAR MS 236</i>		2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1715</i>	5. DATE OBSERVED MO <i>6</i> DA <i>17</i> YR <i>81</i>	
8. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART						
EQUIPMENT IDENTIFICATION:						
7. SUBSYSTEM		NAME		PART NUMBER	S/M MANUFACTURER	
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>	<i>3 HAC</i>	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
11. OTHER						
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input type="checkbox"/>						
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION AXIS POS MIN TYPE <input type="checkbox"/> OTHER						
14. DESCRIPTION OF FAILURE <i>Band 6 Sensor 1 fails A/D conversion test, Step 160 is -17.9h</i> <i>Band 6 Sensor 2 Step 193 is 40.7ms 5/16ms 3/12 and Step 224 is - low 5/16ms 0.0. Band 6 Sensor 3 Step 193 is 47.8ms 5/16ms 3/12 and Step 224 is - low 5/16ms 0.0. Band 6 Sensor 4 Step 193 is 47.8ms 5/16ms 3/12 and Step 224 is - low 5/16ms 0.0.</i>						
18. TEST PROCEDURE <i>TP-52015-005</i>		18A. PARA <i>3.5.3.5</i>	18B. SIGNATURE <i>R. J. ...</i>	18C. ORG <i>441</i>	18D. DATE <i>6/17/81</i>	
19. VERIFICATION AND FAILURE ANALYSIS						
19. FAILED ITEM NAME AND PART NUMBER						
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>REFER TO WAIVER W124 (COPY ATTACHED)</i>						
21. AUTHORIZATION						
22. CONTINUATION SHEET USED						
23. REWORK/RETEST ACTION TAKEN <i>NOT APPLICABLE - REFER TO WAIVER W124 (COPY ATTACHED)</i>						
24. QA REWORK						
25. QA RETEST						
26. LIST ALL PARTS REPLACED						
PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUM
27. REWORK BY						
ORG		DATE		28. RETESTED BY		
29. CONTINUATION SHEET USED						
30. CAUSE AND CORRECTIVE ACTION <i>REFER TO W124 TABLE 3</i>						
31. FRB CLOSURE						
31. CONTINUATION SHEET USED						
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>						
33. FAILURE TYPE						
<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		
<input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		
<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		<input type="checkbox"/> UNKNOWN DEFECT CODE				
37. RESPONSIBLE ENGINEER <i>See Exam</i>		38. FAILURE CLASSIFICATION <i>MAJOR</i>	39. SPACECRAFT SYSTEM ENGINEER <i>...</i>	40. ORG <i>2245</i>	41. DATE <i>12/14/81</i>	
38. RELIABILITY <i>See Exam</i>		42. ORG <i>5141</i>	43. DATE <i>12-10-81</i>	44. POWER OR SUPPLIER <i>...</i>		

12/2/81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO. F4265
CONTINUATION SHEET LETTER A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.

ADDITIONAL FR CONTINUATION SHEETS USED <input type="checkbox"/>

14	11-11-81	Band 6 Sensor 1 Failed A/D Conversion Test. Step 193 is 324.5/6 31.2 max. 6						
			STEP	IS	S/6(MIN)	STEP	IS	S/6(MIN)
14	12-1-81	Band 6 Sensor 1	193	29.7	36.2MV	160	-0.1MV	0.0MV
		Band 6 Sensor 2	193	37.5MV	31.2MV	160	-0.5MV	0.0MV
		Band 6 Sensor 3	225	35.5MV	31.2MV	224	-0.8MV	0.0MV
		Band 6 Sensor 4	193	39.6MV	31.2MV	232	-0.2MV	0.0MV
14	12-1-81	Band 6 Sensor 1	192	—	—	192	-0.1MV	0.0MV
14	12-2-81	Band 6 Sensor 1	193	38.7	31.2	200	-1.5	0.0

ORIGINAL PAGE IS
OF POOR QUALITY

4265

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 CD A01 FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PROCURING ACTIVITY IS

1. ORIGINATOR NAME AND ADDRESS
Hughes Aircraft Co, SCG, El Segundo, California

2. DEVIATION WAIVER

3. CHANGED CALLED CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

5. MODEL/TYPE Flight	6. CFR CODE 82577	7. SYS. DESIG. TM	8. DRAWING NO. W124
-------------------------	----------------------	----------------------	------------------------

9. BASE LINE AFFECTED
 PURC. ORIGINAL ALLO-CATED PREC. UCT YES NO

10. OTHER SYSTEMS CONFIGURATION ITEMS AFFECTED
 YES NO

7. SPECIFICATIONS AFFECTED-TEST PLAN

ITEM	CFR CODE	SPEC./DOC. NO.	EDN	CFR CODE	REVISION	REV.	CON. NO.
a. SYSTEM							
b. ITEM							
c. TEST PLAN							

8. DRAWINGS AFFECTED

CFR CODE	REVISION	REV.	CON. NO.

9. TITLE OF DEVIATION/WAIVER
Minor Performance Discrepancies, S/N 003 Multiplexer

10. CONTRACT NO. & LINE ITEM
NAS 5-24200 L.I. 32

11. IDENTIFICATION ITEM DESCRIPTION
Multiplexer

12. CD NO.
Multiplexer

13. EFFECT NO.
None

14. DEFECT CLASSIFICATION
 CHANGED CALLED CRITICAL

15. NAME OF PART OR SUBASSEMBLY AFFECTED
Multiplexer

16. PART NO. OR TYPE DESIGN.
None

17. LOT NO.
None

18. QTY.
None

19. RECLASSIFY DEVIATION/WAIVER
 YES NO

20. EFFECT ON COST/PRICE
None

21. EFFECT ON DELIVERY SCHEDULE
18 months schedule slip is disapproved

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INVENTORY, ETC.

23. DESCRIPTION OF DEVIATION/WAIVER

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REASONS FOR DEVIATION/WAIVER

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian SYS. ENGR. REL [Signature] CA [Signature]
 PE [Signature]

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

26. AUTHORITY AUTHORITY AND DATE

[Signature] 81 12 10

27. APPROVAL/DISAPPROVAL

APPROVAL RECOMMENDED APPROVED DISAPPROVED

28. GOVERNMENT ACTIVITY

NASA SPEC [Signature] DATE [Signature]

ORIGINAL PAGE IS
OF POOR QUALITY

4265

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

4235

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	12	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N G03 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

4295

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≥ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.5	160	-0.5	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

HUGHES

ORIGINAL PAGE IS OF POOR QUALITY

W124

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

F 4266

HUGHES AIRCRAFT COMPANY SPACE AND COMMUNICATIONS GROUP EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER <i>THEFTIC MAPPIC</i>		2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1300</i>	5. DATE OBSERVED <i>MO 6 DA 18 YR 81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT <i>Multiflexer</i>				<i>3533003-100</i>	<i>3</i>
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RR <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEST <i>715</i> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Band 1 Sensor 1 and Band 6 sensor 12 exceeded A/D threshold test. 9/30 Band Sensor 11. Note: Band 1 Sensor 1 and Band 7 Sensor 11 occasionally Passes on test. also Band 7 Sensor 13</i>					
15. TEST PROCEDURE <i>35015-005</i>		16. PARA <i>3.5.3.5.2</i>	18. ORIGINATOR <i>K. J. Janszki</i>	19. ORG <i>41-4</i>	20. DATE <i>6/18/81</i>
17. CONTINUATION SHEET USED <input checked="" type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS					
19. FAILED ITEM NAME AND PART NUMBER					
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>REFER TO WAIVER W124 (COPY ATTACHED)</i>					
21. AUTHORIZATION					
22. REWORK/RETEST ACTION TAKEN <i>NOT APPLICABLE - REFER TO WAIVER W124 (COPY ATTACHED)</i>		21. ORG		21. DATE	
23. LIST ALL PARTS REPLACED					
PART NUMBER	CIT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
<i>3905973</i>	<i>H71</i>	<i>57LS32</i>			
<i>3905973</i>	<i>H72</i>	<i>57N502</i>			
27. REWORK BY		28. ORG	29. DATE	30. RETESTED BY	
31. CAUSE AND CORRECTIVE ACTION <i>REFER TO W124 TABLE 3</i>					
32. FRB CLOSURE					
33. CONTINUATION SHEET USED <input type="checkbox"/>					
34. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>					
35. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		36. DEFECT CODE			
37. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
39. RESPONSIBLE ENGINEER <i>R. J. Janszki</i>		40. ORG <i>41-4</i>	41. DATE <i>12/9/81</i>	42. SPACELAB SYSTEM ENGINEER <i>R. J. Janszki</i>	
43. RELIABILITY <i>100%</i>		44. ORG <i>51-41</i>	45. DATE <i>12-10-81</i>	46. CONTINUED OR SUPPLIER <i>NO</i>	

C-2

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT
CONTINUATION SHEET**

PR SERIAL NO.	F4266
CONTINUATION SHEET LETTER	A

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON	ADDITIONAL PR CONTINUATION SHEETS USED <input type="checkbox"/>
<input type="checkbox"/> IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.	

14	4/18/81	Band 1 Sensor 1	37.0 32	ia -0.8	3/6 40.0 *
		** Band 2 Sensor 11	37.0 185	ia -0.7	3/6 40.0 *
		Band 6 Sensor 1	37.0 182	ia -0.7	3/6 28.0 *
		Band 6 Sensor 2	37.0 183	ia -0.7	3/6 28.0 *
		Band 6 Sensor 3	37.0 184	ia -0.7	3/6 28.0 *
		Band 6 Sensor 4	37.0 185	ia -0.7	3/6 28.0 *
		Band 7 Sensor 13	37.0 201	ia -0.4	3/6 40.0 *

* FAILURE ON REPEAT - SEE WIZY TABLE 3
 ** BANDS TRIPPED IN DPA RELAY IN TEST EQUIPMENT.
 ** PASSED AFTER REMOVAL & REPLACEMENT OF
 HYBRID D/I 7905973 IN 522 & 502. REFER
 TO BLOCK 22 OF THIS FR.

ORIGINAL PAGE IS
OF POOR QUALITY

4260

REQUEST FOR DEVIATION/EXEMPTION
(SEE ALL-STD-420 OR MIL FOR INSTRUCTIONS)

DATE REQUESTED

12/3/81

PRODUCTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS

Hughes Aircraft Co, SCG, El Segundo, California

2. DEVIATION STATUS
 SPECIFIED CORRECTED
 EXEMPT REJECTED CANCELLED

3. DESIGNATION FOR DEVIATION/EXEMPTION

4. MODEL/TYPE	5. S/N. CODE	6. S/N. CODE	7. DRAWING NO.	8. CASE LINE AFFECTED	9. OTHER PRODUCTIVITY/CASE LINE AFFECTED
Flight	82577	TM	W124	<input type="checkbox"/> SPEC. TOLERANCE <input type="checkbox"/> DIM. TOL. <input type="checkbox"/> MFG. DEF. <input type="checkbox"/> TEST	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

7. SPECIFICATIONS AFFECTED-TEST PLAN

8. S/N. CODE	9. S/N. CODE	10. S/N. CODE	11. S/N. CODE	12. S/N. CODE	13. S/N. CODE

14. TITLE OF DEVIATION/EXEMPTION
 Minor Performance Discrepancies, S/N 003 Multiplexer

15. PRODUCTIVITY NO. AFFECTED
 NAS 5-24200 L.I. 32

16. EFFECTIVE DATE

17. EXPIRY DATE

18. EXPIRY CLASSIFICATION
 PERMANENT TEMPORARY CANCELLED

19. EFFECTIVE DATE OF DEVIATION/EXEMPTION
 Multiplexer

20. EXPIRY DATE OF DEVIATION/EXEMPTION
 Multiplexer

21. EFFECT OF DEVIATION/EXEMPTION
 None

22. EFFECT OF DEVIATION/EXEMPTION
 18 months schedule slip is disapproved

23. DESCRIPTION OF DEVIATION/EXEMPTION

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. BASIS FOR DEVIATION/EXEMPTION

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REQ. BY R L Julian REL. BY [Signature] QA BY [Signature]
 SYS. ENGR. [Signature] DE [Signature]

25. APPROVAL/DISAPPROVAL

26. APPROVAL/DISAPPROVAL

27. APPROVAL/DISAPPROVAL

28. APPROVAL/DISAPPROVAL

29. APPROVAL/DISAPPROVAL

30. APPROVAL/DISAPPROVAL

31. APPROVAL/DISAPPROVAL

32. APPROVAL/DISAPPROVAL

33. APPROVAL/DISAPPROVAL

34. APPROVAL/DISAPPROVAL

35. APPROVAL/DISAPPROVAL

36. APPROVAL/DISAPPROVAL

37. APPROVAL/DISAPPROVAL

38. APPROVAL/DISAPPROVAL

39. APPROVAL/DISAPPROVAL

40. APPROVAL/DISAPPROVAL

41. APPROVAL/DISAPPROVAL

42. APPROVAL/DISAPPROVAL

43. APPROVAL/DISAPPROVAL

44. APPROVAL/DISAPPROVAL

45. APPROVAL/DISAPPROVAL

46. APPROVAL/DISAPPROVAL

47. APPROVAL/DISAPPROVAL

48. APPROVAL/DISAPPROVAL

49. APPROVAL/DISAPPROVAL

50. APPROVAL/DISAPPROVAL

ORIGINAL PAGE IS
OF POOR QUALITY

4266

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

4266

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

4266

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

4266

BAND	SENSOR	TEMP °C	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
			STEP #	≤ 31.2 MV	STEP #	≥ 0.0 MV	
1	1	+15			32	-0.8	F4266
7	13	+15			241	-0.4	F4266
6	1	+15	193	41.7	192	-0.1	F4266
6	2	+15	193	37.3			F4266
6	3	+15	193	39.1	192	-0.4	F4266
6	4	+15	193	39.3	192	-0.3	F4266
6	1	+50	128	39.8	129	-0.1	F4267
6	2	+50	128	37.0	129	-0.1	F4267
6	3	+50	128	36.8			F4267
6	4	+50	128	36.8	192	-0.1	F4267
6	1	Ambient	193	39.4	160	-0.1	F4265
6	2	Ambient	193	37.5	160	-0.5	F4265
6	3	Ambient	225	39.5	224	-0.8	F4265
6	4	Ambient	193	39.6	232	-0.2	F4265

TABLE 3. A/D CONVERSION FAILURES



ORIGINAL PAGE IS OF POOR QUALITY

W124

SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

F 4267

HUGHES AIRCRAFT COMPANY SPACE AND COMMUNICATIONS GROUP EL SEGUNDO, CALIFORNIA

1 PROGRAM NAME AND NUMBER <i>INSPIRE MUXER HS-236</i>		2 QLA <i>E330</i>	3 MODEL <i>HLT</i>	4 TIME OBSERVED <i>1015</i>	5 DATE OBSERVED <i>MO 6 DA 19 YR 81</i>						
6 HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECAM <input type="checkbox"/> PART											
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/W MANUFACTURER											
7 SUBSYSTEM											
8 UNIT <i>MULTIPLIER</i> <i>3533003-100</i> <i>3</i> <i>HAC</i>											
9 <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
10 <input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD											
11 OTHER											
12 TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM											
13 ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <i>150 C</i> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MRO AT <input type="checkbox"/> ENC/RF <input type="checkbox"/> VIBRATION AXIS FOR <input type="checkbox"/> VIB TYPE											
14 DESCRIPTION OF FAILURE <i>Break 6 sensor 1 fail A/D Threshold test. 31025 1230 500 316 2.62</i>											
15 TEST PROCEDURE <i>2015-005</i>		16 PARA <i>3.3.3.5.2</i>	17 OPERATOR <i>R. Johnson</i>	18 DATE <i>4-4-81</i>	19 CONTINUATION SHEET USED						
18 VERIFICATION AND FAILURE ANALYSIS											
19 FAILED ITEM NAME AND PART NUMBER											
20 <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>REFER TO WALKER W124 (COPY ATTACHED)</i>											
21 AUTHORIZATION		ORG	DATE	22 CONTINUATION SHEET USED							
23 REWORK/RETEST ACTION TAKEN <i>NOT APPLICABLE - REFER TO WALKER W124 (COPY ATTACHED)</i>				24 CA REWORK							
				25 CA RETEST							
26 USE ALL PARTS REPLACED											
PART NUMBER	CRT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER					
27 REWORK BY		ORG	DATE	28 RETESTED BY		ORG	DATE	29 CONTINUATION SHEET USED			
30 CAUSE AND CORRECTIVE ACTION <i>REFER TO W124</i>						31 PRO CLOSURE					
						32 CONTINUATION SHEET USED					
33 DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>						34 BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR ROUGH-HANDLING WEAR-OUT <input type="checkbox"/> UNKNOWN				DEFECT CODE	
35 FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36 FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY							
37 RESPONSIBLE ENGINEER <i>R. Johnson</i>		ORG <i>41-41</i>	DATE <i>12/9/81</i>	38 SPECIALTY SYSTEM ENGINEER <i>Walker</i>		ORG <i>2241</i>	DATE <i>12/15/81</i>				
39 RELIABILITY <i>AC</i>		ORG <i>41-41</i>	DATE <i>12-10-81</i>	40 NUMBER OR SUPPLIER <i>88</i>							



SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO.	F 4267
CONTINUATION SHEET LETTER*	A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON		ADDITIONAL FR CONTINUATION SHEET(S) USED <input type="checkbox"/>
<input type="checkbox"/> IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.		
14	Band B Sensor 2 *	
7/2/81	STEP 128 is 37.0MV 3/6 MAX 31.2MV	
	STEP 129 is -0.1MV 3/6 MIN 0.0MV	
	Band B Sensor 3 *	
	STEP 128 is 36.8MV 3/6 MAX 31.2MV	
	STEP 129 Req 7/2/81	
	Band G Sensor 4 *	
	STEP 128 is 36.8MV 3/6 MAX 31.2MV	
	STEP 192 is -0.1MV 3/6 MIN 0.0MV	
* FAILED AT PRETEST - SEE W124 TABLE 3		

ORIGINAL PAGE IS
OF FOUR QUALITY

4267

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR MIL FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PROCESSING ACTIVITY IS

1. ORIGINATOR NAME AND ADDRESS

Hughes Aircraft Co, SCG, El Segundo, California

2. DEVIATION WAIVER
3. CHANGE DELETE CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER

5. SERIAL/TYPE: Flight
6. DTD. CODE: 82577
7. DTD. PREFIX: TM
8. DRAWING NO.: W124

9. BASIC LINE AFFECTED

PARALLEL ALLOCATED SPEC. GET YES NO

10. OTHER SYSTEMS/CONFIGURATIONS ITEMS AFFECTED

7. SPECIFICATIONS AFFECTED-TEST PLAN

8. SYSTEM	9. CODE	10. SPEC. CODE	11. QTY

8. DRAWINGS AFFECTED

9. CODE	10. QTY	11. QTY	12. QTY

9. TITLE OF DEVIATION/WAIVER

Minor Performance Discrepancies, S/N 003 Multiplexer

10. DRAWING NO. & LINE ITEM

NAS 5-24200 L.I. 32

11. CONFIGURATION ITEM IDENTIFICATION

Multiplexer

12. CLASSIFICATION OF DEFECT

13. DEFECT NO. 14. DEFECT CLASSIFICATION
 CHANGE DELETE CRITICAL

15. CODE OF PART OR LEGIT. AFFECTED

Multiplexer

16. PART NO. AS TYPE CODED

17. LOT NO.

18. QTY

19. REQUIRING DEVIATION/WAIVER
 YES NO

20. EFFECT ON COST/PRICE

None

21. EFFECT ON DELIVERY SCHEDULE

18 months schedule slip is disapproved

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/WAIVER

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REASON FOR DEVIATION/WAIVER

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian SYS. ENGR.

REL [Signature]

QA [Signature]
PE [Signature]

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

26. AUTHORITY ACTIVITY APPROVING STRUCTURE
[Signature] 81 12 10

27. APPROVAL/DISAPPROVAL

APPROVAL DECLASSIFIED APPROVED DISAPPROVED

28. GOVERNMENT ACTIVITY

NASA GFC

SIGNATURE [Signature] DATE 12-1-81

DD FORM 1694

© GPO 1980 - 240-154/018

ORIGINAL PAGE IS
OF POOR QUALITY

4267

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

4267

ORIGINAL PAGE IS
OF POOR QUALITY

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

4267

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rates up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

4267

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.3		F4266
7	13	+15			241	-0.4		F4266
6	1	+15	193	41.7	192	-0.1		F4266
6	2	+15	193	37.3				F4266
6	3	+15	193	39.1	192	-0.4		F4266
6	4	+15	193	39.3	192	-0.3		F4266
6	1	+50	128	39.8	129	-0.1		F4267
6	2	+50	128	37.0	129	-0.1		F4267
6	3	+50	128	36.8				F4257
6	4	+50	128	36.8	192	-0.1		F4267
6	1	Ambient	193	39.4	160	-0.1		F4265
6	2	Ambient	193	37.5	160	-0.5		F4265
6	3	Ambient	225	35.5	224	-0.8		F4265
6	4	Ambient	193	39.6	232	-0.2		F4265

TABLE 2. A/D CONVERSION FAILURES

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

W124

F 4268

1. PROGRAM NAME AND NUMBER <i>TP 3533003-100</i> <i>Hs 236</i>		2. GLA <i>E330</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1730</i>	5. DATE OBSERVED <i>MO 6 DA 26 YR 81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> S/SUBSYSTEM <input type="checkbox"/> ASS'YBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT <i>MULTIPLExER</i> <i>3533003-100</i> <i>3</i> <i>HAC</i>					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMPERATURE <i>15 C</i> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Numerous crosstalk failures. See attached sheet</i>					
15. TEST PROCEDURE <i>32015-005</i>		16. PARA <i>3.5.3.6</i>	17. ORIGINATOR <i>Comanchi</i>	18. ORG <i>41-41</i>	19. DATE <i>6/26/81</i>
18. VERIFICATION AND FAILURE ANALYSIS <i>Failures verified. Some channels slightly out of specification. Groupings of failed channels indicate that analog multiplexer hybrids may be partial cause.</i>		19. FAILED ITEM FRAME AND PART NUMBER <i>3533003-100</i>			
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>Replace analog multiplexer hybrids Band 2 HY1 and Band 7 HY2. REFER TO Hs 236-2260 (COPY ATTACHED)</i>					
21. AUTHORIZATION <i>R Sullivan</i>		22. ORG <i>41-41</i>	23. DATE <i>6/28/81</i>	24. CONTINUATION SHEET USED <input type="checkbox"/>	
25. REWORK/RETEST ACTION TAKEN <i>Replaced two 3905973 hybrids as above. Retested per TP 3533003-100 Paragraph 3.5.3.6.</i>		26. QA REVIEW <input checked="" type="checkbox"/> <i>W124</i>			
27. QA RETEST					
28. LIST ALL PARTS REPLACED					
PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MA. FACTURER	PROBABLE DEFECT
<i>3905973</i>	<i>HY1</i>	<i>S/N 532</i>			
<i>3905973</i>	<i>HY2</i>	<i>S/N 502</i>			
29. REWORK BY <i>W124</i>		30. URG <i>45-21</i>	31. DATE <i>10-20-81</i>	32. RETESTED BY <i>Comanchi</i>	33. ORG <i>41-41</i>
34. CAUSE AND CORRECTIVE ACTION <i>Minor crosstalk between some channel pairs is an unavoidable consequence of the assembly and design used. It will not adversely affect system performance so no design change will be undertaken. CIA REFER TO W124</i>		35. DATE <i>11-24-81</i>			
36. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 COPY ATTACHED</i>		37. CONTINUATION SHEET USED <input type="checkbox"/>			
38. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		39. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		40. MFG. PROCEDURE <input type="checkbox"/> ASS'Y/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
41. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		42. UNKNOWN <input type="checkbox"/> NO FAILURE		43. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
44. RESPONSIBLE ENGINEER <i>R Sullivan</i>		45. ORG <i>41-41</i>	46. DATE <i>12/1/81</i>	47. CONTINUATION SHEET USED <input type="checkbox"/>	
48. RESPONSIBLE ENGINEER <i>R Sullivan</i>		49. ORG <i>5-41</i>	50. DATE <i>12-10-81</i>	51. CONTINUATION SHEET USED <input type="checkbox"/>	

12/2/81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO. F4268
CONTINUATION SHEET LETTER A

LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.

ADDITIONAL FR CONTINUATION SHEETS USED	<input checked="" type="checkbox"/>
--	-------------------------------------

14	6/26/81							
		Bank #	Sensor #					
	1	7 *		BIST failure caused by bad relay in test equipment				
	2	2		Passed on next test after rework 11/14/81				
	2	5		Failed				
	2	6 **						Passed 11/24/81
	2	8 **						11/24/81
	3	6		Failed on RETEST - SEE W124 TABLE 1				
	3	8 **		Passed by retest after rework 12-2-81				
	3	10		Failed on RETEST - SEE W124 TABLE 1				
	6	1		"	"	"	"	"
	6	2		"	"	"	"	"
	6	3		"	"	"	"	"
	6	4		"	"	"	"	"
	7	13 **		Passed on retest after rework 11/26/81				
	7	16 **						

* PROBLEM TRACED TO BAD RELAY IN TEST EQUIPMENT.
PASSED WHEN TESTED WITH REPAIRED TEST EQUIPMENT.
** FAILED ON RETEST - THEREFORE NOT A W124.

ORIGINAL PAGE IS
OF POOR QUALITY

4268

REQUEST FOR DEVIATION/VAIANCE
(SEE MIL-STD-883B OR MIL-STD-883C FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PREPARED BY

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Co, SCG, El Segundo, California				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> CHANGE	
3. DESIGNATION FOR DEVIATION/VAIANCE				4. BASIC ITEM AFFECTED	
5. ORIGINATOR CODE	6. SPO. CASE	7. SPO. CASE	8. SPO. CASE	<input type="checkbox"/> PRE-TEST	<input type="checkbox"/> POST-TEST
Flight	82577	TM	W124	<input type="checkbox"/>	<input checked="" type="checkbox"/>
9. SPECIFICATIONS AFFECTED-TEST PLAN			10. SPECIFICATIONS AFFECTED		
11. SYSTEM	12. ITEM	13. TEST PLAN	14. TITLE OF DEVIATION/VAIANCE	15. DRAWING NO. & DATE	
			Minor Performance Discrepancies, S/N 003 Multiplexer	NAS 5-24200 L.I. 32	
16. DESCRIPTION OF DEVIATION/VAIANCE			17. EFFECT ON		
Multiplexer			18. RESULT CLASSIFICATION		
19. NAME OF PART OR COMPONENT AFFECTED			20. NAME OF TYPE CLASS.		
Multiplexer			21. LOT NO.		
22. TYPE OF DEVIATION/VAIANCE			23. EFFECT ON DELIVERY SCHEDULE		
None			18 months schedule slip is disapproved		

23. DESCRIPTION OF DEVIATION/VAIANCE

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REPAIR FOR DEVIATION/VAIANCE

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian SYS. ENGR. REL [Signature] QA [Signature] PE [Signature]

16. APPROVAL/DISAPPROVAL

APPROVAL DISAPPROVED APPROVED DISAPPROVED

17. APPROVAL/DISAPPROVAL

18. SIGNATURE

NASA GFEC [Signature] 12/1/81

ORIGINAL PAGE IS
OF POOR QUALITY

4268

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table J. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

4268

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

4268

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

4268

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.5	160	-0.3	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company

INTERNAL MEMORANDUM

TO: G. Gritt
SUBJECT: 3905973 Hybrid Crosstalk Testing

CC: L. O'Connell

DATE: 22 December 1981

REF: HS 236-2260

PE 225:81

FROM: R. Julian
41-41

BLDG. B-11 MAIL STA. 39
EXT. 6293

Two 3905973 hybrids were removed in an attempt to fix the crosstalk in Bands 2 and 7 of the S/N 3 Multiplexer. (Ref. FR No.'s F4254, F4257, and F4258). These hybrids are not being formally failure analyzed because:

1. Crosstalk is caused by a combination of the hybrids and the unit wiring, and is not observable at the hybrid level.
2. The hybrids are tested by observing output levels with an oscilloscope. Errors of the size involved ($\pm 1/2\%$ of full scale, max.) are not visible on oscilloscopes.
3. The hybrids would pass all their tests and are fully functional.

In the course of hybrid repair, we will make static measurements to see whether these hybrids are abnormal in any detectable way.

R. L. Julian

Richard C. Julian
REA, Multiplexer
Thematic Mapper Program

RCJ:jc

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

W124
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

No F 07295

HUGHES

SEE REVERSE SIDE OF HARD COPY FOR INSTRUCTIONS

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
2525 AVENUE, CALIFORNIA

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper 15236</i>		2. GLA <i>F264</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>1415</i>	5. DATE OBSERVED YR <i>81</i> MO <i>11</i> DA <i>25</i>
6. HOW UNDER TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>	<i>3</i>
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					<i>HAC</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS	<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> SPECIAL TEST
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI	<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP <i>50.5</i> CYCLE	<input type="checkbox"/> THERMAL VAC. HSE AT _____
14. DESCRIBE FAILURE, INCLUDE "IS" AND "SHOULD BE" DATA <i>Band 2 sensor head 13 failed Xtalk.</i>					
16. TEST PROCEDURE <i>3-015-005</i>		18. PARA <i>3.5.31</i>	19. OPERATOR <i>K-YAMAUCHI</i>	20. ORG <i>49-41</i>	17. DATE <i>11-25-81</i>
15. CONTINUATION SHEET USED <input type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS					
19. FAILED ITEM NAME					
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED		21. AUTHORIZATION			
<input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<i>REFER TO W124 (COPY ATTACHED)</i>			
22. REWORK/RETEST ACTION TAKEN		23. ORG		24. DATE	
<i>NOT APPLICABLE - REFER TO WORKER W124 (COPY ATTACHED)</i>					
25. LIST ALL PARTS REMOVED		26. ORG		27. DATE	
PART NUMBER		DATE		DATE	
CXT SYM		MFG DATE CODE		MFG	
HAC H-REL		MANUFACTURER		HOW LEVEL	
PART LOT NUMBER		REMOVAL CAUSE		PART NO.	
MFG		FAIL CLASS		ANALYSIS NUMBER	
DATE CODE		28. RETESTED BY		29. CONTINUATION SHEET USED	
MANUFACTURER		ORG		<input type="checkbox"/>	
REMOVAL CAUSE		DATE			
FAIL CLASS					
ANALYSIS NUMBER					
28. Rework by		29. Retested by		30. Continuation sheet used	
ORG		ORG		<input type="checkbox"/>	
DATE		DATE			
31. CAUSE		32. FAILURE CLASSIFICATION		33. FAILURE CLASSIFICATION	
<i>REFER TO W124 TABLE 1</i>		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
32. CORRECTIVE ACTION		34. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		35. CONTINUATION SHEET USED	
<i>REFER TO W124 TABLE 1</i>		<i>REFER TO W124 (COPY ATTACHED)</i>		<input type="checkbox"/>	
33. BASIC CAUSE OF VERIFIED FAILURE		36. TEST EQUIPMENT		37. WIRING ERROR	
<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
37. FAILURE TYPE		38. FAILURE CLASSIFICATION		39. UNKNOWN OPERATOR ERROR SPECIFICATION PROBLEM	
<input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> UNKNOWN OPERATOR ERROR <input type="checkbox"/> SPECIFICATION PROBLEM	
40. RESPONSIBLE ENGINEER		41. SPACECRAFT SYSTEM ENGINEER		42. CONTINUATION SHEET USED	
<i>William</i>		<i>J. Ennis</i>		<input type="checkbox"/>	
43. RELIABILITY		44. USER OR SUPPLIER		45. DATE	
ORG		ORG		DATE	
DATE		DATE		DATE	
A		K		22 41 12/15/81	

ORIGINAL PAGE IS
OF POOR QUALITY

F07295

REQUEST FOR DEVIATION/BAIWER
(SEE OIL-STD-459 OR MIL FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

PROCEDURES REFER TO

1. ORIGINATOR NAME AND ADDRESS

Hughes Aircraft Co, SCG, El Segundo, California

2. DEVIATION BAIWER
 CRITICAL MAJOR MINOR

3. DESIGNATION FOR DEVIATION/BAIWER

4. SERIAL/TIME 5. SPO. CODE 6. SPO. DESIG. 7. ESTABLISH. NO.
Flight 82577 TM W124

8. CASE LINE AFFECTED
 PLANE-TYPICAL CALLO-CATED PART-LET
9. OTHER SYSTEMS/CERTIFICATION ITEMS AFFECTED
 YES NO

7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DOCUMENTS AFFECTED			
SPO. CODE	SPEC./DOC. NO.	REV.	SPO. CODE	REV.	REV.	REV.	REV.

9. TITLE OF DEVIATION/BAIWER
Minor Performance Discrepancies, S/N 003 Multiplexer

10. CASELINE NO. & LINE NO.
NAS 5-24200 L.I. 32

11. CATEGORY TYPE OF DEFECT
Multiplexer

12. DEF. NO. 13. EFFECT NO. 14. DEFECT CLASSIFICATION
 CRITICAL MAJOR MINOR

15. NAME OF PART OR SUBASSEMBLY AFFECTED
Multiplexer

16. PART NO. OR P/N NO. 17. LOT NO. 18. QTY. 19. DISCREPANCY DEVIATION/BAIWER
 YES NO

20. EFFECT ON ENVIRONMENT
None

21. EFFECT ON DELIVERY SCHEDULE
18 months schedule slip is disapproved

22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

23. DESCRIPTION OF DEVIATION/BAIWER

The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REAS FOR DEVIATION/BAIWER

Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian REL [Signature] QA [Signature]
SYS. ENGR. [Signature] OF [Signature]

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER

26. EFFECTIVITY BY SERIAL NUMBER AND DATE
[Signature] 81 12 10

27. APPROVAL/DISAPPROVAL
 APPROVAL RECOMMENDED APPROVED DISAPPROVED

28. GOVERNMENT ACTIVITY
NASA/GFEC

29. SIGNATURE
[Signature] DATE 12/3/81

ORIGINAL PAGE IS
OF POOR QUALITY

F-07295

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

F07295

ORIGINAL PAGE IS
OF POOR QUALITY

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

F07295

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.5	160	-0.5	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

W124

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

No F07296

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SEE REVERSE SIDE OF HARD COPY FOR INSTRUCTIONS

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper HS 236</i>		2. CLA <i>F764</i>		3. MODEL <i>FLT</i>		4. TIME OBSERVED <i>1400</i>		5. DATE OBSERVED <i>YR 81 MO 12 DA 1</i>		
6. HOW UNDER TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:										
7. SUBSYSTEM		NAME			PART NUMBER		S/N		MANUFACTURER	
8. UNIT		<i>MULTIPLEXER</i>			<i>3533003-100</i>		<i>3</i>		<i>HAC</i>	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD										
11. OTHER										
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> SPECIAL TEST		
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMP		<input type="checkbox"/> CYCLE <input type="checkbox"/> THERMAL VAC		
14. REPAIRS FAILURE INCLUDE "IS" AND "SHOULD BE" DATA		<i>The following bands and sensors failed & still. Band 1 sensors 10 and 14. Band 2 sensor dead w/ failed sensor 10.</i>								
15. TEST PROCEDURE		16. PARA <i>3-S-36</i>		18. ORIGINATOR <i>R. J. Manucha</i>		19. DATE <i>12-1-81</i>		17. CONTINUATION SHEET USED <input type="checkbox"/>		
20. VERIFICATION AND FAILURE ANALYSIS										
20. FAILED ITEM NAME										
20. FAILED ITEM PART NO.										
20. S/N										
20. MFR										
20. HOW LEVEL										
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED										
20. <input checked="" type="checkbox"/> RERWORK/RETEST NOT REQUIRED BECAUSE <i>REFER TO W124 (COPY ATTACHED)</i>										
21. AUTHORIZATION										
21. ORG										
21. DATE										
21. CONTINUATION SHEET USED <input type="checkbox"/>										
21. CA REWORK										
21. CA RETEST										
21. CA RETEST (OPTIONAL)										
22. LIST ALL PARTS REMOVED										
PART NUMBER										
CXT SYM										
HAC NR-REL PART LOT NUMBER										
MPG DATE CODE										
MANUFACTURER										
REMOVAL CAUSE										
FAIL CLASS										
ANALYSIS NUMBER										
22. REWORK BY										
ORG										
DATE										
22. RETESTED BY										
ORG										
DATE										
22. CONTINUATION SHEET USED <input type="checkbox"/>										
23. CAUSE <i>REFER TO W124 TABLE 1</i>										
23. CORRECTIVE ACTION <i>REFER TO W124 TABLE 1</i>										
23. FAB CLOSURE										
23. CONTINUATION SHEET USED <input type="checkbox"/>										
23. PEP. FB NUMBER										
24. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>										
25. BASIC CAUSE OF VERIFIED FAILURE										
<input checked="" type="checkbox"/> DESIGN										
<input checked="" type="checkbox"/> ENVIRONMENTAL										
<input checked="" type="checkbox"/> DEFECTIVE PARTS										
<input type="checkbox"/> TEST EQUIPMENT										
<input type="checkbox"/> TEST PROCEDURE										
<input type="checkbox"/> TEST SET-UP										
<input type="checkbox"/> MFG. PROCEDURE										
<input type="checkbox"/> ASSY/FAB ERROR										
<input type="checkbox"/> WORKMANSHIP										
<input type="checkbox"/> WRING ERROR										
<input type="checkbox"/> ROUGH HANDLING										
<input type="checkbox"/> WEAR-OUT										
<input type="checkbox"/> UNKNOWN OPERATOR ERROR										
<input type="checkbox"/> SPECIFICATION PROBLEM										
27. FAILURE TYPE										
<input type="checkbox"/> PRIMARY										
<input type="checkbox"/> INDUCED										
<input type="checkbox"/> UNKNOWN										
<input type="checkbox"/> NO FAILURE										
28. FAILURE CLASSIFICATION										
<input type="checkbox"/> CRITICAL										
<input type="checkbox"/> MAJOR										
<input type="checkbox"/> MINOR										
<input type="checkbox"/> SAFETY										
29. RESPONSIBLE ENGINEER <i>J. J. Julian</i>										
ORG <i>41-41</i>										
DATE <i>12/9/81</i>										
30. SPACECRAFT SYSTEM ENGINEER <i>J. J. Julian</i>										
ORG <i>22-41</i>										
DATE <i>12/14/81</i>										
31. RELIABILITY										
ORG <i>11</i>										
DATE <i>12/14/81</i>										
32. TEST CENTER OR SUPPLIER										
DATE										

ORIGINAL PAGE IS
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR ASI FOR INSTRUCTIONS)

DATE PREPARED

12/3/81

01296

PROCESSING ACTIVITY OR

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Co, SCG, El Segundo, California				<input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVED	
2. DESIGNATION FOR DEVIATION/WAIVER				3. BASIC LINE AFFECTED	
a. MODEL/TYPE Flight	b. S/N CODE 82577	c. SYS. DESIG. TM	d. DRAWING NO. W124	<input type="checkbox"/> PLAC. TYPICAL <input type="checkbox"/> CALI. CATED <input type="checkbox"/> PART KIT <input type="checkbox"/> VIS <input checked="" type="checkbox"/> IMP	4. OTHER SYSTEMS/COMPONENTS AFFECTED
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
a. SYSTEM	b. ITEM	c. TEST PLAN	d. TITLE OF DEVIATION/WAIVER Minor Performance Discrepancies, S/N 003 Multiplexer	10. DRAWING NO. & LINE ITEM NAS 5-24200 L.I. 32	
11. CONFIGURATION TYPES AFFECTED				12. CLASSIFICATION OF IMPACT	
Multiplexer				<input type="checkbox"/> CRASH <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> CRITICAL	
13. EFFECT ON COST/PRICE None		14. EFFECT ON SCHEDULE 18 months schedule slip is disapproved		15. EFFECT ON RELIABILITY/LOGIC 18 months schedule slip is disapproved	

13. DESCRIPTION OF DEVIATION/WAIVER
The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

14. REASON FOR DEVIATION/WAIVER
Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian REL [Signature] QA [Signature]
 SYS. ENGR. [Signature] PE [Signature]

15. PRODUCTION EFFECTIVITY OF SERIAL NUMBERS

16. EFFECTIVITY AUTHORITY AND SIGNATURE
[Signature] 81 12 10

17. APPROVAL/DISAPPROVAL

18. APPROVAL/DISAPPROVAL

APPROVAL RECOMMENDED
 APPROVED
 DISAPPROVED

19. DEVELOPMENT ACTIVITY
NASA GSFC

SIGNATURE
[Signature] DATE
12/1/81

DD FORM 1694

GPO: 1979 - 945-788/010

ORIGINAL PAGE IS
OF POOR QUALITY

07296

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

07296

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

07296

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

07296

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.9	160	-0.5	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

W12B
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

No F 07299

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SEE REVERSE SIDE OF HARD COPY FOR INSTRUCTIONS

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper H3236</i>		2. GLA <i>F 264</i>		3. MODEL <i>FLT</i>		4. TIME OBSERVED <i>1530</i>		5. DATE OBSERVED <i>YR 81 MO 11 DAY 4</i>	
6. HOW UNDER TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT <i>Multiplexer</i>				<i>3533003-100</i>		<i>3</i>		<i>Hac</i>	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> SPECIAL TEST									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <i>+15 C</i> CYCLE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MIB AT <input type="checkbox"/> OTHER									
14. DESCRIBE FAILURE, INCLUDE "IS" AND "SHOULD BE" DATA <i>Banker sensors 4, 5 and 7 Fail x Calc.</i>									
15. TEST PROCEDURE <i>32019-005</i>		PARA <i>3.5.36</i>		16. ORIGINATOR <i>K. YAMAMOTO</i>		DATE <i>11/28/81</i>		17. CONTINUATION SHEET USED <input type="checkbox"/>	
18. VERIFICATION AND FAILURE ANALYSIS									
19. FAILED ITEM NAME									
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest not required because		<i>REFER TO W124 (COPY ATTACHED)</i>							
21. AUTHORIZATION									
22. CONTINUATION SHEET USED <input type="checkbox"/>									
23. REWORK/RETEST ACTION TAKEN <i>NOT APPLICABLE - REFER TO W124 (COPY ATTACHED)</i>									
24. QA Rework									
25. QA RETEST									
26. QA RETEST (OPTIONAL)									
27. LIST ALL PARTS REMOVED									
28. Rework by									
29. RETESTED BY									
30. CONTINUATION SHEET USED <input type="checkbox"/>									
31. CAUSE <i>REFER TO W124</i>									
32. CORRECTIVE ACTION <i>REFER TO W124</i>									
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>W124 (COPY ATTACHED)</i>									
34. BASIC CAUSE OF VERIFIED FAILURE									
35. FAILURE TYPE									
36. FAILURE CLASSIFICATION									
37. RESPONSIBLE ENGINEER <i>W. J. Wilson</i>									
38. DATE <i>12/9/81</i>									
39. CUSTOMER OR SUPPLIER <i>J. L. Conrad</i>									
40. DATE <i>12-9-81</i>									
41. DATE <i>12/15/81</i>									

ORIGINAL PAGE IS
OF POOR QUALITY

07299

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-461 AND 461 FOR INSTRUCTIONS)

DATE PROPOSED

12/3/81

PROCESS AND ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Co, SCC, El Segundo, California				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
3. DESIGNATION FOR DEVIATION/WAIVER				4. CASE LINE EFFECTED	
a. MODEL/TYPE Flight	b. SPO. CODE 82577	c. SPO. DESIGN. TM	d. CASE LINE NO. W124	5. OTHER SYSTEMS/COMPONENTS AFFECTED	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
9. SYSTEMS				10. EFFECT CLASSIFICATION	
11. DESCRIPTIONS OF DISCREPANCIES				12. EFFECT CLASSIFICATION	
13. TITLE OF DEVIATION/WAIVER Minor Performance Discrepancies, S/N 003 Multiplexer				14. PART NO. & LINE NO. NAS 5-24200 L.I. 32	
15. TITLE OF DEVIATION/WAIVER Multiplexer				16. EFFECT CLASSIFICATION	
17. TITLE OF DEVIATION/WAIVER Multiplexer				18. EFFECT CLASSIFICATION	
19. TITLE OF DEVIATION/WAIVER None				20. EFFECT CLASSIFICATION 18 months schedule slip is disapproved	

23. DESCRIPTION OF DEVIATION/WAIVER
The S/N 003 Multiplexer (P/N 3533003-100) exhibits minor performance discrepancies in its processing of some of its 100 signal channels. These discrepancies result from random wire dressing and other phenomena which are not correctable, and they do not have any impact upon Thematic Mapper performance. These discrepancies include:

- o Sixteen channels exhibit levels of crosstalk to other channels slightly exceeding specification. They are listed in Table 1.
- o Two channels exhibit levels of DC Restore droop slightly higher than specified at room temperature. They are listed in Table 2.

(Continued)

24. REASON FOR DEVIATION/WAIVER
Repair of the Multiplexer to correct these discrepancies is not practical within a reasonable time for several reasons. The crosstalk failures are random and repair would be as likely to create new crosstalk as to correct that already present. The A/D conversion and DC Restore droop rate discrepancies might be correctable by replacing hybrid microcircuits, but the replacement parts are not available, and the discrepancies are so minor that they might not be corrected in any case. None of the performance discrepancies present will have a detectable effect upon Thematic Mapper instrument performance.

REA R L Julian SYS. ENGR. REL [Signature] QA [Signature]
PE [Signature]

25. APPROVAL/DISAPPROVAL	
<input type="checkbox"/> APPROVAL	<input checked="" type="checkbox"/> DISAPPROVAL
26. SIGNATURE <u>[Signature]</u> 12/1/81	

ORIGINAL PAGE IS
OF POOR QUALITY

07299

Thematic Mapper Request for Deviation/Waiver W124 (Continued)

Item 23 - Description of Deviation/Waiver (Continued)

- o Six channels exhibit one A/D conversion step which exceeds the specified maximum of 31.2 millivolts and/or is less than the specified minimum of zero millivolts in size. No sensor exhibits more than one step which is too large and one which is too small. The sensors and corresponding Failure Reports are listed in Table 3. In all cases the discrepant conversion step does not cause the RMS noise of the sensor channel to exceed specified values, and therefore the discrepancies will not appreciably affect Instrument performance. The minimum and maximum step sizes are a self-imposed Multiplexer requirement, rather than a system level requirement.

ORIGINAL PAGE IS
OF POOR QUALITY

07299

FROM		TO		TEMPERATURE			F. R. NUMBER(S)
BAND	SENSOR	BAND	SENSOR	+50°C	+15°C	AMB	
1	10	1	8			X	F07296
1	14	1	12			X	F07296
2	4	2	2	X	X	X	F07299, F07295, F07296
2	5	2	3		X		F07299
2	13	2	11	X			F07295
2	14	2	12		X	X	F07299, F07296
3	6	3	4		X		F4268
3	10	3	6				F4268
4	12	4	10			X	F07296
4	16	4	14	X			F4254
6	1	6	4	X	X	X	F4268, F4254, F4257
6	2	6	3	X	X	X	F4268, F4254, F4257
6	3	6	1	X	X	X	F4268, F4254, F4257
6	4	6	2	X	X	X	F4268, F4254, F4257
7	7	7	5	X			F4254
7	13	7	11	X			F4254

TABLE 1. MULTIPLEXER S/N 003 CROSSTALK

NOTE: All channel pairs were out of specification by only one multiplexer quantization level.

ORIGINAL PAGE IS
OF POOR QUALITY

07299

BAND	SENSOR	TEMPERATURE	MV/SEC	F. R. NUMBER
1	3	Ambient	4.11	F4255
5	6	Ambient	4.90	F4255

NOTE: Spec maximum of ± 3 mv/sec is a self-imposed specification. Instrument error budgets would allow rate up to ± 120 mv/sec.

TABLE 2. DROOP TEST FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

07299

BAND	SENSOR	TEMP °C	STEP #	MAX VALUE (MV)		MIN VALUE (MV)		F. R. NUMBER
				≤ 31.2 MV	STEP #	≥ 0.0 MV		
1	1	+15			32	-0.8	F4266	
7	13	+15			241	-0.4	F4266	
6	1	+15	193	41.7	192	-0.1	F4266	
6	2	+15	193	37.3			F4266	
6	3	+15	193	39.1	192	-0.4	F4266	
6	4	+15	193	39.3	192	-0.3	F4266	
6	1	+50	128	39.8	129	-0.1	F4267	
6	2	+50	128	37.0	129	-0.1	F4267	
6	3	+50	128	36.8			F4267	
6	4	+50	128	36.8	192	-0.1	F4267	
6	1	Ambient	193	39.4	160	-0.1	F4265	
6	2	Ambient	193	37.5	160	-0.5	F4265	
6	3	Ambient	225	35.5	224	-0.8	F4265	
6	4	Ambient	193	39.6	232	-0.2	F4265	

TABLE 3. A/D CONVERSION FAILURES

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.2
SCAN MIRROR ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

2.2.1

Section 2.2.1

Scan Mirror Assembly

Performance Data

The acceptance performance (test) data for the Scan Mirror
Assembly is contained in Appendix B (Vol. IV, part B).

2.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.2.2

Acceptance Data

2.2.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.2.2.1

Configuration Lists

ORIGINAL PAGE IS
OF POOR QUALITY

DATE: 4/22/81

P/N 3533002-100

PAGE 1 OF 4

THEMATIC MAPPER

SCAN MIRROR ASSEMBLY SERIAL NO. 004

AS DESIGNED			AS BUILT		
DOCUMENT NO.	REV.	SUPPLEMENTARY DOCUMENTS	DOCUMENT	REV.	SUPPLEMENTARY DOCUMENTS
3533002-100	D	W020 EO 64358 EO 13113 EO 64363 EO 64374 EO 64369	3533002-100	D	W020 EO 64358 EO 13113 EO 64363 EO 64374 EO 64369
TS 32015-004	B	EO 13100 EO 64391 EO 13111 EO 64385 EO 64394 EO 13112 EO 64379 EO 13105	TS 32015-004	B	EO 13100 EO 64391 EO 13111 EO 64385 EO 64394 EO 13112 EO 64379 EO 13105
3568874	B	EO 70667 EO 70504 EO 64304 EO 70565 EO 70614 EO 70583 EO 64371	3568874	B	EO 70667 EO 70504 EO 70565 EO 70614 EO 70583
3568900	C	EO 70693	3568900	C	EO 70693
3568899-2	B	W062 W044 EO 64392	3568899-2	B	W062 W044 EO 64392
3568911	B	EO 64344 EO 70672	3568911	B	EO 64344 EO 70672
3568909	A		3568909	A	
3568970	A	EO 64322 EO 64330 EO 64317 EO 64314	3568970	A	EO 64322 EO 64330 EO 64317 EO 64314

DATE: 4/22/81

P/N 3533002-100

ORIGINAL PAGE IS
OF POOR QUALITY
PAGE 2 OF 4

THEMATIC MAPPER

SCAN MIRROR ASSEMBLY SERIAL NO. 004

AS DESIGNED			AS BUILT		
DOCUMENT NO.	REV.	SUPPLEMENTARY DOCUMENTS	DOCUMENT	REV.	SUPPLEMENTARY DOCUMENTS
568972	F	W070	3568972	E	W070 EO 64335 EO 64360 EO 64352 EO 64329 EO 64323 EO 64318
568980	D	D009 D020 D024	3568980	C	D009 D020 D024 EO 64350 EO 70677 EO 64341 EO 64302 EO 64339 EO 64328 EO 64356
568995	N/C	EO 70482 EO 70546 EO 70577 EO 70615	3568995	N/C	EO 70482 EO 70546 EO 70615 EO 70577
568980 <i>SAME AS ABOVE</i>	D	D009 D020 D024	3568980	C	D009 D020 D024 EO 64350 EO 70677 EO 64341 EO 64302 EO 64339 EO 64323 EO 64356
568995 <i>SAME AS ABOVE</i>	N/C	EO 70482 EO 70546 EO 70577 EO 70615	3568995	N/C	EO 70482 EO 70546 EO 70615 EO 70577

ORIGINAL PAGE IS
OF POOR QUALITY

DATE: 4/22/81

P/N 3533002-100

PAGE 3 OF 4

THEMATIC MAPPER

SCAN MIRROR ASSEMBLY SERIAL NO. 004

AS DESIGNED			AS BUILT		
DOCUMENT NO.	REV.	SUPPLEMENTARY DOCUMENTS	DOCUMENT	REV.	SUPPLEMENTARY DOCUMENTS
3568985	E	D011 D019 D023 EO 64337 EO 64342	3568985	E	D011 D019 D023 EO 64337 EO 64342
3568997	N/C	EO 70406 EO 70483	3568997	N/C	EO 70406 EO 70483
3568985-1	E	D011 D019 D023 EO 64337 EO 64342	3568985-1	E	D011 D019 D023 EO 64337 EO 64342
3568997 <i>SMILE AS ASSEMB</i>	N/C	EO 70406 EO 70483	3568997	N/C	EO 70406 EO 70483
3568990	D	D029 D017 EO 64355 EO 70684 EO 64319	3568990	D	D029 EO 64355 EO 70684 EO 64319
3569087	N/C	EO 64311 EO 64359 EO 64347	3569087	N/C	EO 64311 EO 64359 EO 64308 EO 64347
3569000	D	W070 EO 70646 EO 70679 EO 64357	3569000	D	W070 EO 70646 EO 70679 EO 64357
3569018	B	EO 70587 EO 64354 EO 64362 EO 64361	3569018	B	EO 70587 EO 64354 EO 64361

ORIGINAL PAGE IS
OF POOR QUALITY

DATE: 4/22/81

P/N 3533002-100

PAGE 4 OF 4

THEMATIC MAPPER

SCAN MIRROR ASSEMBLY SERIAL NO. 004

AS DESIGNED			AS BUILT		
DOCUMENT NO.	REV.	SUPPLEMENTARY DOCUMENTS	DOCUMENT	REV.	SUPPLEMENTARY DOCUMENTS
3569010	C	D0008 EO 70622	3569010	C	D0008 EO 70662
3569093	N/C	EO 70336	3569093	N/C	EO 70336
3569010 <i>SAME AS ABOVE</i>	C	D0008 EO 70622	3569010	C	D0008 EO 70622
3569093 <i>SAME AS ABOVE</i>	N/C	EO 70336	3569093	N/C	EO 70336
3569050-1	A	EO 64332	3569050-1	A	EO 64332
9050-2	A	EO 64332	3569050-2	A	EO 64332
3 7062-1	A		3569062-1	N/C	EO 70606 EO 70551 EO 70434 EO 70564 EO 70553
3569062-2	A		3569062-2	N/C	EO 70551 EO 70606 EO 70553 EO 70434 EO 70564
3569083	N/C	EO 70391 EO 70397 EO 64346 EO 70521	3569083	N/C	EO 70391 EO 70397 EO 70521
3569114 ✓	A	EO 64345	3569114	A	EO 64345
3569019 ✓	D		3569019	C	EO 70568 EO 70575

R. L. Cook
R. L. COOK, MANAGER
THEMATIC MAPPER CMO

A. R. Handette
QUALITY ASSURANCE ENGINEER

2.2.2.2

ORIGINAL PAGE IS
OF POOR QUALITY

SCAN MIRROR ASSEMBLY

Listing of Liens

ORIGINAL PAGE IS
OF POOR QUALITY

SCAN MIRROR ASSEMBLY

P/N 353302-100

FLIGHT

Failure Report No.	
Open	Closed
	F0170*
	F1302
	F1305
	F1306
	F1307
	F1308
	F1322
	F1325
	F1327
	F1328
	F1329
	F1330
	F1342
	F1352
	F1353
	S8392
	S8116
	S8369

Deviations	Waivers
	W-121

* Spare

ORIGINAL PAGE 13
OF POOR QUALITY

SCAN MIRROR ASSY.

P/N 3533002

<u>FLIGHT</u>		<u>PROTOFLIGHT</u>		<u>ENGINEER</u>		<u>LTM</u>	
Failure Report No.		Failure Report No.		Failure Report No.		Failure Report No.	
Open	Closed	Open	Closed	Open	Closed	Open	Closed
	F0170 Spare						
	F1302		F1317		A0028		F0161
	F1305		F1318		A0080		F1304
	F1306		F1344		A0081		F1309
	F1307		F1345		A0082		F1310
	F1308		F1350		A0083		F1313
	F1322		F1354		F0502		F1314
	F1325		F2642		F0503		F1315
	F1327		F2691		F0701		F1316
	F1328		F2739		F0702		F1320
	F1329		S8092		F1301		F1323
	F1330		S8300		F1312		
	F1342				F1343		
	F1352				F1351		
	F1353						
	S8116						
	S8369						
	S8392						

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1302

1. PROGRAM NAME AND NUMBER HS 236 THEMATIC MAPPER		2. GLA	3. MODEL PLT	4. TIME OBSERVED 1300	5. DATE OBSERVED 6 28 79
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> M-CAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM 3533002-100		NAME SMA		PART NUMBER 3533002-100	S/N 001EM
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> DISASSEMBLY		TORQUER ASSY		3568911	4563
10. <input type="checkbox"/> MODULE <input type="checkbox"/> M-CAM <input type="checkbox"/> CARD					
11. OTHER SUBASSEMBLY: HOUSING ASSY - TORQUER		3568909		3456	
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input type="checkbox"/>					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° _____ THERMAL VAC _____ HRA AT _____ ° <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AIS FOR _____ MIN TYPE _____ OTHER _____					
14. DESCRIPTION OF FAILURE TERMINALS E5, E1, E4, E8 ARE NOT MARKED AS PER DRAWING 3568902					
15. TEST PROCEDURE		PARA	16. ORIGINATOR A.G. HOLER	ORG 28 15 125	DATE 7/19/79
15. CONTINUATION SHEET USED <input type="checkbox"/>					
16. VERIFICATION AND FAILURE ANALYSIS VISUAL INSPECTION VERIFIED DISCREPANCY					
17. FAILED ITEM NAME AND PART NUMBER					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REMARK TERMINALS PER PRINT					
21. AUTHORIZATION		ORG	DATE	21. CONTINUATION SHEET USED <input type="checkbox"/>	
22. REWORK/RETEST ACTION TAKEN S/N 003, 004 AND 005 WERE REWORKED TO PRINT OCHR'S ATTACHED. S/N 6 WAS USED IN ENGINEERING MODEL.					
23. LIST ALL PARTS REPLACED					
PART NUMBER	QTY	S/N	PART LOT NO.	DATE CODE	U/R
27. REWORK BY		ORG	DATE	28. RETESTED BY	ORG
29. CAUSE AND CORRECTIVE ACTION WORKMANSHIP ERROR. TECHNICIANS AND QA PERSONNEL WERE ADVISED TO USE CAUTION IN MARKING TERMINALS AND INSPECTING MARRINGS.					
31. PRO CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
33. CONTINUATION SHEET USED <input type="checkbox"/>					
34. BASIC CAUSE OR VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURES <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> REAR OUT					
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCED					
36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE		DATE	38. SPACECRAFT	ORG	DATE
A.G. HOLER		7/19/79	PLT		

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1305

1. PROGRAM NAME AND NUMBER <i>HS 236-TA1</i>		2. CLA <i>E331</i>		3. MODEL <i>A-1</i>		4. TIME OBSERVED <i>1630</i>		5. DATE OBSERVED MO <i>7</i> DA <i>27</i> YR <i>70</i>			
6. HAZARD LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> PART											
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER			
8. UNIT											
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<i>MIRROR</i>		<i>3568899</i>		<i>5</i>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD											
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM		<i>Pre-Test to Assy For EM</i>									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> KRE AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER											
14. DESCRIPTION OF FAILURE <i>NICKEL PLATING ON REAR SURFACE LISTED 2 PLACES; NEAR ONE CORNER OF THE HOLE & AT EDGE NEAR MAJOR AXIS</i>											
15. TEST PROCEDURE		PARA		16. ORIGINATOR <i>F. W. GIBBETT</i>		ORG <i>100-45</i>		DATE <i>1/27/80</i>			
17. VERIFICATION AND FAILURE ANALYSIS <i>ACTUALLY ONLY ONE HOLE IN AREA NEAR CORNER OF THE HOLE</i>											
18. FAILED ITEM NAME AND PART NUMBER <i>M-0000 P/N 3568800</i>											
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <i>MIRROR WILL BE RETURNED TO VENDOR FOR REWORK AFTER USE ON EM (ALSO SEE TFR #1352)</i>											
20. REWORK/RETEST ACTION TAKEN <i>VENDOR TO STRIP, REPAIR & REWORK</i>		21. AUTHORIZED BY <i>[Signature]</i>		ORG <i>100-15</i>		DATE <i>1/31/80</i>		22. CONTINUATION SHEET USED			
23. LIST ALL PARTS REPLACED											
PART NUMBER		CMT SYN		PART LOT NO.		DATE CODE		MFR			
								PROBABLE DEFECT			
								ANALYSIS NO.			
27. REWORK BY		ORG		DATE		28. RETESTED BY		ORG			
29. CAUSE AND CORRECTIVE ACTION <i>IMPROPER CLEANING BY VENDOR.</i>											
RETURN TO VENDOR REF. NCMR 316897								33. FRB CLOSURE			
<i>SUPPLIER CORRECTIVE ACTION REQUEST # 63891 WAS SENT TO VENDOR IN ACCORDANCE WITH HUGHES AIRCRAFT Co. SUPPLIER CORRECTIVE ACTION SYSTEM.</i>											
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>NCMR 316897</i>								34. CONTINUATION SHEET USED			
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE											
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		37. RESPONSIBLE ENGINEER <i>[Signature]</i>		ORG <i>177-15</i>		DATE <i>1/23-80</i>		38. SPACECRAFT/SYSTEM ENG <i>[Signature]</i>	
39. RELIABILITY		ORG		DATE		40. CUSTOMER OR EMPLOYEE		DATE			

ORIGINAL PAGE IS
OF POOR QUALITY



DUPLICATE
SPACE AND COMMUNICATION GROUP
FAILURE REPORT

1306
F

1. PROGRAM NAME AND NUMBER TM HS-236		2. OLA E330	3. MODEL FLT	4. TIME OBSERVED ---	5. DATE OBSERVED 10/12/79	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:						
7. SUBSYSTEMS		NAME		PART NUMBER	S/N	
8. UNIT SVA				3533002-100	---	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD				3568985	007	
11. OTHER					HAC	
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS		
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> ELEC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMPERATURE _____ ° AXIS FOR _____ MIN TYPE _____	<input type="checkbox"/> THERMAL VAC _____ HRS. AT _____ °	<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE AR2 rotated counter-clockwise. ART was on Reg 4 assembly drawing ambiguous. work						
15. TEST PROCEDURES TS32015-006		PARA 4.8	16. ORIGINATOR Warren Hayden	ORG 77-35-24	17. CONTINUATION SHEET USED <input type="checkbox"/>	
18. VERIFICATION AND FAILURE ANALYSIS -24vdc voltage adjustment faulty. due to pin rotation on AR2. Other than AR2, no parts were stressed. Power supply was current limited a 30 ma.						
19. FOLLOWING REPAIR/RETEST REQUIRED REWORK/RETEST NOT REQUIRED EXCEPT		Replace AR2/Retest				
20. REWORK/RETEST ACTION TAKEN Removed AR2		21. AUTHORIZATION Warren Hayden		ORG 17-35-22	22. CONTINUATION SHEET USED <input type="checkbox"/>	
23. LIST ALL PARTS REPLACED		24. REWORK/RETEST ACTION TAKEN Replaced F/R 10/22/79 Retested 10/30/79				
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT	
908950-1	AR 2	90892-501W				
27. REWORK BY HS		ORG 77-55	DATE 10/19/79	28. RETESTED BY W. Hayden	ORG 77-32-12	
29. CAUSE AND CORRECTIVE ACTION Drawing was not clear Dwg Changed - See ECR 873583 Revision D						
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION ECR 873 583 Rev D released 11/1/81		33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY				
34. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	<input type="checkbox"/> UNKNOWN DEFECT CODE	
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	36. SPACECRAFT SYSTEM ENGR. W. Hayden			
37. RESPONSIBLE ENGINEER R. B. ...		ORG 77-32-11	DATE 10/16/80	38. CUSTOMER OR SUPPLIER R.B.		
39. RELIABILITY ...		ORG 77-44	DATE 11-12-80	DATE 11/21/80		

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

DUPLICATE
SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F

1307

1. PROGRAM NAME AND NUMBER H3-236 (TM)		2. QLA# E330		3. MODEL NUMBER NS236TM		4. TITLE OBSERVED LTMT		5. DATE OBSERVED 12/10/79	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> C/SPACECRAFT	<input type="checkbox"/> S/SYSTEM	<input checked="" type="checkbox"/> ASSEMBLY	<input type="checkbox"/> SPECIAL	<input type="checkbox"/> CARD			
		<input type="checkbox"/> SYSTEM	<input type="checkbox"/> UNIT	<input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> EXCAN	<input type="checkbox"/> PART			
7. EQUIPMENT IDENTIFICATION									
7. SUGGESTED		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT		Scan Mirror Assy		3533002-103		--		HAC	
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> SPECIAL <input type="checkbox"/> CARD									
11. OTHER									
12. TEST SYSTEM FAILURE WAS OBSERVED									
<input type="checkbox"/> DEVELOPMENT		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS			
<input type="checkbox"/> IN-PROD USE		<input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED									
<input checked="" type="checkbox"/> AMBIENT		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMPERATURE		<input type="checkbox"/> THERMAL VAC		<input type="checkbox"/> MEL AT	
<input type="checkbox"/> EMC/RFI		<input type="checkbox"/> VIBRATION		AXIS FOR		MIN		TYPE	
14. DESCRIPTION OF FAILURE									
Harness continuity failure. (1) No continuity for J2-22 to A1-E91. (2) P3-8 has the wire that should be connected to P3-9. P3-8 should have no connection. (3) Chassis ground & RTN are connected together and be isolated.									
15. TEST PROCEDURE TS32015-006 PARA 4.4 16. ORIGINATOR W. Hayden ORG 177-35-42 DATE 12/10/79 CONTINUATION SHEET USED									
18. VERIFICATION AND FAILURE ANALYSIS									
No power was applied, therefore no operations occurred.									
19. FAILED ITEM NAME AND PART NUMBER									
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE									
Forward a description of all rework action to test to determine if complete/partial retest is required.									
21. AUTHORIZATION									
BY W. Hayden		ORG 177-35-42		DATE 12/10/79		CONTINUATION SHEET USED			
22. REWORK/RETEST ACTION TAKEN									
(1) J2 22 wired to E3/Replaced J2-22 wire (2) Switched P38 wire to P3-9 (3) Item 13 was shorted to Item 26. Replaced Item 33. Retest successful to TS 32015-006.									
23. LIST ALL PARTS REPLACED									
PART NUMBER		CKT SYN		PART LOT NO.		DATE CODE		MFR	
27. REWORK BY Jean Halder ORG 177-55 DATE 12/13/79 28. RETESTED BY W. S. Hayden ORG 177-35-42 DATE 12/18/79 CONTINUATION SHEET USED									
29. CAUSE AND CORRECTIVE ACTION									
Workmanship									
Assembler has been cautioned to use extreme care when performing the wiring operation.									
33. PRO CLOSURE									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
Verbal									
34. BASIC CAUSE OF VERIFIED FAILURE									
<input type="checkbox"/> DESIGN		<input type="checkbox"/> TEST EQUIP.		<input type="checkbox"/> MFG. PROCEDURE		<input type="checkbox"/> WRINKING ERROR		<input type="checkbox"/> UNKNOWN	
<input type="checkbox"/> ENVIRONMENTAL		<input type="checkbox"/> TEST PROC.		<input type="checkbox"/> ASSY/PKG ERROR		<input type="checkbox"/> ROUGH HANDLING		<input type="checkbox"/> DEFECT CODE	
<input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST SET-UP		<input checked="" type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WEAR-OUT			
35. FAILURE TYPE		<input checked="" type="checkbox"/> PRIMARY		<input type="checkbox"/> UNKNOWN		<input type="checkbox"/> CRITICAL		<input checked="" type="checkbox"/> MINOR	
		<input type="checkbox"/> INDUCED		<input type="checkbox"/> NO FAILURE		<input type="checkbox"/> MAJOR		<input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER		ORG 177-15		DATE 1/29/80		38. SPACECRAFT SYSTEM ENGR		ORG 22-4 DATE 1/11/80	
J. Pulina		157-41		11-10-80		W. S. Hayden		177-35-42	
39. RELIABILITY		ORG 157-41		DATE 11-10-80		40. CUSTOMER OR SUPPLIER		DATE	
157-41		157-41		11-10-80		W. S. Hayden			

HUGHES

HUGHES AIRCRAFT COMPANY

DUPLICATE

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F

1308

~~1308~~

1. PROGRAM NAME AND NUMBER TM HS-236		2. QLA E330		3. MODEL FLT		4. TIME OBSERVED --		5. DATE OBSERVED 10/31/79		
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:										
7. EQUIPMENT		NAME		PART NUMBER		SN		MANUFACTURER		
8. UNIT		SMA		3533002-100		--		HAC		
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		SME		3568970		--		HAC		
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		Elect. Comp. Assy.		3568990		008		HAC		
11. OTHER										
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INPROCES		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS		
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMPERATURE _____ ° _____		<input type="checkbox"/> THERMAL VAC _____ HRS. AT _____		OTHER _____		
14. DESCRIPTION OF FAILURE		CR38 polarity reversed para 4.1, 3)a test failed. E78 measured 5.6v instead of 0v indicating CR38 polarity reversed.								
15. TEST PROCEDURE		TS 32015-006 para 4.1		16. ORIGINATOR		W. Hayden		17. CONTINUATION SHEET USED		
18. VERIFICATION AND FAILURE ANALYSIS		CR38 diode was polarity was reversed CR38 allows high voltage to be applied to Q1. The only effect of CR38 being reversed is to block voltage to base of Q1. No other effect.								
19. FOLLOWING REMOVAL/RETEST REQUIREMENTS/RETEST NOT REQUIRED/RETEST REQUIRED		REF. IDC HS236-777 FOR STRESS ANALYSIS. (CIT ATTACHED) Remove and reverse CR38. Retest.								
20. AUTHORIZATION		W. Hayden		21. DATE		10/31/79		22. CONTINUATION SHEET USED		
23. REMOVAL/RETEST ACTION TAKEN		Removed & reversed CR38-- Retested 10/31/79								
24. LIST ALL PARTS REPLACED										
PART NUMBER		CKT SYM		PART LOT NO.		DATE CODE		PROBABLE DEFECT		ANALYST NO.
25. REPORT BY										
E. P.		ORG 77-15		DATE 10-31-79		26. RETESTED BY		DATE 11-12-79		27. CONTINUATION SHEET USED
28. CAUSE AND CORRECTIVE ACTION		Part was installed backward during assembly and was not detected by assemblers or quality.								
29. PRO CLAUSE		Assembler cautioned to use EXTREME CARE AND REINSTRUCTED REGARDING THIS DIODE INSTALLATION IN ACCORDANCE WITH DRAWINGS.								
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		CAR 63100 - COPY ATTACHED								
31. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT. <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE		
32. FAILURE TYPE		<input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		33. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		
34. RESPONSIBLE ENGINEER		R.J.L. / C500		35. DATE		77-15 10/31/79		36. SPACECRAFT SYSTEM ENGR		
37. RELIABILITY		R. Pedraza		38. DATE		11-19-79		39. CUSTOMER OR SUPPLIER		

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

F 1308

TO: L. O'Connell

CC: Altman, L.
Barnett, G.C.
Day, J.G.
Data Bank

DATE: 13 November 1981

REF: HS236-7717
REAH 81/60

FROM: A. Huber

SUBJECT: FR: F1308
(SME Interface Bd,
3568990, Flt)

B.L.D.C. B-11 MAIL STA. 102
EXT. 6246

FR: F1308, dated 10/31/79

The failure was encountered during board test of the scan mirror electronics interface board (assy. no. 3568990) and consisted of an improperly installed diode (CR38 installed with reverse polarity). Figure 1 illustrates the circuit which utilizes CR38. With CR38 installed backwards it was not possible to generate +5VDC logic power via relay K2. The diode was subsequently reinstalled with correct polarity. No overstress to interface board circuitry occurred as a result of the absence of +5VDC power.

Andrew E Huber

A. Huber

AH:jc

ORIGINAL PAGE IS
OF POOR QUALITY

F1308

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 1. SME INTERFACE BOARD CIRCUITRY FOR GENERATION OF +5VDC LOGIC POWER

CORRECTIVE ACTION REQUEST

SEE REVERSE SIDE FOR COMPLETION INSTRUCTIONS

TFR 1308

63100

	NAME	SOURCE CODE	ADDRESS/ MAIL STATION	PHONE EXT.
1. TO:	E. A. ANZIVINO	77-07	12	4165
2. FROM:	R. L. COON	77-15	12/V104	7433
3. REFERENCE:	Failure Report F-1308			E330 GLA NO.

ORIGINATOR

5. PLEASE TAKE THE NECESSARY ACTION TO CORRECT THE CAUSE OF THE FOLLOWING CONDITION(S):

PROBLEM DESCRIPTION:

No inspection of parts placement on PCB boards is taking place causing failures during test.
- See Ref Failure Report

[Signature] 1/14/80
SIGNATURE DATE
BLDG 12 MAIL STATION V104

7. CAUSE:

SEE ATTACHMENT

ORIGINAL PAGE IS
OF POOR QUALITY

RECIPIENT

8. THE FOLLOWING CORRECTIVE MEASURES HAVE BEEN TAKEN TO ELIMINATE THE CAUSE OF THE CONDITION(S) NOTED ABOVE

EFFECTIVITY: _____
(LOT, SERIAL, DATE, OTHER)

9. REMEDY:

SEE ATTACHMENT

10. SIGNED: [Signature] DATE: 1/13/80

CONCLUSION - SATISFACTORY CORRECTION HAS BEEN EFFECTED - YES NO

12. FOLLOW UP REQUIRED:

13. SUSPENSE DATE: _____ 14. SIGNED: [Signature] DATE: 2/5/80
ORIGINATOR

F 1308

Reply to CAR 63100

ORIGINAL PAGE IS
OF POOR QUALITY

An investigation into this problem indicates that this was an oversight by both the Manufacturing operator and the QA inspector. Discussion with all inspection personnel has assured me they are aware of the requirement to review component polarity, component placement, component value, and workmanship during inspection operations. Therefore this is a random error.

NOTE:

Although the failure was detected by test personnel on 10-31-79, neither Manufacturing supervisor nor the operator were contacted until 1-28-80, at which time Q.A. requested Corrective Action. Q.A. was not notified of the error until 1-14-80.

REMEDY

- a) Manufacturing supervision and operator were notified of discrepancy on 1-28-80.
- b) A review of the affected drawing and planning was performed on 1-28-80. These documents were found to be adequate and did not contribute to the problem.
- c) The inspector assigned to the program was cautioned on 1-28-80, to exercise more care during future inspections.

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1322

1. PROGRAM NAME AND NUMBER <i>Thematic Mapper</i>		2. OLA <i>E330</i>	3. MODEL <i>F-1</i>	4. TIME OBSERVED <i>1:30pm</i>	5. DATE OBSERVED <i>Nov 5 '80</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM <i>Scan Mirror</i>		PART NUMBER <i>3568399</i>		S/N <i>005</i>	
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>BRDF testing showed an average Total Integrated Scatter of 0.5% and drawing note (19) (20) (21) specifies less than 0.4%</i>					
15. TEST PROCEDURE		PARA	16. ORIGINATOR <i>M.P. Wirick</i>	ORG <i>77-45</i>	DATE <i>12/1/80</i>
17. VERIFICATION AND FAILURE ANALYSIS <i>Failure verified by M.P. Wirick & Tim Siebert</i>					
18. FAILED ITEM NAME AND PART NUMBER					
19. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>Retest and verify the storage container - factory results</i>					
SPEC CHANGED EO 64392					
20. AUTHORIZATION		ORG	DATE	21. CONTINUATION SHEET USED	
22. REWORK/RETEST ACTION TAKEN					
23. CA REWORK					
24. CA RETEST					
25. LIST ALL PARTS REPLACED					
PART NUMBER	QTY SYN	PART LOT NO.	DATE CODE	WR	PROBABLE DEFECT
					ANALYSIS NO.
27. Rework BY		ORG	DATE	28. RETESTED BY	ORG
					DATE
29. CAUSE AND CORRECTIVE ACTION <i>MEASURED VALUE IS CONSIDERED TO BE WITHIN STATE OF THE ART MFG. LIMITS. INCREASE SPEC TO ALLOW MEASURED VALUE FROM 0.4% TO 0.5% WHICH CORRESPONDS TO ISATBR SPEC AT NEXT LEVEL OF ASSEMBLY.</i>					
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>EO 64392</i>					
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> INSUFFICIENT HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WORN-OUT					
32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCTED		33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER <i>A.D. [Signature]</i>		ORG <i>77-15</i>	DATE <i>1-13-81</i>	38. SPACECRAFT SYSTEM ENGR <i>M. J. [Signature]</i>	
39. RELIABILITY <i>1. [Signature]</i>		ORG <i>51-41</i>	DATE <i>1-15-81</i>	40. CUSTOMER OR SUPPLIER <i>B.B.</i>	

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1325

1 PROGRAM NAME AND NUMBER T.M. HS 236	2 QLA F33	3 MODEL F-1	4 TIME OBSERVED 10:04	5 DATE OBSERVED 7 2 81	6 DA 81	7 YR 81
8 HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MECAN <input type="checkbox"/> CARD <input type="checkbox"/> PART						
EQUIPMENT IDENTIFICATION						
1 SUBSYSTEM	NAME		PART NUMBER		LN	MANUFACTURER
2 UNIT						
3 <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
4 <input type="checkbox"/> MODULE <input type="checkbox"/> MECAN <input type="checkbox"/> CARD						
5 OTHER	SYSTEM UNIT SMTA		3533002-100		4	HAC
6 TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS						
7 ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> ENCLOSURE <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> AIRSPEED <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> WRE AT <input type="checkbox"/> OTHER						
14 DESCRIPTION OF FAILURE TELEMETRY READOUT - LINE LENGTH WAS 000 000 000 000 (REV. E 1-26-81) TYP. LINE LENGTH IS 000 377 350 000 FAIL INDICATION WAS IN F-1 PRE-TEST RUN #1098.1126-A.S.600 REPORT 16/04/81 (SITS)						
15 TEST PROCEDURE TS 32015-004	16 ORIGINATOR A. J. Williams	17 DATE 7-21-81	18 CONTINUATION SHEET USED			
19 VERIFICATION AND FAILURE ANALYSIS TELEMETRY TABLE PRINTOUT REVEALED THAT NEITHER SERIAL FLIGHT LINE LENGTH DATA WERE BEING RECEIVED. FURTHER INVESTG. SHOWED THAT THIS CONDITION CAN ONLY OCCUR FOR CERTAIN INTERNAL FAILURES IN THE DAS (TEST EQUIPMENT). REPAIR HAS BEEN POSTPONED FOR SCHEDULE (N/A - DESTRUCTIVE & INTERMITTANT) DAS (TEST EQUIP)						
20 CONFIRMATION OF DAS OPERABILITY TO BE PERFORMED AFTER EACH DATA COLLECTION (PRINT 1ST & LAST 2 TLMY TABLES & CONFIRM LINE LENGTH & TLMY OK) BEFORE PROCEEDING, REPAIR DAS INTERMITTANT PROBLEMS						
21 AUTHORIZED BY A. J. Williams DATE 7-22-81						
22 REWORK / TEST ACTION TAKEN RETEST CONFIRMED INTERMITTANT FAILURE IN DAS. DATA TAKEN DURING PERIOD OF DAS REPAIR OPERATION. STATED PROBLEMS TELEMETRY LINE LENGTH READOUT SEE TM SMTA F-1 MODEL W/STAN: TEST DATA PLS TS 236.						
23 LIST ALL PARTS REPLACED						
PART NUMBER	CRYSM	PART LOT NO.	DATE CODE	UPR	PROBABLE DEFECT	ANALYSIS NO.
27 REWORK BY ORG DATE DATE 28 RETESTED BY DATE 29 CONTINUATION SHEET USED						
30 CAUSE AND CORRECTIVE ACTION DAS INTERNAL COMPONENT FAILURE OR INTERMITTANT REPAIR TO BE POSTPONED. REPAIR OUTLINE IN AVO FORM PR. PRINCIPLES TO AB. MARCMAT, Feb 23, 1981. TESTING WILL INCLUDE INFORMAL DATA CHECK TO CONFIRM VALID DATA BEFORE PROCEEDING TO FOLLOWING TEST. (PRINT SER. TLMY TABLES AT TRD. FILE 15/16). CHECK FOR VALID DATA IN 1ST & LAST TABLE.						
31 DOCUMENT IMPLEMENTING CORRECTIVE ACTION						
32 BASIC CAUSE OF FAILURE <input type="checkbox"/> DESIGN <input checked="" type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WORKING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT						
33 FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCED						
34 FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY						
35 RESPONSIBLE ENGINEER A. J. Williams DATE 7-22-81						
36 RELIABILITY ORG DATE 7-3-81						
37 SPACECRAFT SYSTEM ENGR A. J. Williams DATE 7-26-81						
38 CUSTOMER OR SUPPLIER HAC DATE 7/18/82						

HUGHES

SPACE AND COMMUNICATIONS GROUP

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

**FAILURE REPORT
CONTINUATION SHEET**

FORM NO. **F-125**
CONTINUATION SHEET LETTER

LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON
 IDENTIFY ENTRIES BY REFERENCES TO BLOCK NUMBERS IN COLUMN, DATE EACH ENTRY. ADDITIONAL PR CONTINUATION SHEETS USED

30 THE DAS (DATA ACQUISITION SYSTEM) WILL NOT BE REPAIRED UNLESS A FOLLOW-UP CONTRACT IS AWARDED AT THAT TIME THE DAS WILL BE REPAIRED AS OUTLINED IN P.R. PRINCE'S AVO (DATED 2/23/82) TO A. B. MARCHANT. (COPY ATTACHED) *[Signature]* 2/27/82
HS 236-7830 DIRECTS THAT DAS BE RED TAPPED TO FLAG DISCREPANCY AND ASSURE REPAIR PRIOR TO NEXT USE.

ORIGINAL PAGE IS
OF POOR QUALITY

F1325

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

TO: G. Gaudetta

CC: A.B. Marchant

DATE: 8 February 1982

REF: HS 236-7830

PE 21:82

FROM: A. Perline

SUBJECT: Equipment Usage Suspension
for Scan Mirror Assembly DAS
Test Set.

BLDG. B-11 MAIL STA. 39
EXT. 6106

1. Failure Report F1325 documents an SMA discrepancy that was discovered on 2 February 1981. The cause of this discrepancy was traced to the DAS used for testing the SMA.
2. The DAS will not be repaired unless there is some follow-up work on the Thematic Mapper.
3. It is necessary to preclude any possible future utilization of the DAS prior to repair. Therefore, you are requested to affix a red "equipment usage suspension" tag to the DAS with an explanation that maintenance is required prior to use.



A. Perline

AP:jc

Attachments: Failure Report F1325

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1327

1. PROGRAM NAME AND NUMBER TM HS236		2. C/A E330		3. MODEL F-1		4. TIME OBSERVED 10 AM		5. DATE OBSERVED NOV 2 81			
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> D/CRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECAN <input type="checkbox"/> PART		7. EQUIPMENT IDENTIFICATION: NAME		PART NUMBER		S/N		MANUFACTURER			
7. SUBSYSTEM		8. UNIT SCAN MIRROR ASST		9. PART NUMBER 3533002-100		10. S/N 4		11. MANUFACTURER HAC			
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROGRESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM		13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° <input type="checkbox"/> THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ OTHER _____		14. DESCRIPTION OF FAILURE (1) TEE K, L, N; DATA SHIT 4.3.5.2; TURN AROUND TIME EXCEEDED 10590 SDR HSG. LIMITS - 1112 10.6 70.245 (2) FAILURE IN SEQUENCE TEE'S & R		15. TEST PROCEDURE T532015-004 PARA 14351		16. ORIGINATOR R. SCHREINER		17. DATE 17-21-23 12-281	
18. VERIFICATION AND FAILURE ANALYSIS Failure: Frame to data station failure alarm was 1.5 mils thick, should have been 2.5 mils; then alarm value has been corrected (corrected turn-around times). Also Relay Mirror position non-optimum		19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE REPORT TEE-H OF T532015-004 & PROCEED REF HS236-2043, @ AS SEQUENCE #6		20. FAILURE TEST MARKS AND PART NUMBER DNA		21. AUTHORIZATION R. Schreiner		22. DATE 17-22-11 Feb 23 '81		23. CONTINUATION SHEET USED <input type="checkbox"/>	
24. REWORK/RETEST ACTIONS TAKEN EDONE - IDC LETTER 24, SA ENS 900273 EXISTING TAT. (HS236-7381) (WAIVER - 171 ATTACHED)		25. LIST ALL PARTS REPLACED		26. RETESTED BY		27. DATE		28. CONTINUATION SHEET USED <input type="checkbox"/>		29. CA RETEST <input type="checkbox"/>	
25. LIST ALL PARTS REPLACED		26. RETESTED BY		27. DATE		28. CONTINUATION SHEET USED <input type="checkbox"/>		29. CA RETEST <input type="checkbox"/>		30. CAUSE AND CORRECTIVE ACTION ECR #64797 GENERATED TO INCLUDE SHIM PROCEDURES IN DP 50647 & T532015-004, S/N 5 & UP - TEST PERSONNEL MADE AWARE OF SENSITIVITY TO SHIMS & TORQUE. REVISION REV B = DP 50647 TO MORE NEARLY OPTIMIZE RELAY MIRROR POINT (TATA APPROX = TATB) SER NO 5 & UP; AS PREVIOUSLY USE AS IS.	
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> MFG. PROC. <input type="checkbox"/> MIRROR ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT		32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION ECR #64797 HS236-2043; ECR #400612		33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE		34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY		35. RESPONSIBLE ENGINEER J. Long		36. DATE 22-11 1310407	
37. RELIABILITY J. Long		38. SPACECRAFT SYSTEM ENGR J. Long		39. CUSTOMER OR SUPPLIER H.A.		40. DATE 11-18-81		41. DATE 11-18-81		42. DATE 11-18-81	

CRITICAL PAGE IS
OF POOR QUALITY

F 1327

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED
18 November 1981

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Company Culver City, CA 90230				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE FL	8. WFR. CODE 82577	9. SYS. DESIG. HS-236	10. DEV/WAIVER NO. W121	<input type="checkbox"/> FURC. TIONAL	<input type="checkbox"/> ALLO- CATED
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIGU- RATION ITEMS AFFECTED	
11. CONFIGURATION TYPE NOMENCLATURE Scan Mirror Assembly				14. DEFECT CLASSIFICATION	
15. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Scan Mirror Assembly				16. (DEFECT CLASSIFICATION)	
17. PART NO. OR TYPE DESIG. 3533002-100				18. RECURRING DEVIATION/WAIVER	
19. EFFECT ON COST/PRICE None				20. EFFECT ON DELIVERY SCHEDULE None	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					
23. DESCRIPTION OF DEVIATION/WAIVER The F-1 SMA exceeded the specifications for turnaround time during acceptance test. The Specification for Turnaround time is 10590 ± 68 usec. Four of the twenty measurements that were made exceeded the specification. The worst case exceedance was 10515.4 usec or 13.2 usec higher than the unit spec allows. Another was 6 usec below the system specification. System Engineering evaluated these effects on system performance and found that they are acceptable. References: IDC HS236-7381, and Failure Report F1327 (Attached).					
24. NEED FOR DEVIATION/WAIVER Resetting the bumper springs would invalidate much of the acceptance test. The cost impact of repeating acceptance tests is not justified since this condition will not affect system performance.					
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER S/N 4 (F-1)				26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE 20 Nov 81	
27. APPROVAL/DISAPPROVAL				28. GOVERNMENT ACTIVITY	
<input type="checkbox"/> APPROVAL RECOMMENDED				<input checked="" type="checkbox"/> APPROVED	
29. GOVERNMENT ACTIVITY NASA GSFC				SIGNATURE James B. Litt 11/23/81	

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY

F1327

HUGHES



INTERDEPARTMENTAL CORRESPONDENCE

TO: B. Marchant
ORG:

CC: HS 236 Distribution

DATE: February 20 1981
REF. 7731.1/2043

HS 236-2043

FROM: Nick J. Constantinides
ORG. 77-31-11

SUBJECT: F-1 SMA Re-entry into the Acceptance Test

BLDG. 5 MAIL STA. B146
LOC. CC EXT. 7601


On February 4th the F-1 Scan Mirror Assembly Acceptance Test was interrupted. A penalty Acceptance Test was introduced so that a SAM Offset Angle variation and a pointing angle discrepancy be investigated. This investigation was completed on February 19th.

An IDC on pertinent information and findings resulting from this investigation will be published at a later time.

On February 20th, the F-1 SMA is scheduled to re-enter the Acceptance Test.

The reduced data, and the aforementioned investigation was conclusive of the fact that both SAM Offset and Pointing angle discrepancy were not related to the SMA's thermal and/or vibrational test.

For this reason the recommendation is made that the F-1 SMA re-enters the Acceptance Test starting with Test Flow Event "H" as shown below.



(N) OVERALL (N, R, L) INPUT VOLTAGES, HIGH, NOMINAL, LOW
DTS = DEVELOPMENT TEST STATION

F-1 SMA Test Flow Event Sequence.

Test flow event I was Vibration and Thermal Cycle. It has been changed to a test that consists of removing and replacing the SMA on the TDS fixture.

It is to be noted that a new scan profile baseline is established by a re-run of Test Flow Event "H" which incorporates new, corrected values for Scan Mirror pointing angles.

Nick J. Constantinides
Systems Engineering

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

F 1327

TO: J. L. Engel CC: Distribution DATE: 1 April 1981
REF: HS236-7381

SUBJECT: F-1 Scan Mirror Acceptance Test Data FROM: W. H. Freudenstein

BLDG. 774 MAIL STA. 79
EXT. 4132

SUMMARY


The test data for the Flight One Model of the Thematic Mapper Scan Mirror Assembly was reviewed on 13 March 1981. The performance of the assembly as validated by the test record is excellent. The turn around time specification is exceeded. This does not pose a problem to system performance at the levels measured.

DISCUSSION

The acceptance test data for the F-1 SMA is summarized in Table I. The scan profile data is excellent and meets the required specifications in all cases. A special procedure was employed for this unit to provide a calibration profile at the end (in addition to the beginning) of the acceptance test sequence. This data showed a maximum nonlinearity of 9.9 μ rad along scan and -1.7 μ rad cross scan. The maximum band-to-band misregistration was determined at this point to be 0.044% compared to a specification of 0.094%. The maximum overlap/underlap is 1.23 μ rad against a requirement of 2.1 μ rad. Along and cross-scan geometric repeatability met specification as did line length repeatability and scan rate.

The specification for turnaround time imposed by the SMA specification had been tightened since the test of the Protoflight unit. The specification for turnaround time imposed on the Flight One SMA was 10590 \pm 68 μ sec. This specification was exceeded in four instances, in the worst case by 13.2 μ sec at 10670.2 μ sec. That number indicates an out of specification condition as far as the SMA spec is concerned. It does not represent an out of spec condition at the system level. One value of turnaround (SAM 2, turnaround B) is out of spec both with regard to the SMA spec and the system spec of 10.515 msec as compared to a system spec of 10.521 msec. Analysis of the impact of this condition indicates a minimal impact on overlap/underlap. No other system level specifications are impacted. The performance underlap/overlap is dominated by other terms to the extent that this condition will not affect system performance.

The F-1 SMA performs well and is acceptable from the view of Systems Engineering for mating with the Flight One Thematic Mapper.


W. H. Freudenstein

/lbg

ORIGINAL PAGE IS
OF POOR QUALITY

F 1327

W. H. Freudenstein to J. L. Engel
HS236-7381
1 April 1981

TABLE I
SCAN PROFILE DATA

TEST SEQUENCE	ALONG SCAN PROFILE (μ RAD)		CROSS SCAN PROFILE (μ RAD)		BAND-TO-BAND REGISTRATION (%)		OVERLAP/UNDERLAP MAX/ μ RAD
	FWD	REV	FWD	REV	FWD	REV	
SME 1	+5.4	+7.4	+0.0	+0.3	0.051	0.039	0.82
	-6.4	-3.9	-1.6	-1.2			
SME 2	+8.7	+10.1	+0.5	+0.9	0.044	0.045	1.23
	-3.1	-1.7	-1.2	-0.7			
TEST SEQUENCE I	ALONG SCAN REPEATABILITY μ RAD RMS		CROSS SCAN REPEATABILITY μ RAD RMS				
	FWD	REV	FWD	REV			
	1.39	0.85	0.56	0.77			
TEST SEQUENCE K	ALONG SCAN REPEATABILITY μ RAD RMS		CROSS SCAN REPEATABILITY μ RAD RMS		LINE LENGTH REPEATABILITY μ SEC/ σ		
	FWD	REV	FWD	REV	FWD	REV	
SME 1	0.62	0.50	0.89	1.13	0.39	0.39	
SME 2	1.26	0.65					
TEST SEQUENCE S	ALONG SCAN REPEATABILITY μ RAD RMS		CROSS SCAN REPEATABILITY μ RAD RMS				
	FWD	REV	FWD	REV			
SME 1	0.85	1.17	0.78	1.13			
SME 2	0.82	0.41	0.65	0.64			
TEST SEQUENCE L	ALONG SCAN REPEATABILITY μ RAD RMS		CROSS SCAN REPEATABILITY μ RAD RMS				
	FWD	REV	FWD	REV			
SME 1	1.57	1.71	0.50	0.61			
SME 2	1.19	0.92	0.55	0.66			

F 1327

W. H. Freudenstein to J. L. Engel
 HS236-7381
 1 April 1981

TABLE I - SCAN PROFILE DATA - Page 2 of 2

ORIGINAL PAGE IS
 OF POOR QUALITY

TEST SEQUENCE N	ALONG SCAN REPEATABILITY μRAD RMS		CROSS SCAN REPEATABILITY μRAD RMS	
	FWD	REV	FWD	REV
	SME 1	1.13	1.29	1.17
SME 2	1.19	1.09	1.06	0.81

TEST SEQUENCE R	ALONG SCAN REPEATABILITY μRAD RMS		CROSS SCAN REPEATABILITY μRAD RMS	
	FWD	REV	FWD	REV
	SME 1	1.18	0.51	0.74
SME 2	0.82	0.54	1.70	0.85

TEST SEQUENCE H-7	ALONG SCAN PROFILE (μRAD)		CROSS SCAN PROFILE (μRAD)		BAND-TO-BAND REGISTRATION (%)		OVERLAP/UNDERLAP /MAX/μRAD
	FWD	REV	FWD	REV	FWD	REV	
	SME 1	+6.0 -5.5	+6.6 -3.9	-0.1 -1.7	+0.2 -1.3	0.044	
SME 2	+9.3 -3.0	+9.9 -1.9	-0.1 -1.7	+0.2 -1.3	0.046	0.042	0.82

TEST SEQUENCE	(μSEC) TURNAROUND TIME			
	SAM 1		SAM 2	
	TTA	TTB	TTA	TTB
K	<u>10658.3</u>	10536.4	10653.3	10526.4
S	10651.9	10542.5	10648.9	10530.8
L	10656.0	10540.1	10647.1	10534.2
N	<u>10653.5</u>	10539.8	<u>10650.6</u>	<u>10527.8</u>
R	<u>10670.2</u>	10524.7	<u>10664.6</u>	<u>10515.4</u>

SPEC. 10590 ± 68 μSEC

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1328

1. PROGRAM NAME AND NUMBER TM HS 236		2. GLA E330		3. MODEL F-1		4. TIME OBSERVED 1500		5. DATE OBSERVED MO 2 DA 4 YR 81		
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAMP <input type="checkbox"/> PART										
EQUIPMENT IDENTIFICATION:										
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER		
8. UNIT F-1 SCAN MIRROR ASSEMBLY		3535002-100		4		HAC				
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAMP <input type="checkbox"/> CARD										
11. OTHER										
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM										
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE AFTER THERMAL <input type="checkbox"/> OTHER										
14. DESCRIPTION OF FAILURE TFE S, L, M: SINE 2; REV SCAN OUT OF SPEC. RMS; AN GEOMETRIC WAS 1.82; 2.07; 2.61; SHOULD BE 2.175 MAX ALSO SMC 1; TFE N. REV SCAN WAS 2.66										
15. TEST PROCEDURE TS 32015-004		PARA 14341		16. ORIGINATOR R. SCHUBINER		ORG 177-21-25		DATE 12-6-81		17. CONTINUATION SHEET USED
18. VERIFICATION AND FAILURE ANALYSIS REF HS 236-2043; TRANSMISSION OF BUMPER SPRING BOUNCES TO SCAN WING & FOLD MIRRORS IS DEPENDENT UPON PROPER INTERFACE SHIM & TORQUE. SHIM WAS 2.5 MILS. SHOULD HAVE BEEN 2.5 MILS. THE SHIMS HAVE BEEN CORRECTED. TORQUE WAS INCORRECT ON INTERFACE BOLTS.										
19. POL. CURING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REPEAT TFE-H; REMOVE & REPLACE SHM; CONTINUE UNIT TEST SPEC. PER FOLLOWING TFE-H PRIOR TO REMOVAL PERFORM ENVISION TEST I SMCUSAMS ONLY, ADRNG & CROSS SCAN ESD. REPEATABILITY (IT 43532)										
20. AUTHORIZATION P.R. [Signature]		ORG 177-32-11		DATE 12-23-81		17. CONTINUATION SHEET USED		24. CA REWORK		
23. REWORK/RETEST ACTION TAKEN TESTED SUCCESSFULLY TO TS 32015-004 Para 4.3.4.1 - DATA SHEET ATTACHED										
26. LIST ALL PARTS REPLACED										
27. REWORK BY										
30. CAUSE AND CORRECTIVE ACTION TEST PERSONNEL CAUTIONED ABOUT SENSITIVITY TO SHIMS & TORQUE. ECR SUBMITTED FOR SHIM PROCEDURE ADDITION TO DP 50647 & TS 32015-004, S/N 5 & UP										
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION ECR 564797; EO 13112										
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT										
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> INDUCED										
36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY										
37. RESPONSIBLE ENGINEER [Signature]		ORG 177-32-11		DATE 12-23-81		38. SPACECRAFT SYSTEM ENGR [Signature]		ORG 177-61		DATE 12-04-81
39. RELIABILITY [Signature]		ORG 51-41		DATE 1-3-81		40. CUSTOMER OR SUPPLIER [Signature]		DATE		

ORIGINAL PAGE IS
OF POOR QUALITY

1329

J 84

ENGINEERING ORDER - REVISIONS / (SEE EP 1-14 FOR INSTRUCTIONS)	HUGHES <small>CORE IDENT 0877</small>	<small>DDO/SPFC NUMBER</small> 7392015-004
<small>DDO/SPEC TITLE</small> ACCEPTANCE TEST SPECIFICATION FOR TM-SMA	<input checked="" type="checkbox"/> <small>EO NO.</small> 13112 <small>IN</small> 1 <small>OF</small> 3 <input type="checkbox"/>	

<small>CONTROL ITEM NAME</small> SMA		<small>SYN/EQPT</small> THEMATIC MAPPER		<small>AUTHORITY</small> ECR 064797 ECR 700102 GLB B	
<small>CONTROL ITEM PART NUMBER</small> 3535072-100	<small>CHANGE EFF</small> 1 & UP	<small>CONTROL ITEM PART NUMBER</small>	<small>CHANGE EFF</small>	<small>CONTROL ITEM PART NUMBER</small>	<small>CHANGE EFF</small>

ZONE	DESCRIPTION
p36 4.3.3.2-1	<p>Add in the Acceptance Test Specification Document DS 32015-004 B, page 36 as Paragraph 4.3.3.2-1 The SMA INSTALLATION-REMOVAL Procedure outlined below:</p> <p>4.3.3.2-1 SMA INSTALLATION & REMOVAL</p> <p>Because of flatness imperfections in fabricating the SMA frame and the sensitivity of the SMA Optics to bending moments, installing and removing the SMA from its interface requires special attention.</p> <p>In Fig. 4.3.3.2.1A the SMA bolts are number coded as per SBRC code and are to be torqued-down to within 30 ± 2 in-lbs in their order of appearance on the table of the figure 4.3.3.2-1A.</p> <p>Insert shims between SMA and interface, using the shim location and thickness established during the SMA assembly. (DP 50667)</p> <p>Verification of torquing, torque Sequence and Shimming is required by QA, and QA stamp is required to be entered on DATA SHEET 4.3.0-4 page 64a . DATA SHEET 4.3.0-4 is attached as part of this EO.</p>
p46 4.3.7	<p>Also add on Page 46 paragraph 4.3.7 the following:</p> <p>4.3.7 Operability Check:</p> <p>Install the SMA on the TDS as per INSTALLATION procedure outlined on page 36 paragraph 4.3.3.2-1. CAUTION:</p>

DISPOSITION OF ITEMS N/A

<small>PREPARED BY</small> <i>[Signature]</i> Nick J. Constantinides	<small>ORG CODE</small> 77-31-11	<small>DATE</small> 2-24-81	<small>ORG CODE</small> 	<small>DATE</small>
<small>CHECKED BY</small> <i>[Signature]</i>	<small>ORG CODE</small> 77-32-70	<small>DATE</small> 8-1-81	<small>ORG CODE</small> 	<small>DATE</small>
<small>APPROVAL</small> <i>[Signature]</i>	<small>ORG CODE</small> 77-32-70	<small>DATE</small> 8-1-82-87	<small>RELEASED BY</small> <i>[Signature]</i>	<small>ORG CODE</small> 77-32-70

ORIGINAL PAGE IS
OF POOR QUALITY

1328

ENGINEERING ORDER - ~~REVISION NOTICE~~
(SEE EP 1.14 FOR INSTRUCTIONS)

HUGHES

CODE IDENT 62577

EO NO. 13112 SH 2 OF 3
 REV. NOTICE


ORG/SPEC NUMBER

TS-32015-004

ZONE

DESCRIPTION

SMA INSTALLATION-REMOVAL CONFIGURATION



NOTE: Torque SMA to TDS fixture
using 30 ± 2 in-lbs. Use
only bolts indicated.

Order Of Torquing	Bolt # As Defined At SBRC
1	17
2	19
3	20
4	18
5	15
6	13
7	14
8	16
9	6
10	12
11	10

FIGURE 4.3.3.2-1A

ORIGINAL PAGE IS
OF POOR QUALITY

1328

ENGINEERING ORDER - REVISION NOTICE

(SEE EP 1.14 FOR INSTRUCTIONS)

HUGHES

CODE IDENT 88877

EO NO. 13112 SH 3 OF 3
 REV NOTICE LTR

DWG/SPEC NUMBER

TS32015-004

ZONE

DESCRIPTION

DATA SHEET 4.3.0 - 4

SSA INSTALLATION AND REMOVAL FROM THE DTS INTERFACE

INSTALLATION

RE-INSTALLATION

Initial

Post-Vibration

Bolt @ _____ QA _____

Bolt @ _____ QA _____

Installation/Removal of SSA was executed by: _____ QA _____

NOTE: _____

SHIMS ARE LOCATED @ BOLT @ _____ QA _____

DATE: _____

ORIGINAL PAGE IS
OF POOR QUALITY

323

TS 32015-004
8 March 1980

DATA SHEET 4.3.6-3
OPERATIONAL PERFORMANCE
ALONG SCAN GEOMETRIC REPEATABILITY

SAM MODE (and calibrated)
SME (1) or (2) 2

Voltage: High , Nom , Low

SMA Designation F-1 ACCEPT TEST S/N 4

IPAR COUNTS:

CALIBRATION

BUMPER A

P2 P3

MID - P1 P4

P3 P8

BUMPER B

SCANNING

SAM OFFSETS, μ RAD


MEAN VALUES

P2 2.6 P3 -1.6
P1 3.1 P4 -1.3
P0 1.7 P5 0.5
LAST P0 1.6

TEMP: T1 T2 T3 T4 T5 T6 T7 T8 T9
28.9 -28.8 7.1
26.1 24.8 25.5 25.9 26.1 27.8 32.6 24.0 24.0
SAM ANGLES USED (MRAD) -67.182 67.168

PWD SMOOTHED PROFILE
FROM TEST RUN NO 2281.1651
REV SMOOTHED PROFILE
MEASURED AVE. PWD
MEASURED AVG. REV

FWD REV
MIDSCAN OFFSET ANGLES, Φ_{11} , Φ_{12}
score 7.28 8.75
sigma 0.88 1.08
MIDSCAN GROUND CORRECTION
score 4.81 1.93



data for smoothed profile: NORM
data for measured/avg profile: NORM/AVG

1.55 Torr Pressure
MIDSCAN PRESSURE CORRECTION 0.78 μ rad

WORST CASE DEVIATIONS OF AVERAGES FROM PROFILES

	SCAN TIME (USEC)	MEAN ERROR	ONE SIGMA	RMS	STDEV	P/F
PWD	0.00	-0.82	0.00	0.82		
REV	46119.36	-0.41	0.36	0.54	01.70	P

© MICROC ADIANS

Run No. 30981.1651

Test Flow Event R-20 eq 6

Comments test no. 20.19 FWD/REV SCAN. 75pts each

QA Stamp

Date 36981

Tested By

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1329

1. PROGRAM NAME AND NUMBER T.M HS 236		2. OLA E330		3. MODEL 4		4. TIME OBSERVED 1500		5. DATE OBSERVED MO 7 4 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION									
7. SUBSYSTEM		NAME		PART NUMBER		I/M		MANUFACTURER	
8. UNIT		F1 SCAN MIRROR ASSEMBLY		3533002-100		4		HAC	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° <input type="checkbox"/> THERMAL VAC _____ HRS. AT _____ ° <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE TFE H <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE CROSS SCAN RMS EXCEEDED SPEC. (-2.0). REQ. (11.5 uadians)									
15. TEST PROCEDURE TS 32015-004 14341 16. ORIGINATOR R. Schaeffer 17. DATE 177-31-75 12-6-81 18. CONTINUATION SHEET USED									
19. VERIFICATION AND FAILURE ANALYSIS TESTS INDICATE POSSIBILITIES OF ±1 RAD ERROR IN LINEAR TERM RG- MOVED FROM CROSS AXIS IFAR PROFILES DUE TO CRAMIS IFAR FIXTURE TEMP. GRADIENTS. EO 13111 APPLIES A TEST IN CALIBRATION TO INSURE TEMP. STABILITY (OF TEST EQUIP). ADDITIONAL VARIATIONS IN LINEAR TERM MAY BE AN INHERENT FLEX POINT PHENOMENON. 19. FAILED ITEM NAME AND PART NUMBER N/A (TEST EQUIP)									
20. FOLLOWING REWORK/TEST REQUIRED <input type="checkbox"/> REWORK/TEST NOT REQUIRED BECAUSE REPEAT TFE H & BEYOND (EXCLUDING TFE J). REF HS 236-2047									
21. AUTHORIZATION R. Schaeffer 22. DATE 177-32-11 Feb 23, 81 23. CONTINUATION SHEET USED									
24. REWORK/TEST ACTION TAKEN RETESTED SUCCESSFULLY. SEE TM SMT F-1 MODEL ACCEPTANCE TEST DATA PKG, 79 357 25. CAUSE 116 26. ACTION 20									
27. LIST ALL PARTS REPLACED									
27. REWORK BY _____ ORG _____ DATE _____ 28. RETESTED BY _____ ORG _____ DATE _____ 29. CONTINUATION SHEET USED									
30. CAUSE AND CORRECTIVE ACTION ECR 864796 EO 13111 ADDS TEST TO INSURE CROSS-AXIS IFAR (TEST EQUIP) THERMAL STABILITY. WITH SOFTWARE CHANGE OF EO 13111 NO FAILURE EXISTS IN CROSS SCAN RMS. (SEE DATA SHEET ATTACHED) 31. PRB CLOSURE 4/9/81									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION EO 13111 TO TS 32015-004 33. CONTINUATION SHEET USED									
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input checked="" type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT									
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE <input type="checkbox"/> INCLD									
36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY									
37. RESPONSIBLE ENGINEER R. Schaeffer ORG 77-32-11 DATE Feb 23 '81 38. SPACECRAFT SYSTEM ENGR J. Campbell ORG 2261 DATE 810807									
39. RELIABILITY R. Schaeffer ORG 51-41 DATE 4-6-81 40. CUSTOMER OR SUPPLIER 11/18 DATE									

4/1/81

ORIGINAL PAGE IS
OF POOR QUALITY

F 1329



HUGHES

INTERDEPARTMENTAL CORRESPONDENCE

TO: B. Marchant
ORG:

CC: HS 236 Distribution

DATE: February 20 1981

REF. 7731.1/2043

HS 236-2043

FROM: Nick J. Constantinides

ORG. 77-31-11

SUBJECT: F-1 SMA Re-entry into the Acceptance Test

BLDG. 5
LOC. CC

MAIL STA. 8146
EXT. 7601


On February 4th the F-1 Scan Mirror Assembly Acceptance Test was interrupted. A penalty Acceptance Test was introduced so that a SAM Offset Angle variation and a pointing angle discrepancy be investigated. This investigation was completed on February 19th.

An IDC on pertinent information and findings resulting from this investigation will be published at a later time.

On February 20th, the F-1 SMA is scheduled to re-enter the Acceptance Test.

The reduced data, and the aforementioned investigation was conclusive of the fact that both SAM Offset and Pointing angle discrepancy were not related to the SMA's thermal and/or vibrational test.

For this reason the recommendation is made that the F-1 SMA re-enters the Acceptance Test starting with Test Flow Event "H" as shown below.



(N) OVERALL (H, N, L) INPUT VOLTAGES, HIGH, NOMINAL, LOW
DTS - DEVELOPMENT TEST STATION

F-1 SMA Test Flow Event Sequence.

Test flow event I was Vibration and Thermal Cycle. It has been changed to a test that consists of removing and replacing the SMA on the TDS fixture.

It is to be noted that a new scan profile baseline is established by a re-run of Test Flow Event "H" which incorporates new, corrected values for Scan Mirror pointing angles.

Nick J. Constantinides
Systems Engineering

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1330

1. PROGRAM NAME AND NUMBER TM HS-236		2. QLA E330		3. MODEL F-1		4. TIME OBSERVED		5. DATE OBSERVED 49-3-81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		L/N		MANUFACTURER	
8. UNIT SMA				3533002-100		4		HAC	
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST PHASE WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROGRESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION		<input checked="" type="checkbox"/> TEMPERATURE 24 ° C		<input type="checkbox"/> THERMAL VAC		HRS. AT _____	
14. DESCRIPTION OF FAILURE Turnaround time exceeded limits 10658.3 usec. Should be less than 10658 usec; Bumper A out of spec .3 usec. TFE K-1 (SME 1) High Voltage; 24°C									
15. TEST PROCEDURE TS32015-004		PARA 4.3.5		16. ORIGINATOR R. Schreiner		ORG 77-37-25		DATE 3-3-81	
17. CONTINUATION SHEET USED <input type="checkbox"/>									
18. VERIFICATION AND FAILURE ANALYSIS Spec limit exceeded verified by McVey & Prince									
19. FAILED ITEM NAME AND PART NUMBER									
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE Turnaround times are stable ie nothing broken or changing with time except for normal wear see IDC and measured values are acceptable to system engineering									
21. AUTHORIZATION ORG _____ DATE _____									
22. CONTINUATION SHEET USED <input type="checkbox"/>									
23. REWORK/RETEST ACTION TAKEN IDC HS236-7381 written by SBRC systems engineering accepts existing turnaround time		24. QA APPROVAL							
25. QA RETEST									
26. LIST ALL PARTS REPLACED									
PART NUMBER	CKT SYM	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT	ANALYSIS NO.			
27. Rework by _____ CAG _____ DATE _____									
28. RETESTED BY _____					29. CONTINUATION SHEET USED <input type="checkbox"/>				
30. CAUSE AND CORRECTIVE ACTION THIS IS NOT A FAILURE UNIT LEVEL OUT OF SPEC. CONDITION HAS BEEN ACCEPTED PER W 121 PER W 121 12/2/81									
31. FRB CLOSURE									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION W 121 (COPY ATTACHED)									
33. CONTINUATION SHEET USED <input type="checkbox"/>									
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE	
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INCIDENT		<input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER JAG		DATE 4/22/81		38. SPACECRAFT SYSTEM ENGR. JAG		DATE 2261		DATE EIC 20	
39. RELIABILITY 1		ORG 57-41		DATE 4-22-81		40. CUSTOMER OR SUPPLIER DATE			

ORIGINAL PAGE IS
OF POOR QUALITY

F1330

REQUEST FOR DEVIATION/WAIVER
(SEE MIL-STD-883 OR 883 FOR INSTRUCTIONS)

DATE PREPARED
18 November 1981

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Hughes Aircraft Company Culver City, CA 90230				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE FL	8. MFR. CODE 82577	7. SYS. DESIG. HS-236	9. DEV/WAIVER NO. W121	<input type="checkbox"/> FUNCTIONAL	<input type="checkbox"/> ALLO-CATED
7. SPECIFICATIONS AFFECTED-TEST PLAN				6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
8. DRAWINGS AFFECTED				<input checked="" type="checkbox"/> PRODUCT	
9. TEST PLAN TS32015-004				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
11. CONFIGURATION ITEM NO/ENCLATURE Scan Mirror Assembly				10. CONTRACT NO. & LINE ITEM NAS 5-24200	
12. EFFECT ON COST/PRICE None				13. EFFECT ON DELIVERY SCHEDULE None	
14. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.				15. EFFECT ON DELIVERY SCHEDULE	

23. DESCRIPTION OF DEVIATION/WAIVER
The F-1 SMA exceeded the specifications for turnaround time during acceptance test. The Specification for Turnaround time is $10590 \pm 68 \mu\text{sec}$. Four of the twenty measurements that were made exceeded the specification. The worst case exceedance was $10515.4 \mu\text{sec}$ or $13.2 \mu\text{sec}$ higher than the unit spec allows. Another was $6 \mu\text{sec}$ below the system specification. System Engineering evaluated these effects on system performance and found that they are acceptable. References: IDC HS236-7381, and Failure Report F1327 (Attached).

24. REED FOR DEVIATION/WAIVER
Resetting the bumper springs would invalidate much of the acceptance test. The cost impact of repeating acceptance tests is not justified since this condition will not affect system performance.

REA *A.B. Marchant*
A.B. Marchant

QA *[Signature]*
RE *[Signature]*
PE *[Signature]*

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER
S/N 4 (F-1)

26. AUTHORITY AUTHORIZING SIGNATURE
[Signature] 20 Nov 81
TITLE
MGR SYSTEMS ENGINEERING

27. APPROVAL/DISAPPROVAL
 APPROVAL RECOMMENDED APPROVED DISAPPROVED

28. GOVERNMENT ACTIVITY
NASA GSFC
SIGNATURE
[Signature] DATE
11/23/81

DD FORM 1694

ORIGINAL PAGE IS
OF POOR QUALITY
DUPLICATE

HUGHES
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1342

1. PROGRAM NAME AND NUMBER HS236 Thematic Mapper		2. GLA E330		3. MODEL FLT		4. TIMES OBSERVED 1300		5. DATE OBSERVED 80 28 80			
6. HARDWARE LEVEL WHICH FAILURE WAS OBSERVED <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART											
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM (SMA) Scan Mirror Assy.		NAME		PART NUMBER		S/N		MANUFACTURER			
8. UNIT				3533002-100							
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY Torquer Assy.				3568911		004					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD											
11. OTHER Subassembly: Housing Assy. Torquer				3568909		004					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM											
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ HRS. AT _____ <input type="checkbox"/> ENCRFP <input type="checkbox"/> VIBRATION _____ AXES FOR _____ MIN TYPE _____ OTHER _____											
14. DESCRIPTION OF FAILURE Torquer Motor fails OP 32015-009 dated 24 April 1978, step 4.7.1 Torquer output test. Torquer motor torqued to mid-position instead of Torquing to the right or left (normal indication)											
15. TEST PROCEDURE pp32015-009		PARA 4.7.1		16. ORIGINATOR A. G. Holer		28 15/25		DATE 7-17			
18. VERIFICATION AND FAILURE ANALYSIS Coil Assy. 3568908-2 was found incorrectly indexed causing a Phase Shift. <i>No OVERSTRESS RESULTED FROM THIS CONDITION.</i> <i>Coils were applied with unit in DESIRED CONSTRUCTION.</i>											
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE Remove & Replace coils per print											
20. AUTHORIZATION R. L. Coon		ORG 177/15		DATE 7/30/79		21. CONTINUATION SHEET USED					
22. REWORK/RETEST ACTION TAKEN Removed and replaced coils per print and retested per DP 3205-009 PARA 4.5.1 & 4.7.1											
23. LIST ALL PARTS REPLACED											
PART NUMBER		CKT SYM	PART LOT NO.	DATE CODE	WFR	PROBABLE DEFECT		ANALYSIS NO.			
3568908-2		\$	2285								
27. REPORT BY O.D.		ORG 173-22		DATE 7-25-79		28. RETESTED BY McVey		ORG 177-32			
29. CAUSE OF CORRECTIVE ACTION IMPROPER USE OF ASSY TOOLING AND BAD JUDGEMENT ON PART OF QUALITY SUPERVISION		33. PRO CLOSURE SEE CAR 63109 REF FR F1302									
34. DOCUMENT IMPLEMENTING CORRECTIVE ACTION CAR 63109											
35. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST PROC. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SETUP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT											
36. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> NO FAILURE		37. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY									
37. RESPONSIBLE ENGINEER A. G. Holer		ORG 177-15		DATE 12-3-80		38. SPACECRAFT SYSTEM ENGR M. A. ...		ORG 122-61			
39. RELIABILITY L. ...		ORG 177-41		DATE 7-26-81		40. CUSTOMER OR SUPPLIER 6.5		DATE 2/3/81			

3/17/81

ORIGINAL PAGE IS
OF POOR QUALITY

JFR P-1342

CORRECTIVE ACTION REQUEST

63109

SEE REVERSE SIDE FOR COMPLETION INSTRUCTIONS

NAME SOURCE CODE ADDRESS/MAIL STATION PHONE EXT.

0. E.A. Anzivino 77-03 12/7/79 4105

1. FROM: R.L. Coon 77-15 12/1/04 7433

2. REFERENCE: AT/CA 42133, Same Subject

GLA NO.

8. PLEASE TAKE THE NECESSARY ACTION TO CORRECT THE CAUSE OF THE FOLLOWING CONDITION(S):

PROBLEM DESCRIPTION:

1. Reply to noted CRT was unsatisfactory, to properly dispose of related information report numbers F1302 and F1304.
2. Dimensions on the drawings are clearly within the requirements of the Contract. (See 2.3, paragraph 2.3 and 3.0 paragraph 3.0 h.)
3. Documentation that storage was not used is required (see para 1.0.3) and OIS required use of same.

SIGNATURE

DATE

BLOK

MAIL STATION

7. CAUSE:

1. "Corrective Action Request 63109" to E. A. Anzivino from A. J. Rodenbucker Ref. 7934/681 dated 8 November 1979.
2. "Corrective Action Request 63109" to A. J. Rodenbucker from R. D. Gourlay Ref. 7631.20/323 dated 30 October 1979.

8. THE FOLLOWING CORRECTIVE MEASURES HAVE BEEN TAKEN TO ELIMINATE THE CAUSE OF THE CONDITION(S) NOTED ABOVE EFFECTIVELY:

(LOT, SERIAL, DATE, OTHER)

9. REMEDY:

1. "Corrective Action Request 63109" to E. A. Anzivino from A. J. Rodenbucker Ref. 7934/681 dated 8 November 1979.
2. "Corrective Action Request 63109" to A. J. Rodenbucker from R. D. Gourlay Ref. 7631.20/323 dated 30 October 1979.

10. SIGNED:

DATE

11. CONCLUSION - SATISFACTORY CORRECTION HAS BEEN EFFECTED - YES NO

12. FOLLOW UP REQUIRED:

13. SUSPENSE DATE:

14. SIGNED:

DATE

(ORIGINATOR)

ORIGINATOR

RECIPIENT

ORIGINATOR

F 1342



INTERDEPARTMENTAL CORRESPONDENCE

TO: E. A. Anzivino
ORG: 77-07

CC:

DATE: 8 November 1979
REF: 7934/681

SUBJECT: Corrective Action
Request 63109

ORIGINAL PAGE IS
OF POOR QUALITY

FROM: A. J. Rodenbucher
ORG: 79-34

BLDG. T4005 MAIL STA. W750
LOC. CC EXT. 7898

After extensive investigation the following was found:

Traceability for the 3568902, S/N 4 housing could not be established. The fact that the 3568902 housing is not physically marked until the 3568911 assembly made obtaining history on the housing impossible.

Assuming that the 3568902 housing for torquer assembly, S/N 4 is in fact the housing manufactured as S/N 4, it is reasonable to surmise from the evidence at hand that the tooling was improperly used.

The personnel currently assigned to the involved activity have been reformed by their department manager on the importance of strictly adhering to the operation instruction sheet and applicable drawings and specifications. Effective date of corrective action is 30 October 1979.

A judgement error was made by Quality Supervision in assessing by-passed assembly and inspection operations. Subject Supervisor has been instructed to evaluate unusual conditions in assembly/inspection operations more thoroughly. Effective date of corrective action is 8 November 1979.

A. J. Rodenbucher
A. J. Rodenbucher, Head
Engineering Divisions Support
Product Assurance
Division 79

AJR:maj

F1342



INTERDEPARTMENTAL CORRESPONDENCE

TO: A. Rodenbucher ✓
ORG: 79-30

cc: E. Shimbel

DATE: 30 October 1979
REF. 7631.20/323

SUBJECT: Corrective Action
Request 63109

FROM: R. D. Gourlay
ORG. 76-31

BLDG. 6 MAIL STA. D163
LOC. CC EXT. 21512

All the involved personnel in this department were interviewed regarding the fabrication of the discrepant 3568911 torquer assembly. Because of the elapsed time and transfer of some involved personnel, a complete picture of the assembly process for serial #4 could not be pieced together. It is reasonable to surmise from the evidence at hand that the tooling was improperly used.

The personnel currently assigned to the involved activity have been reformed on the importance of strictly adhering to the Operation Instruction Sheet and applicable drawings and specifications.


R. D. Gourlay, Manager
Components Development Department

RDG/gr

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1352

1. PROGRAM NAME AND NUMBER HS236-TPR		2. CLA E330		3. MODEL F-1		4. TIME OBSERVED 5:00		5. DATE OBSERVED 7 20 79			
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input checked="" type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER			
8. UNIT											
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD											
11. OTHER PART - MIRROR 3564899 5 AOC											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SCATTER TEST											
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE											
14. DESCRIPTION OF FAILURE SCATTER DOES NOT MEET REQ'S OF NOTE (19) OF DWG (0.2%) - ACTUAL SCATTER MEASUREMENT WAS 0.4% IN ONE AXIS AND 0.32% IN OTHER 0.32% (8m/12)											
15. TEST PROCEDURE		16. ORIGINATOR EW. GASSETT		ORG 77-45		DATE 7/20/79		17. CONTINUATION SHEET USED			
18. VERIFICATION AND FAILURE ANALYSIS VERIFIED BY TEST - SEE ATTACHED SHEETS AND QPHR ECC 60258											
19. FAILED ITEM NAME AND PART NUMBER 3568899, MIRROR											
20. FOLLOWING REWORK/TEST REQUIRED REWORK/TEST NOT REQUIRED BECAUSE MIRROR MUST BE REPOLISHED											
21. AUTHORIZED BY <i>[Signature]</i>		ORG 77-45		DATE 7/27/79		22. CONTINUATION SHEET USED					
23. REWORK/TEST ACTION TAKEN RETURN TO VENDOR FOR REWORK SEE FR 1305 AND NCMR 316897 AND SCAR 63891								24. QA RWORK			
								25. QA RTEST			
26. LIST ALL PARTS REPLACED											
PART NUMBER		CMT SYN		PART LOT NO.		DATE CODE		MFR			
								PROBABLE DEFECT			
								ANALYSIS NO.			
27. REWORK BY											
ORG		DATE		28. RETESTED BY		ORG		DATE			
								29. CONTINUATION SHEET USED			
30. CAUSE AND CORRECTIVE ACTION INADEQUATE POLISHING - (SEE HPM 23)											
CORRECTIVE ACTION - SCATTERING TESTS TO BE PERFORMED PRIOR TO MIRROR ACCEPTANCE FROM AOC. ALSO SPEC REVISED TO 0.4%, EOG4388								33. FRB CLOSURE <i>[Signature]</i> 4/16/81			
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION 100-64388 HS236-1654											
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT											
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		37. RESPONSIBLE ENGINEER GP [Signature]		DATE 12-3-80		38. SPACECRAFT SYSTEM ENGR. W.A. [Signature]		DATE 12/11/80	
39. RELIABILITY L. [Signature]		ORG 51 41		DATE 12-11-80		40. CUSTOMER OR SUPPLIER 46		DATE			

4/10/81

ORIGINAL PAGE IS
OF POOR QUALITY

~~F 1355~~
F 1352

SUPPLIER CORRECTIVE ACTION REQUEST

63891

(INSTRUCTIONS ON BACK)

SUPPLIER NO. 50762 DATE 12-7-79

SUPPLIER APPLIED OPTICS CENTER PART NO. 90-3568899 S/N. 095

ADDRESS 10 "B" STREET PART NAME SCAN MIRROR

BURLINGTON, MA. P. O. NO. 04-497378-FDA

ATTENTION QUALITY ASSURANCE MANAGER REC'G. RCPT. NO. _____

PREVIOUS CORRECTIVE ACTION REQUESTS _____ PROGRAM I. D. NO. E330

QTY RCVD. 1 LOT SIZE 1 QTY INSP. 1 QTY DISCREPANT _____

QTY SUSPENDED 1 SUSPENSION/REJECTION DOCUMENT NO. HCMR 316897

1. DISCREPANCIES:

MIRROR SCATTER DOES NOT MEET REQUIREMENTS OF NOTE 12 OF DWG. AND E.O. 70351.
 SCATTER IS 1.8%; SHOULD BE \leq 0.2%.
 NICKEL PLATING ON BACK LIFTED ONE PLACE.

PLEASE REVIEW YOUR PROCESSES AND PROCEDURES TO DETERMINE THE CAUSE AND ADVISE HQC OF MEASURES TAKEN TO PREVENT RECURRENCES. INDICATE EFFECTIVITY DATE.

THE PERSON DIRECTLY RESPONSIBLE FOR QUALITY MUST SIGN THIS SCAR.

L. M. OLSEN *L.M. Olsen* 12/19

 QUAL./PRD. ASSURANCE DATE

THE DISCREPANCIES NOTED ABOVE:

- A CONCERN ITEMS THAT HAVE RECEIVED GOVERNMENT SOURCE INSPECTION AT YOUR PLANT.
- B CONCERN PARTS THAT HAVE BEEN REVIEWED AND SUSPENDED BY QUALITY. MATERIAL BEING RETURNED MATERIAL NOT BEING RETURNED
- C REQUIRE THAT YOU TAKE IMMEDIATE CORRECTIVE ACTION TO PRECLUDE FUTURE NON-CONFORMING DELIVERIES.
- D REPLY IS TO BE SUBMITTED NOT LATER THAN _____

TO: HUGHES AIRCRAFT COMPANY ADDRESS: CENTINELA & TEALE, CULVER CITY, CA. 9

BUYER R. HALEY

DEPT. 70-21 BLDG. 17 M/S. J129

E SEE OTHER COMMENTS ON ATTACHED PAGE

2. SUPPLIER REPLY (See reverse side for instructions)

IF REQUIRED - SEE 2A ABOVE

CORRECTIVE ACTION EFFECTIVITY _____

GOVT REPRESENTATIVE'S SIGNATURE _____ DATE _____	SIGNATURE _____ TITLE _____ DATE _____
--	--

TO BE COMPLETED BY HUGHES QUALITY/PRODUCT ASSURANCE

ACTION SATISFACTORY	YES	NO	FURTHER FOLLOW-UP REQUIRED	YES	NO	NEW SCAR NO. _____
SIGNATURE _____			SIGNATURE _____			
DATE _____			DATE _____			


HUGHES


NONCONFORMING MATERIAL REPORT (NCMR)

NO. 5
DATE 11-6-9
PAGE 1 OF 1

PROGRAM ID THEMATIC MAPPER PRD/PRG E330-EAA-21-00

PART NO. 90-3568899		S/N 005	ENG. CHANGES A 70351		NOMENCLATURE SCAN MIRROR	
WORK ORDER DOC NO.		LOT SIZE	QTY. SUSP. 1	SUSPENDED IN TEST (ASSY)	HARDWARE I.D. NO. 75 - 35 - 22	REF. DOCUMENTS QCHR CC 60258
SUPPLIER APPLIED OPTICS CENTER			DIV. OR LOCATION BURLINGTON, MA.		SUPPLIER CODE 50762	P.O. NO. 04-497378-FDA
				ITEM NO. 1	R.R. NO.	

ITEM NO.	QTY INSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR	M.R. LEVEL	CODE
1	-	1	MIRROR SCATTER DOES MEET REQUIREMENTS OF (19) OF DWG AND EO 70351. SCATTER IS 1.8%; SHOULD BE $\leq 0.2\%$.	V	0	PR	F
2	-	1	NICKEL PLATING ON BACK SIDE LIFTED TWO (2) PLACES. LIFTED PLATING: 	V	0	PR	F

ORIGINAL BY <i>E.M. Olsen</i>	DATE 11/6/9	QUALITY <i>E.M. Olsen</i>	DATE 11/6/9	ENGINEERING	DATE
ITEM NO. 1	DISP. CODE F	DISPOSITION/INSTRUCTIONS RETURN TO VENDOR FOR REWORK TO B/P REQUIREMENTS.			STAMP
SHIP TO: APPLIED OPTICS CENTER				ORIGINAL PAGE IS OF POOR QUALITY	
					

ENGINEERING	DATE	QUALITY	DATE	CUSTOMER	DATE
ITEM NO.	CAUSE OF NONCONFORMANCE		RESULTS OF CORRECTIVE ACTION INVESTIGATION		CORRECTIVE ACTION
<p>12-6-9 SCAR # 63891</p> <p><i>E.M. Olsen</i></p>					
SIGNATURE			DATE		
RESPONSIBILITY	DEBIT VENDOR	DISP. CODE	VENDOR PACKING SHEET	QTY. R.T.V.	QTY. SCRAP
VENDOR HAC	YES NO	F	-	1	-
BUYER'S SIGNATURE <i>R. L. Haley</i>				DATE 11/6/9	COPY

INTERDEPARTMENTAL CORRESPONDENCE



F 1352

TO: E. W. Gossett

CC: Data Bank (3)

DATE: 3 December 1979

ORG:

REF. 771510/007

HS236-1654

SUBJECT: Scattering Tests for
TM Mirrors

FROM: R.L. Coon

ORG. 77-15-18

BLDG. 12

MAIL STA. V104

LOC. CC

EXT. 7433

REP. TFR # P-1352

Due to the high scattering exhibited by Mirror S/N 5,
all mirrors must be measured at HAC for scattering and
accepted prior to coating at Denton Vacuum.

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1353

F-100 5-5-81

1. PROGRAM NAME AND NUMBER H5 236-TA		2. CLA E330	3. MODEL 5A	4. TIME OBSERVED	5. DATE OBSERVED 10 8 79	NO	QA
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:							
7. SUBSYSTEM		NAME		PART NUMBER	S/N	MANUFACTURER	
8. UNIT							
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY				3568900	5	HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
11. OTHER							
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/>			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMPERATURE AXIS FOR _____ MIN TYPE _____	<input type="checkbox"/> THERMAL VAC	HRS. AT _____ °		<input type="checkbox"/> OTHER
14. DESCRIPTION OF FAILURE WHEN "SCAPER CLAD" STRIPPABLE PROTECTIVE COATING PER HWS 16-1768 WAS STRIPPED FROM FRONT MIRROR SURFACE, COATING WAS DAMAGED							
15. TEST PROCEDURE NONE		16. ORIGINATOR E. W. GOSSET	ORG 199-05110/9/00	DATE 10/8/79	17. CONTINUATION SHEET USED <input type="checkbox"/>		
18. VERIFICATION AND FAILURE ANALYSIS Para. 4 of H236-1640 verifies that coating damage was noted during week of October 1, 1979.							
19. FAILED ITEM NAME AND PART NUMBER SCAN MIRROR 90-3568899							
20. FOLLOWING REWORK/RETEST REQUIRED Returned to vendor - See NCMR 316897 - RETESTED SUCCESSFULLY (SEE FR F1303, ATTACHED)							
21. AUTHORIZATION		ORG	DATE	22. CONTINUATION SHEET USED <input type="checkbox"/>			
23. REWORK/RETEST ACTION TAKEN Rework to print requirements of DWG 90-3568899						24. QA RECORD <input type="checkbox"/>	
						25. QA RETEST <input type="checkbox"/>	
26. LIST ALL PARTS REPLACED							
PART NUMBER	CKT SYN	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT	ANALYSIS NO.	
27. REWORK BY		ORG	DATE	28. RETESTED BY	ORG	DATE	29. CONTINUATION SHEET USED <input type="checkbox"/>
30. CAUSE AND CORRECTIVE ACTION Cause unknown. Supplier corrective Action. Request #63897 from Hughes Aircraft System. REPLATED AND REPOLISHED (SEE FR F1305, ATTACHED)							
						33. FRB CLOSURE 	
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION NCMR 316897		31. CONTINUATION SHEET USED <input type="checkbox"/>					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	35. UNKNOWN DEFECT CODE <input type="checkbox"/>		
36. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		37. MINOR SAFETY <input checked="" type="checkbox"/>		
37. RESPONSIBLE ENGINEER [Signature]		ORG 17-15	DATE 4/27/81	38. SPACECRAFT SYSTEM ENGR. [Signature]		ORG 2261	DATE 1/31/81
39. RELIABILITY [Signature]		ORG 51-41	DATE 5-1-81	40. CUSTOMER OR SUPPLIER [Signature]		DATE 5/6/81	

NONCONFORMING MATERIAL REPORT (NCMR)

NO. 11-1
 DATE 11-1
 PAGE 1 OF 1

PROGRAM ID THEMATIC MAPPER PRD/PRG E330-EAA-21-00

NO 90-3568899 S/N 005 ENG. CHANGES A 70351 NOMENCLATURE SCAN MIRROR

ORDER DOC NO. ----- LOT SIZE ----- QTY. SUSP. 1 SUSPENDED IN TEST (ASSY) HARDWARE I.D. NO. 75 - 35 - 22 REF. DOCUMENTS QCHR CC 60258

CLIENT APPLIED OPTICS CENTER DIV. OR LOCATION BURLINGTON, MA. SUPPLIER CODE 50762 P.O. NO. 04-497378-FDA ITEM NO. 1 R.R. NO. -----

QTY. SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR	M.R. LEVEL	COC
- 1	MIRROR SCATTER DOES MEET REQUIREMENTS OF <u>(19)</u> OF DWG AND EO 70351. SCATTER IS 1.8%; SHOULD BE $\leq 0.2\%$.	V	0	PR	F
- 1	NICKEL PLATING ON BACK SIDE LISTED TWO (2) PLACES. LIFTED PLATING:	V	0	PR	F

INSPECTOR J.M. O'Leary DATE 11/6/19 QUALITY J.M. O'Leary DATE 11/6/19 ENGINEERING ----- DATE -----

DISP. CODE F DISPOSITION/INSTRUCTIONS RETURN TO VENDOR FOR REWORK TO B/P REQUIREMENTS. SHIP TO: APPLIED OPTICS CENTER

Stamp: ORIGINAL PAGE IS OF POOR QUALITY

VEERING ----- DATE ----- QUALITY ----- DATE ----- CUSTOMER ----- DATE -----

CAUSE OF NONCONFORMANCE	RESULTS OF CORRECTIVE ACTION INVESTIGATION	CORRECTIVE ACTION
12-6-9 SCAR # 63891		

DATE 11/6/19 SIGNATURE J.M. O'Leary DATE 11/6/19

BUYER'S SIGNATURE [Signature] DATE 11/6/19 COPY -----

LIABILITY DEBIT VENDOR NO DISP. CODE F VENDOR PACKING SHEET ----- QTY. R.T.V. 1 QTY. SCRAP -----

ORIGINAL PAGE IS
OF POOR QUALITY

F 1353



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1305

1. PROGRAM NAME AND NUMBER <i>H5236-TM</i>		2. GLA <i>E331</i>	3. MODEL <i>A-1</i>	4. TIME OBSERVED <i>1630</i>	5. DATE OBSERVED <i>79 25 80</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <i>MIRROR</i>				<i>3568849</i>	<i>5</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> OTHER <i>PERIOD TO ASSY FOR EX</i>					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE _____ ° _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ MIN TYPE _____ OTHER _____					
14. DESCRIPTION OF FAILURE <i>NICKEL PLATING ON REAR SURFACE LISTED 2 PLACES; NEAR CORNER CURB HOLD & AT EDGE NEAR MAJOR AXIS</i>					
15. TEST PROCEDURE		PARA	16. ORIGINATOR <i>F.W. GOSSETT</i>	ORG <i>179-45</i>	DATE <i>1/26/80</i>
18. VERIFICATION AND FAILURE ANALYSIS <i>ACTUALLY ONLY ONE LISTED AREA NEAR CORNER CURB HOLD</i>		17. CONTINUATION SHEET USED			
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <i>MIRROR WILL BE RETURNED TO VENDOR FOR REWORK AFTER I'VE CLEANED (ALSO SEE REP #1352)</i>		18. FAILED ITEM NAME AND PART NUMBER <i>MIRROR P/N 3568800</i>			
20. REWORK/RETEST ACTION TAKEN <i>VENDOR TO STRIP, REPLATE & REFINISH RETURNED TO VENDOR BY W.D. ADAMS - REPLATED AND REFINISHED RETESTED ALL RECORDS</i>		21. AUTHORITY <i>W.D. Adams</i>	ORG <i>179-45</i>	DATE <i>1/21/80</i>	22. CONTINUATION SHEET USED
23. LIST ALL PARTS REPLACED					
PART NUMBER	QTY	SYM	PART LOT NO.	DATE CODE	MFR
24. CAUSE AND CORRECTIVE ACTION <i>IMPROPER CLEANING BY VENDOR. RETURN TO VENDOR REF. NCMR 316897</i>		25. RETESTED BY		ORG	DATE
26. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>NCMR 316897</i>		27. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		28. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
29. RESPONSIBLE ENGINEER <i>A.S. Mendenhall</i>		ORG <i>177-15</i>	DATE <i>12-3-80</i>	30. SPACECRAFT SYSTEM ENGR <i>M.A. Reinhardt</i>	
31. RELIABILITY		ORG <i>177-15</i>	DATE <i>1-11-80</i>	32. CUSTOMER OR SUPPLIER <i>3/1/81</i>	

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8392

1. PROGRAM NAME AND NUMBER T.M. 1162		2. GLA	3. MODEL 003 (F)	4. TIME OBSERVED 1330	5. DATE OBSERVED MO 2 DA 20 YR 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT		SCAN MIRROR ASSY	3533002	-100	HAC/CC
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		TDP ASSY	51065	003	SBR
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RR		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR _____ MIN TYPE _____	<input type="checkbox"/> THERMAL VAC	HRS AT _____ <input type="checkbox"/> OTHER
14. DESCRIPTION OF FAILURE POWER TO SMA APPLIED, PER TP 32015-301; SMA DID NOT OPERATE. INVESTIGATION SHOWED SMA EO BE TAPED TO BUMPER. GREEN LED DID NOT LIGHT.					
15. TEST PROCEDURE TP 32015-301		PARA 5.1	16. ORIGINATOR F.Y. NICOLAS	17. CONTINUATION SHEET USED 22-71 2-20-82	
18. VERIFICATION AND FAILURE ANALYSIS No overstresses occurred. Power was not available to the SMA until EO 4160 A repair installed in SMA control console.					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest not required because INSTALL EO 4160A - MODIFICATIONS TO SMA CONTROL CONSOLE					
20. REWORK/RETEST ACTION TAKEN EO INSTALLED		21. AUTHORIZATION	ORG	DATE	22. CONTINUATION SHEET USED
23. LIST ALL PARTS REPLACED		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
24. QA REQUEST					
25. REWORK BY		ORG	DATE	26. RETESTED BY	ORG
27. CAUSE AND CORRECTIVE ACTION TEST SET DESIGN PROBLEM INHIBITED OPERATION AND LED INDICATED EO 4160 CORRECT CONDITION.		28. CONTINUATION SHEET USED			
29. FAILURE TYPE DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED	<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	30. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
31. RESPONSIBLE ENGINEER R. Williams		ORG	DATE	32. CUSTOMER OR SUPPLIER	DATE
33. RELIABILITY		ORG	DATE	34. CONTINUATION SHEET USED	

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.3
POWER SUPPLY

2.3.1

ORIGINAL PAGE IS
OF POOR QUALITY

Section 2.3.1

Power Supply

Performance Data

The acceptance performance (test) data for the Power Supply
is contained in Appendix C (Vol. IV, Part C).

ORIGINAL PAGE IS
OF POOR QUALITY

2.3.2

2.3.2
Acceptance Data

2.3.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.3.2.1
Configuration Lists

AS-BUILT CONFIGURATION LIST

POWER SUPPLY ASSEMBLY
50869 S/N 004

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
01	50869	ASSY, POWER SUPPLY	D 2015A 2039A D030 D068 W074 W092 W093 W101	D 2015A 2039A D030 D068 W074 W092 W093 W101	D 2015A 2039A D030 D068 W074 W092 W093 W101	004
02	53319	CHASSIS-POWER SUPPLY	B 9090	B 9090	B 9090	N/A
03	53669	COVER, BOTTOM	A 9471	A 9471	A 9471	N/A
03	53670	COVER, TOP	A 9474 9893 2025A	A 9474 9893 2025A	A 9474 9893 2025A	N/A
02	53664	BUS BAR	A 9071	A 9071	A 9071	2
02	53308	PRINTED WIRING ASSY	A 9060 9069 9465 9485 #D123 D124	A 9060 9069 9465 9485 D124	A 9060 9069 9465 9485 #D123 D124	3,4
02	51566	PRINTED WIRING ASSY	A 8527 9055 9080 9097 2020A #D123 D124	A 8527 9055 9080 9097 2020A D124	A 8527 9055 9080 9097 2020A #D123 D124	3,4

ORIGINAL PAGE IS
OF POOR QUALITY

#D123 was cancelled and replaced by
D124

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	51578	PRINTED WIRING ASSY	B 2002A #D123 D124	B 2002A D124	B 2002A #D123 D124	2
02	53555	PRINTED WIRING ASSY	C 9881 D069 #D123 D124	C 9881 D069 D124	C 9881 D069 #D123 D124	2
02	51570	PRINTED WIRING ASSY	C D069 #D123 D124 2049A	C D069 D124 2049A	C D069 #D123 D124 2049A	3,4
02	52113	PRINTED WIRING ASSY	B 1403A #D123 D124	B 1403A D124	B 1403A #D123 D124	2
02	51574	PRINTED WIRING ASSY	C #D123 D124	C D124	C #D123 D124	4,5,6
02	52976	PRINTED WIRING ASSY	A 6998 9079 9467 #D123 D124	A 6998 9079 9467 D124	A 6998 9079 9467 #D123 D124	2
03	51562	PRINTED WIRING ASSY	D D069 #D123 D124	D D069 D124	D D069 #D123 D124	3,4
02	51594	PRINTED WIRING ASSY	B D069 #D123 D124	B D069 D124	B D069 #D123 D124	2
02	51627	FILTER ASSY	A 8891 9479 1408A 1999A	A 8891 9479 1408A 1999A	A 8891 9479 1408A 1999A	2

ORIGINAL PAGE IS OF POOR QUALITY

TRD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPY. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	51656	FILTER ASSY	A 9473 9480 1409A 1998A	A 9473 9480 1409A 1998A	A 9473 9480 1409A 1998A	1
02	51611	INPUT CHOKE	A 9049 1407A	A 9049 1407A	A 9049 1407A	3,4
02	51590	PRINTED WIRING ASSY	E D059 #D123 D124 W078 +W103 W104	E D069 D124 W078 W104	E D069 #D123 D124 W078 +W103 W104	2
02	51519	PRINTED WIRING ASSY	F 2042A 2043A 2047A 2048A D069 #D123 D124 W078 +W103 W104 2052A	F 2042A 2043A 2047A 2048A D069 D124 W078 W104 2052A	F 2042A 2043A 2047A 2048A D069 #D123 D124 W078 +W103 W104 2052A	2
02	52951	TRANSISTOR	A 1414A	A 1414A	A 1414A	N/A
02	53672	XSTR MTG BRACKET	A	A	A	N/A
03	53297	TERMINAL STRIP	A	A	A	N/A
02	51651	RETAINER, PCB	A	A	A	N/A
02	52901	INSULATOR, SCREW	A	A	A	N/A
02	53298	TERMINAL, STANDOFF	A	A	A	N/A
02	53678	CARD GUIDE, PWB	A 9489	A 9489	A 9489	N/A
02	53679	BACKUP SPRING	B	B	B	N/A

U-3

ORIGINAL PAGE IS
OF POOR QUALITY

#D123 was cancelled and replaced by D124
+W103 was cancelled and replaced by W104

THD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	53666	WIRE LIST, THEMATIC	D D102 W079	D D102 W079	D D102 W079	N/A
02	53299	SHIELD ASSY	B D068	B D068	B D068	2
02	51615	PWB ASSY	A 8371 9082 #D123 D124	A 8371 9082 D124	A 8371 9082 #D123 D124	2
02	53561	REGULATOR ASSY	A 8362 9068 9483 2006A	A 8362 9068 9483 2006A	A 8362 9068 9483 2006A	2
02	53668	CAPACITOR PLATE ASSY	A 9066 2010A	A 9066 2010A	A 9066 2010A	3,4
02	53674	CHOKE ASSY	A	A	A	3,4
02	53575	INDUCTOR ASSY	A	A	A	3,4
02	53311	XFMR MODULE ASSY	B 1410A	B 1410A	B 1410A	4,5
02	52531	TRANSFORMER ASSY	B 9470	B 9470	B 9470	3,4
02	53316	XFMR MODULE ASSY-MUX	B 1412A	B 1412A	B 1412A	4,5
02	53563	TRANSFORMER ASSY	A 8370 9478	A 8370 9478	A 8370 9478	3,4

ORIGINAL PAGE IS
OF POOR QUALITY#D123 was cancelled and replaced by
D124

IID LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	53558	POWER SUPPLY	A	A	A	N/A
03	51655	SCHEMATIC DIAGRAM	D 1415A 2007A 2041A	D 1415A 2007A 2041A	D 1415A 2007A 2041A	N/A
--	3169178	LUG, TERMINAL	- 59211	- 59211	- 59211	N/A

W.D. Collins
QUALITY ASSURANCE

2-9-82
DATE

R.R. Jones
CONFIGURATION/DATA MANAGEMENT

2-9-82
DATE

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

POWER SUPPLY

Listing of Liens

ORIGINAL PAGE IS
OF POOR QUALITY

POWER SUPPLY

F/N 50869

FLIGHT

Failure Report Number	
Open	Closed
F3868	F1035
S8102	F1036
	F1439
	F3864
	F3865
	F3866
	F3867
	F4831
	F4832
	F4833
	F4834
	F4835
	F4836
	F4837

Deviations	Waivers
	W-138

POWER SUPPLY

ORIGINAL PAGE IS
OF POOR QUALITY

P/N 50869

FLIGHT

PROTOFLIGHT

ENGINEER

Failure Report No.		Failure Report No.		Failure Report No.	
Open	Closed	Open	Closed	Open	Closed
F3868	F1035		F0675		F0538
S8102	F1036		F1030		F0555
	F1439		F1033		F2754
	F3864		F1034		S8094
	F3865		F1437		S8095
	F3866		F1438		
	F3867		F1440		
	F4831		F1441		
	F4832		F1442		
	F4833		F1973		
	F4834		F1974		
	F4835		F1975		
	F4836		F1976		
	F4837		F1977		
			F1978		
			F1979		
			F1980		
			F1982		
			F2690		
			F2740		
			F3881		

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1035

1 PROGRAM NAME AND CLASSIFICATION HS-236		2 CLA E330	3 MODEL PLT	4 TIME OBSERVED -	5 DATE OBSERVED 3/23/81
6 HAZARD LEVEL (HIGHEST FAILURE MODE OBSERVED) <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECAS <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7 SUBSYSTEM		PART NUMBER		1/3	MANUFACTURER
8 UNIT		51619		002	HAC
9 <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY MANUAL SWITCHER					
10 <input type="checkbox"/> MODULE <input type="checkbox"/> MECAS <input type="checkbox"/> CARD					
11 OTHER					
12 TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> PROCESSES <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13 ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> H2S AT <input type="checkbox"/> OTHER <input type="checkbox"/> STATIC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> VHM <input type="checkbox"/> TYPG					
14 DESCRIPTION OF FAILURE SUBASSY FAILED OVER CURRENT SHUT MANUAL PER TS 16518, P 5.11.6.1. UNDERCURRENT CIRCUIT FAILED TO FUNCTION/OIL FAILED TO TURN ON. INVESTIGATION REVEALED DIODE CR 77 INSTALLED REVERSE.					
15 TEST PROCEDURE TS-16518		16 PART NO. 51161	17 ORIGINATOR G. BEVON	18 JRG 413723	19 DATE 3/26/81
18 VERIFICATION AND FAILURE ANALYSIS VERIFIED DIODE CR77 INSTALLED REVERSE PREVENTING TRANSISTOR OIL OPERATION. SCHEMATIC CORRECT, ASSY DWG INCORRECT. FAILURE ANALYSIS INDICATES NO OVERSTRESS CONDITION CREATED.					
19 ENGINEERING EVALUATION ATTACHED					
20 <input checked="" type="checkbox"/> ALL OTHERS POWER/ACTIVITY REQUIRED FOR TEST NOT REQUIRED BECAUSE REUSE DWG 51619 (REV F) TO SHOW DIODE CR77 INSTALLED PER SCHEMATIC (51620). REWORK PUB TO REVERSE CR77 AND RETEST.					
21 AUTHORIZATION G. BEVON		22 JRG 4-33	23 DATE 3/26/81	24 CONTINUATION SHEET USED	
25 REPAIR/TEST ACTION TAKEN COR/EO INTERPRETED REUSED INSTALL DIODE CR77 PER REVISED DWG. RETEST.					
26 LIST ALL PARTS REPLACED					
PART NUMBER	QTY SYN	PART LOT NO	DATE CODE	USR	PROBABLE DEFECT
N/A					
27 REPAIR BY EVING BEVON		28 JRG 4-23	29 DATE 4-81	30 RETESTED BY DAVID CARMON	31 JRG 4-23
32 CAUSE AND CORRECTIVE ACTION CAUSE: DRAWING ERROR IN 51619 (REV F) (SCHEMATIC 51620 IS CORRECT)		33 PRE CLOSURE			
CORRECTIVE ACTION: REVISE EO (#2043A) AND REWORK/RETEST PUB. VERIFIED P/F (N=1) PUB HAS DIODE INSTALLED CORRECTLY.					
34 OCCURRENCE/IMPLEMENTING CORRECTIVE ACTION					
35 BASIC CAUSE OF UNRELIABLE FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG PROCEDURE <input type="checkbox"/> WRITING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR		36 FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR			
37 RESPONSIBLE ENGINEER G. BEVON		38 JRG 4-33	39 DATE 3/17/81	40 CUSTOMER OR SUPPLIER 161621	
41 RELIABILITY A. Huber		42 JRG 57-11	43 DATE 10-5-81	44 DATE 3/22-4/16-81	



ORIGINAL PAGE IS OF POOR QUALITY
SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1036

1. PROGRAM NAME AND NUMBER H5-236		2. QLA E330		3. MODEL PLT		4. TIME OBSERVED 10:30		5. DATE OBSERVED NOV 3 1981	
6. HARDWARE LEVEL WHERE FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT		<input type="checkbox"/> SUBSYSTEM		<input type="checkbox"/> ASSEMBLY		<input type="checkbox"/> MODULE	
		<input type="checkbox"/> SYSTEM		<input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MICAS	
7. EQUIPMENT IDENTIFICATION		NAME		PART NUMBER		QID		MANUFACTURER	
8. SUBSYSTEM									
9. UNIT									
10. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		Mini Switches		51619		002		HAL FAB	
11. OTHER									
12. TEST PHASE FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS	
		<input checked="" type="checkbox"/> PRODUCTION		<input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> SYSTEM		<input type="checkbox"/>	
13. ENVIRONMENT WHERE FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> VIBRATION		<input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMPERATURE		<input type="checkbox"/> THROATL VAC	
		<input type="checkbox"/> EMC/RFI		<input type="checkbox"/> VIBRATION		AZIM FOR _____		MIR TYPE _____	
14. DESCRIPTION OF FAILURE		INCORRECT RESISTANCE MEASURED AT K6 PER PER TS 16518 IT WAS OPEN, 5/13/81							
15. TEST PROCEDURE		TS16518		PAR # 15195		COORDINATOR R.K. COLEMAN		DATE 11-3-81	
16. VERIFICATION AND FAILURE ANALYSIS		COMPONENT K6 INCORRECTLY INSTALLED WAS TURNED 90 DEG CC. ALL PINS LOCATED BY PALMATCH. FAILURE ANALYSIS COMPONENT STRESS ATTACHED.							
17. CORRECTIVE ACTION				18. AUTHORITY		G BENSON		DATE 11-3-81	
19. REPAIR PROCEDURE				20. PARTS REPLACED		K6 (908305-5)		DATE 11-3-81	
21. TEST PROCEDURE				22. TEST PROCEDURE		REPLACE K6 AND AR3 AND RETEST PER TS16518. REPORT TO PRINT.		DATE 11-3-81	
23. LIST ALL PARTS REPLACED		PART NUMBER		PART LOT NO		DATE CODE		MFR	
		908305-5		K6		902074-570DN		TECH. ASY ERROR	
		909971-1		AR3		90115-5016		RESISTLESS (NOTE: PAR-3 NOT OBSERVED PER FAILURE ANALYSIS)	
24. CAUSE AND CORRECTIVE ACTION		CAUSE		CORRECTIVE ACTION		33. PRO CLOSURE		34. BASIC CAUSE CATEGORIED	
		CAUSE: COMPONENT NOT INSTALLED PER PRINT		CORRECTIVE ACTION: INSTRUCTED OPERATOR TO FOLLOW COMPONENT ORIENTATION AS INDICATED ON DWG AND SPECIFICATION. DWG WILL BE REVISED TO CLARIFY ORIENTATION (EPR 2042)				<input type="checkbox"/> DESIGN	
								<input type="checkbox"/> TEST EQUIP	
								<input type="checkbox"/> MFG PROCEDURE	
								<input type="checkbox"/> WIRING ERROR	
								<input type="checkbox"/> ENVIRONMENTAL	
								<input type="checkbox"/> TEST PROC.	
								<input type="checkbox"/> SYSTEM FAB ERROR	
								<input type="checkbox"/> ROUGH HANDLING	
								<input type="checkbox"/> WORKMANSHIP	
								<input type="checkbox"/> RADIATION	
								<input type="checkbox"/> TEMPERATURE	
								<input type="checkbox"/> THROATL VAC	
								<input type="checkbox"/> VIBRATION	
								<input type="checkbox"/> AZIM FOR	
								<input type="checkbox"/> MIR TYPE	
								<input type="checkbox"/> HRS AT	
								<input type="checkbox"/> 27000	
35. FAILURE TYPE		<input type="checkbox"/> PRIMARY		<input type="checkbox"/> UNKNOWN		36. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL	
		<input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> NO FAILURE				<input type="checkbox"/> MAJOR	
37. RESPONSIBLE ENGINEER		G BENSON		ORG 41-33		DATE 11/3/81		38. PACKED BY SYSTEM ENGR	
39. RELIABILITY		A. Amber		ORG 57-71		DATE 11/5/81		40. CUSTOMER OR SUPPLIER	

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 1439

1. PROGRAM NAME AND NUMBER HS 236		2. CLA E330	3. MODEL F	4. TIME OBSERVED	5. DATE OBSERVED 10/28/80														
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> PART																			
7. SUBSYSTEM IDENTIFICATION: NAME, PART NUMBER, SYN, MANUFACTURER																			
8. UNIT: POWER SUPPLY 50869 4 HAC																			
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY 19VOLT 51570 3 HAC																			
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD																			
11. OTHER																			
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM																			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCELERATION <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> SHOCK <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS POS <input type="checkbox"/> HUM <input type="checkbox"/> TYPE <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER																			
14. DESCRIPTION OF FAILURE AT INITIAL APPLICATION OF VOLTAGE, INPUT CURRENT WAS APPROACHING LIMIT SET BY T.S. 16518																			
15. TEST PROCEDURE TS 16518		16. ORIGINATOR R. Benson	17. ORG 41-33	18. DATE 10/29	19. CONTINUATION SHEET USED														
20. VERIFICATION AND FAILURE ANALYSIS Component U1 improperly installed. Should have been flower potted. Failure analysis attached. Component U1 only device overstressed.																			
21. FOLLOWING REPAIR/TEST REQUIRED REPLACE U1 & RETEST PER TS 16518.																			
22. REPAIR/TEST ACTION TAKEN REPLACE U1 PER PRINT. RETEST PER TS 16518.																			
23. LIST ALL PARTS REPLACED <table border="1"> <thead> <tr> <th>PART NUMBER</th> <th>CTK SYN</th> <th>PART LOT NO.</th> <th>DATE CODE</th> <th>MFR</th> <th>PROBABLE DEFECT</th> <th>ANALYSIS NO.</th> </tr> </thead> <tbody> <tr> <td>909956-1</td> <td>A2-419033-5050</td> <td></td> <td></td> <td></td> <td>NEW PART</td> <td></td> </tr> </tbody> </table>						PART NUMBER	CTK SYN	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT	ANALYSIS NO.	909956-1	A2-419033-5050				NEW PART	
PART NUMBER	CTK SYN	PART LOT NO.	DATE CODE	MFR	PROBABLE DEFECT	ANALYSIS NO.													
909956-1	A2-419033-5050				NEW PART														
24. REPAIR BY 19957		25. ORG 41-33	26. DATE 11-7-80	27. RETESTED BY RKC	28. ORG 41-33	29. DATE 11-22-80	30. CONTINUATION SHEET USED												
31. CAUSE AND CORRECTIVE ACTION CAUSE: COMPONENT NOT INSTALLED PER PRINT. CORRECTIVE ACTION: INSTRUCTED OPERATOR TO FOLLOW COMPONENT ORIENTATION AS INDICATED ON DWG.																			
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION																			
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN DEFECT CODE <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT																			
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOW <input type="checkbox"/> NO FAILURE <input type="checkbox"/> SECONDARY																			
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY																			
36. RESPONSIBLE ENGINEER G. Benson		37. ORG 41-33	38. DATE 11/20/80	39. SPACECRAFT SYSTEM ENG 11/20/80															
40. RELIABILITY 1. Failure		41. ORG 41-41	42. DATE 1-15-81	43. CUSTOMER OR SUPPLIER 1/15/81															

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F 3864

1. PROGRAM NAME AND NUMBER HS-236		2. GLA E330		3. MODEL PLT		4. TIME OBSERVED		5. DATE OBSERVED MO 3 DA 27 YR 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		MINI SWITCHES		51619		002		HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> RUN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP _____ ° AXIS FOR _____ MIN TYPE _____		<input type="checkbox"/> THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> OTHER _____	
14. DESCRIPTION OF FAILURE INCORRECT LEAD WIRING OBSERVED ON REDUNDANT RELAY K3 DURING CHECKOUT OF PLANT.									
15. TEST PROCEDURE		PARA TS-16518		16. ORIGINATOR G. BENSON		17. CONTINUATION SHEET USED <input type="checkbox"/>		DATE 4-23-81 3/27/81	
18. VERIFICATION AND FAILURE ANALYSIS VERIFIED RELAY K3 INSTALLED INCORRECTLY. ALL PINS ROTATED ONE PIN MISMATCH. CIRCUITRY WAS UNDER POWER, HOWEVER, GND RETURN NOT CONNECTED. THEREFORE, NO COMPONENTS OVERSTRESSED.									
19. FAILED ITEM NAME AND PART NUMBER K3 (908305-C)									
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REPLACE RELAY K3 AND RETEST PER TS-16518. LEADWORK TO PRINT									
21. AUTHORIZATION G. BENSON 4-23-81 3/27/81									
22. REWORK/RETEST ACTION TAKEN REPLACE RELAY K3 (908305-S)									
23. LIST ALL PARTS REPLACED									
PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT		ANALYSIS NUMBER	
908305-S		K3	903A274-51619			WST ERROR			
27. REWORK BY ELISA BOUSE									
ORG	DATE	RETESTED BY	ORG	DATE	28. CONTINUATION SHEET USED <input type="checkbox"/>				
41-33	4-11-81	Randy Coleman	4-33	4-20-81					
29. CAUSE AND CORRECTIVE ACTION CAUSE: COMPONENT NOT INSTALLED PER PRINT. CORRECTIVE ACTION: INSTRUCTED OPERATOR TO FOLLOW COMPONENT ORIENTATION AS INDICATED ON DWG AND SPECIFICATION DWG WILL BE REVISED TO CLARIFY ORIENTATION (ED# 2042A)									
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
31. FRB CLOSURE									
32. BASIC CAUSE OF VERIFIED FAILURE									
<input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN DEFECT CODE	
33. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		34. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR SAFETY	
35. RESPONSIBLE ENGINEER G. BENSON									
ORG	DATE	36. SPACECRAFT SYSTEM ENGINEER	ORG	DATE	37. CONTINUATION SHEET USED <input type="checkbox"/>				
41-33	7/17/81	W. HANSEN	41-33	10/5/81					
38. RELIABILITY A. Hansen									
ORG	DATE	39. CUSTOMER OR SUPPLIER	ORG	DATE					
51-11	10/5/81	HP	51-11	10/5/81					

HUGHES

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 3865

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. CLAS E330	1. MODEL FLT	4. TIME OBSERVED 1200PM	5. DATE OBSERVED MO 7 DA 13 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> URGIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> C/PD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER
8. URGIT POWER SUPPLY			50869	4	HAC
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION	<input type="checkbox"/> TEMP	<input type="checkbox"/> THERMAL VAC	
14. DESCRIPTION OF FAILURE DURING ENGINEERING EVALUATION OF SYNC CIRCUITRY ON REDUNDANT SIDE USING EXTERNAL PULSE GENERATOR, MINI INVERTER FAILED IN HIGH INPUT CURRENT MODE AND CAME FROM THE MAIN.					
15. TEST PROCEDURE ENG. EVALUATION		16. PARA	18. ORIGINATOR G. FENSON	19. DATE 4-33	20. DATE 7/13/81
17. CONTINUATION SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS CHASSIS Q3 COLLATERAL TO BURE SHOT ENGINEER ORGN, R20 SHARRED, R19 SCARCHED. COMPONENT FAILURE ANALYSIS ATTACHED. REFER TO SHOT ANALYSIS (COPY ATTACHED)					
19. FAILED ITEM NAME(S) AND PART NUMBER R18					
21. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE ON A24 (MINI) R/R Q1, Q2, Q4, R19, R20, CR12, AND Q3 ON CHASSIS PER RECOMMENDATION ON FAILURE ANALYSIS.					
22. RETEST: SHOT FORM TS 16603					
23. AUTHORITY G. FENSON					
24. REWORK/RETEST ACTION TAKEN POWER: A24 AND REPAIR Q1, Q2, Q4, R18, R19, R20, CR12 ALSO REPAIR CHASSIS MTD Q3 AND Q4.					
25. RETEST: SHOT FORM TS 16603					
26. CONTINUATION SHEET USED					
27. CONTINUATION SHEET USED					
28. CONTINUATION SHEET USED					
29. CONTINUATION SHEET USED					
30. CONTINUATION SHEET USED					
31. CONTINUATION SHEET USED					
32. CONTINUATION SHEET USED					
33. CONTINUATION SHEET USED					
34. CONTINUATION SHEET USED					
35. CONTINUATION SHEET USED					
36. CONTINUATION SHEET USED					
37. CONTINUATION SHEET USED					
38. CONTINUATION SHEET USED					
39. CONTINUATION SHEET USED					
40. CONTINUATION SHEET USED					
41. CONTINUATION SHEET USED					
42. CONTINUATION SHEET USED					
43. CONTINUATION SHEET USED					
44. CONTINUATION SHEET USED					
45. CONTINUATION SHEET USED					
46. CONTINUATION SHEET USED					
47. CONTINUATION SHEET USED					
48. CONTINUATION SHEET USED					
49. CONTINUATION SHEET USED					
50. CONTINUATION SHEET USED					
51. CONTINUATION SHEET USED					
52. CONTINUATION SHEET USED					
53. CONTINUATION SHEET USED					
54. CONTINUATION SHEET USED					
55. CONTINUATION SHEET USED					
56. CONTINUATION SHEET USED					
57. CONTINUATION SHEET USED					
58. CONTINUATION SHEET USED					
59. CONTINUATION SHEET USED					
60. CONTINUATION SHEET USED					
61. CONTINUATION SHEET USED					
62. CONTINUATION SHEET USED					
63. CONTINUATION SHEET USED					
64. CONTINUATION SHEET USED					
65. CONTINUATION SHEET USED					
66. CONTINUATION SHEET USED					
67. CONTINUATION SHEET USED					
68. CONTINUATION SHEET USED					
69. CONTINUATION SHEET USED					
70. CONTINUATION SHEET USED					
71. CONTINUATION SHEET USED					
72. CONTINUATION SHEET USED					
73. CONTINUATION SHEET USED					
74. CONTINUATION SHEET USED					
75. CONTINUATION SHEET USED					
76. CONTINUATION SHEET USED					
77. CONTINUATION SHEET USED					
78. CONTINUATION SHEET USED					
79. CONTINUATION SHEET USED					
80. CONTINUATION SHEET USED					
81. CONTINUATION SHEET USED					
82. CONTINUATION SHEET USED					
83. CONTINUATION SHEET USED					
84. CONTINUATION SHEET USED					
85. CONTINUATION SHEET USED					
86. CONTINUATION SHEET USED					
87. CONTINUATION SHEET USED					
88. CONTINUATION SHEET USED					
89. CONTINUATION SHEET USED					
90. CONTINUATION SHEET USED					
91. CONTINUATION SHEET USED					
92. CONTINUATION SHEET USED					
93. CONTINUATION SHEET USED					
94. CONTINUATION SHEET USED					
95. CONTINUATION SHEET USED					
96. CONTINUATION SHEET USED					
97. CONTINUATION SHEET USED					
98. CONTINUATION SHEET USED					
99. CONTINUATION SHEET USED					
100. CONTINUATION SHEET USED					



HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F 3866

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. CIA E264		3. MODEL PLANT		4. TIME OBSERVED		5. DATE OBSERVED MO 10 DA 30 YR 81		
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> IC/CAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:										
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER		
8. UNIT		Power Supply (P.T. SN-4)		50869		4		HAC		
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
10. <input type="checkbox"/> MODULE <input type="checkbox"/> IC/CAM <input type="checkbox"/> CARD										
11. OTHER										
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS										
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP. _____ <input type="checkbox"/> THERMAL VAC. _____ HRS AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXES FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER										
14. DESCRIPTION OF FAILURE UNIT DEMONSTRATED GREATER THAN 375 WATTS INPUT POWER DURING PREVIOUS SHORT DURATION TEST @ 35V PER YF 5-11-4-2-3 TRAIL 5-11-4-2-5. THIS IS NOT A UNIT REQUIREMENT AND THE LIMITS SHALL BE REMOVED.										
15. TEST PROCEDURE TS-16603(B) SCN-2 5-11-4-2-3 G. BENSON 5-23 10/30/81										
16. VERIFICATION AND FAILURE ANALYSIS THE HIGH INPUT POWER RESULTS FROM A HIGH 35V POS. LOAD CURRENTS ON THE HIGH SIDE AND A MAX EDGE VOLTAGE SET TO THE HIGH SIDE OF NOMINAL. PLEASE TS-16603 TO REMOVE LIMITS ON INPUT POWER. NO REPAIRS										
17. FOLLOW-UP REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE PLEASE TS-16603 TO REMOVE LIMITS ON INPUT POWER. SCN-3 RELEASED 11/1/81 ATTACHED.										
21. AUTHORIZATION: G. BENSON 4-33 11/3/81										
22. CONTINUATION SHEET USED <input type="checkbox"/>										
23. REWORK/RETEST ACTION TAKEN NONE REQUIRED										
24. QA REVIEW <input checked="" type="checkbox"/>										
25. QA RETEST <input checked="" type="checkbox"/>										
26. LIST ALL PARTS REPLACED										
PART NUMBER		CKT SYM	PART LOT NUMBER		DATE CODE	MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMBER
None										
27. REWORK BY										
ORG		DATE		28. RETESTED BY		ORG		DATE		29. CONTINUATION SHEET USED
30. CAUSE AND CORRECTIVE ACTION CAUSE: INPUT POWER GREATER THAN VALUE INDICATED IN DATA SHEETS AS MAXIMUM INPUT POWER. MAXIMUM INPUT POWER AT THE UNIT LEVEL IS AN INTERNAL SPECIFICATION BASED ON TEST CONDITIONS, NOT SYSTEM PERFORMANCE. C/A: REMOVE MAXIMUM INPUT POWER REQ'D PER SCN-3 TO TS-16603/ATTACHED										
31. FRG CLOSURE Wick 12-1-81 J. Brown 2/11/82										
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION PER SCN-3 TO TS-16603/ATTACHED										
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT <input type="checkbox"/> UNKNOWN DEFECT CODE										
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE										
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY										
36. RESPONSIBLE ENGINEER G. BENSON 4-33 11/9/81										
37. SPACECRAFT SYSTEM ENGINEER J. Brown 4-33 11/11/81										
38. RELIABILITY Leo Cran 5-41 11/24/81										
39. MANUFACTURER OR SUPPLIER 3/10/82										

ATTACHMENT TO FC# F3866

TS 16603
Rev B
~~10 December 1980~~
SCN-2 7-6-91
SCN-2 11/3/81

10.5 Performance test (short form) data sheets (continued)

REF. PARA.	DESCRIPTION	DVM SWITCH POSITIONS	LIMITS	MEASUREMENT	
				PRIMARY	REDUNDANT
5.11.4.1.13	Band 6+ load current	S26-7, S34-11	mV ÷ 0.5 = mA	_____	_____
5.11.4.1.14	Band 6 - load current	S26-7, S34-12	mV ÷ 0.5 = mA	_____	_____
5.11.4.1.15	SMA Htr + load current	S26-8, S34-1	mV ÷ 0.5 = mA	_____	_____
5.11.4.1.16	SMA Htr - load current	S26-8, S34-2	mV = mA	_____	_____
5.11.4.1.17	SMA +29V load current	S26-8, S34-3	mV ÷ 0.402 = mA	_____	_____
5.11.4.1.18	SMA -29V load current	S26-8, S34-4	mV ÷ 0.402 = mA	_____	_____
5.11.4.1.19	SMA +7V load current	S26-8, S34-5	V ÷ 0.1 = Amps	_____	_____
5.11.4.1.20	Analog - load current	S26-8, S34-6	mV ÷ 3.402 = mA	_____	_____
5.11.4.1.21	Radiometer load current	S26-8, S34-9	mV ÷ 0.5 = mA	_____	_____
5.11.4.1.22	CDVU load current	S26-8, S34-10	mV ÷ 0.5 = mA	_____	_____
5.11.4.1.23	Electrmch load current	S26-8, S34-11	mV ÷ 0.402 = mA	_____	_____
5.11.4.2.1	Bus power apply vltge	S26-1, S27-1 (S27-3 for RLT)		_____	_____
5.11.4.2.2	Bus input current	S26-1, S27-2 (S27-4 for RDT)	mV ÷ 10 = Amps	_____	_____
5.11.4.2.3	PIN (Section 5.11.4)			_____	_____
5.11.4.2.4	PIN (Section 5.11.2)			_____	_____
5.11.4.2.5	PIN (avg)			_____	_____
5.11.4.3.1	P _{OUT}			_____	_____
5.11.4.3.2	Efficiency		<i>removal</i> <i>Dr. ...</i> > 70%	_____	_____
5.11.5.1	Bus voltage	S26-1, S27-1 (S27-3 for RDT)		_____	_____
5.11.5.2	Input bus current	S26-1, S27-2 (S27-4 for RDT)	mV ÷ 10 = Amps	_____	_____
5.11.5.3	SMA Htr + otpt vltge	S26-2, S27-5	21.20 ± 2.12V	_____	_____
5.11.5.4	SMA Htr + otpt rpple	Seen on Scope	< 530 mV pk-pk	_____	_____
5.11.5.5	SMA Htr - otpt vltge	S26-2, S27-6	-21.20 ± 2.12V	_____	_____
5.11.5.6	SMA Htr - otpt rpple	Seen on Scope	< 530 mV pk-pk	_____	_____
5.11.5.7	CDVU output voltage	S26-3, S27-3	6.00 ± 0.80V	_____	_____
5.11.5.8	CDVU output ripple	Seen on Scope	< 40 mV pk-pk	_____	_____
5.11.5.9	Outgas - otpt vltge	S26-3, S27-7	80.00 ± 8.00V	_____	_____
5.11.5.10	Outgas - otpt rpple	Seen on Scope	< 2.5V pk-pk	_____	_____
5.11.5.11	Parasitic otpt vltge	S26-3, S27-9 (S27-10 Rdt)	30.00 ± 0.90V	_____	_____

SCN-2
-3
-2

ORIGINAL PAGE IS
OF POOR QUALITY

ATTACHMENT TO FR# F3866

TS 16603
Rev B

number 1989
~~SCN-2~~ 7-6-81
SCN-3 11/3/81

10.4 Performance test (continued)

REF. PARA.	DESCRIPTION	LVM SWITCH POSITIONS	LIMITS	MEASUREMENT	
				PRIMARY	REDUNDANT
5.10.5.1.17	SMA +29V load current	S26-8, S34-3	mV ÷ 0.402 = mA	_____	_____
5.10.5.1.18	SMA -29V	S34-4	mV ÷ 0.402 = mA	_____	_____
5.10.5.1.19	SMA +7V	S34-5	V ÷ 0.1 = Amps	_____	_____
5.10.5.1.20	Analog -	S34-6	mV ÷ 0.402 = mA	_____	_____
5.10.5.1.21	Radiometer	S34-9	mV ÷ 0.5 = mA	_____	_____
5.10.5.1.22	CDVU	S34-10	mV ÷ 0.5 = mA	_____	_____
5.10.5.1.23	Electromech. load current	S26-8, S34-11	mV ÷ 0.402 = mA	_____	_____
5.10.5.2.1	Bus power supply voltage	S26-1, S27-1 (S27-3 for RDT)		_____	_____
5.10.5.2.2	Bus input current	S26-1, S27-2 (S27-4 for RDT)	mV ÷ 10 = Amps	_____	_____
5.10.5.2.3	FIN (Section 5.10.5)			_____	_____
5.10.5.2.4	FIN (Section 5.10.3)			_____	_____
5.10.5.2.5	FIN (avg)			_____	_____
5.10.5.2.9	Input current at current limit		26-1, 27-2 (26-1 27-4 Rdt)	_____	_____
	Input voltage at current limit		27-1 (27-3 Rdt)	_____	_____
	MUX voltage at current limit		26-3, 27-1	_____	_____
	MUX current at current limit		27-12	_____	_____
5.10.5.3.1	P _{OUT}			_____	_____
5.10.5.3.2	Efficiency		> 70%	_____	_____

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F 3867

1. PROGRAM NAME AND NUMBER THEMATIC Mapper		2. GLA F264		3. MODEL FLIGHT		4. TIME OBSERVED		5. DATE OBSERVED MO 11 DA 2 YR 81		
8. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART		
EQUIPMENT IDENTIFICATION:										
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER		
8. UNIT POWER SUPPLY (FLT-SN-004)				50869		004		HAC		
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD										
11. OTHER										
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> QUALIFICATION		<input type="checkbox"/> INTEGRATION		<input type="checkbox"/> LAUNCH OPERATIONS				
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RR		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR _____ MIN TYPE _____		<input type="checkbox"/> THERMAL VAC _____ HRS AT _____		<input type="checkbox"/> OTHER		
14. DESCRIPTION OF FAILURE UNIT FAILED POST VIBRATIONAL SHORT PER IN TEST PER 9.5.11.2-3 UNIT FAILED TO RESPOND TO OFF-HOLD ON PRIMARY SIDE.										
15. TEST PROCEDURE TS-16603(B) SN-2		PARA 5.11.2.3		16. ORIGINATOR G. SEWSON		ORG 41-33		DATE 11/2/81		17. CONTINUATION SHEET USED <input type="checkbox"/>
18. VERIFICATION AND FAILURE ANALYSIS RELAY A24-K5 DOES NOT CHANGE STATE WHEN CMD CHG IS VERIFIED BY LACK OF AUDIBLE NOISE DURING CONTACT TRANSFER. TEST AFTER UNIT WAS REMOVED AND BEFORE RELAY COULD BE FULLY INSTRUMENTED. NORMAL RELAY OPERATION RESUMED. REFER TO ATTACHED TEST REPORT A24-K5 908307-2										
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REPLACE A24-K5 PER PRINT. RETEST PER TS 16603. SUBMIT FAILED PART TO FAILURE ANALYSIS. REPEAT VIBRATION LEVEL VIBRATION PER TS-16603. PARTS BOARD OFFICER'S RECOMMENDS REPLACEMENT OF ALL 908307-2 IN SN-4 P/S. G. SEWSON 41-33 11/30/81										
20. JUST ALL PARTS REPLACED										
21. REWORK/RETEST ACTION TAKEN		22. AUTHORIZATION		ORG G. SEWSON		DATE 11/30/81		17. CONTINUATION SHEET USED <input type="checkbox"/>		
23. CAUSE AND CORRECTIVE ACTION REMOVE AND REPLACE K1K2 ON 51570 SN-3 P4 WITH CDU-00702. REMOVE AND REPLACE K1, 2, 4, 5 ON 57619 SN-2 WITH CDU-00702. REPEATED VIBRATION AND POST VIB PERFORMANCE TEST.										
24. DATE REWORK/RETEST TEST 12-22-81		25. TEST REPORT NUMBER S22		26. ANALYSIS NUMBER		27. CONTINUATION SHEET USED <input type="checkbox"/>		28. DEFECT CODE		
29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN		
30. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		31. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY		32. RESPONSIBLE ENGINEER G. SEWSON		DATE 12/21/81		
33. RESPONSIBLE ENGINEER G. SEWSON		ORG 41-33		DATE 12/21/81		34. RESPONSIBLE ENGINEER G. SEWSON		DATE 12/21/81		
35. RESPONSIBLE ENGINEER G. SEWSON		ORG 5L41		DATE 1-4-82		36. RESPONSIBLE ENGINEER G. SEWSON		DATE 1/5/82		

CLASSIFIED
EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

ATTACHMENTS TO FR# F3867

AVOID VERBAL ORDERS



TO	<u>F. R. PHILLIPS</u>	FROM	<u>FRANK CARLE</u>
SUBJECT	<u>PRELIMINARY THEMATIC MAPPER PMPCB</u>	OSPT	<u>44-29-00</u> DATE <u>12/1/</u>
	<u>RECOMMENDATION - 908307-2 RELAY</u>	CLER	<u>S13</u> LS <u>D329</u>
		LOS	<u>SC</u> EXT <u>5-935</u>

CONFIRMING OUR RECENT TELEPHONE CONVERSATION, A TELEPHONE POLL OF THE THEMATIC MAPPER PMPCB HAS BEEN MADE TO ARRIVE AT AN EARLY RECOMMENDATION ON THE DISPOSITION OF THEMATIC MAPPER 908307-2 RELAYS. OUTLINED BELOW ARE PRELIMINARY RECOMMENDATIONS.

1. CHANGE OUT F-1 RELAYS FOR THOSE OF LOT DATE CODE 7846, WHICH SUCCESSFULLY PASSED SCREENING TESTS AT TELEDYNE, AND ARE BEING REIDENTIFIED TO CDU00702.
2. RETAIN THE CURRENT PROTOFLIGHT SYSTEM RELAYS (ALL OF LOT DATE CODE 7846) IN THE SYSTEM WITHOUT CHANGEOUT.

THE REASON FOR THIS RECOMMENDATION IS AS FOLLOWS:

- A. INTEGRITY OF RELAYS OF LOT DATE CODE 7846 WAS ESTABLISHED BY A SCREEN OF 39 PIECES, WITHOUT A PICK-UP VOLTAGE HANG-UP.
- B. LACK OF INVENTORY ON RELAYS LOT DATE CODE 7615 (ONE OF WHICH WAS THE FAILURE), AND LOT DATE CODE 7330, WHICH ARE IN F-1 PRECLUDES EARLY VALIDATION OF INTEGRITY PROVING CONCLUSIVELY THAT THE FAILURE IS RANDOM.
- C. RATHER THAN SUFFER FURTHER SCHEDULE DELAYS TO F-1, CHANGEOUT TO THE SCREENED 7846 PARTS APPEARS THE EXPEDIENT SOLUTION.

E. F. Carle

E. F. CARLE

:AC
:C: ~~XXXXXXXXXX~~, DISTRIBUTION "G"

ORIGINAL PAGE IS
OF POOR QUALITY

①

ORIGINAL PAGE IS
OF POOR QUALITY

F3867

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

TO: L. O'Connell

CC: See Distribution List DATE: 6 November 1981

REF: HS236-7711

REAR 81/57

FROM: A. Huber

SUBJECT: Power Supply
908307-2 Relays
(FR: F3867)

BLDG. B11 MAIL STA. 102
EXT. 6246

FR: F3867, dated November 2, 1981

Following acceptance test vibration of the Flight Model power supply, test of the power supply revealed that the power supply could not be commanded to the OFF state. It was verified by measuring coil current to the relay that the command to the OFF relay (A24-R5) was proper (+28V pulse for 6ms). The power supply cover was then removed and the miniswitcher board instrumented to investigate the failure. Subsequent testing found that the relay then functioned; the audible sound of relay contact transfer could be heard. (This sound was not present during earlier testing.) The relay (908307-2, Teledyne part no. 412-6111, date code 7615, serial no. 183) was removed and sent to Teledyne for failure analysis.

There are a total of eight 908307-2 relays in the power supply: four each in the primary and redundant supplies. Each of the four relays within a given power supply performs one of the following functions:

- (a) turns the supply ON (relay 1)
- (b) turns the supply OFF (relay 2)
- (c) applies 30V to the multiplexer and removes 30V from the parasitic mux load (relay 3)
- (d) applies 30V to the parasitic mux load and removes 30V from the multiplexer.

Figure 1 illustrates the circuitry associated with the two relays that turn a given power supply (primary or redundant) to the ON or OFF states. The 908307-2 relays are non-latching relays which momentarily (6 ms) apply signal ground to the input of 30 ms single shots. The single shots, in turn, apply voltage to the first of two high-current (power) relays to apply or remove bus voltage to power supply circuitry.

There are two power relays in series. The second power relay has associated with it a 10 ohm power resistor. This resistor limits the inrush current. When the voltage at the 10 ohm resistor reaches +18.5, the contacts of the second power relay close, thereby shorting the resistor. The power supply is then fully operational. The second power relay opens and closes as a function of line voltage (+18.5V threshold), controlled by voltage sensing circuitry within the power supply.

Once a power supply has been commanded to the ON state, the contacts of the first power relay can only be opened by three events:

To: L. O'Connell
From: A. Huber

ORIGINAL PAGE IS
OF POOR QUALITY

F 3867
HS 236-7711
Page 2

- (1) the issuance of an OFF command (by the 908307-2 Off command relay)
- (2) a line voltage in excess of +38.5V, thereby causing overvoltage shutdown
- (3) an overvoltage associated with the internally generated +30V reference voltage (+34V initiates the shutdown)

It is possible to command a power supply to the ON state (requires the presence of line voltage) and then remove the bus voltage. This leaves the contacts of the first power relay in the closed state. The contacts of the second relay open when the bus voltage drops below +18.5V (thereby reinserting the 10 ohm power resistor). Re-application of bus voltage will cause the contacts of the second power relay to close (similar to a commanded ON sequence). Initial inrush current will be limited by the 10 ohm resistor.

The above demonstrates a sequence that can be initiated prior to launch, to guarantee that at least one power supply will receive power after launch. It removes the possibility that neither power supply can be turned on due to the failure of both ON relays.

Figure 2 illustrates the circuitry associated with the two relays that control the application and removal of 30V to the multiplexer and the parasitic mux load. Each command relay (908307-2) momentarily (6MS) applies signal ground to the input of a 30MS single shot. The single shot, in turn, applies voltage to the coil of a latching power relay.

Figure 3 illustrates the interconnection of the contacts of the multiplexer relays of the primary and redundant power supplies. For the configuration shown, the redundant power supply is connected to the multiplexer and the primary power supply is connected to the parasitic load.

A failure mode can be defined in which one power supply (primary) cannot be commanded off, and its multiplexer relay cannot be commanded to the multiplexer position (two relay failures exist). This requires that the redundant power supply be commanded ON, and that its multiplexer relay be commanded ON. The configuration is then as shown in Figure 3.

Electrically it is possible to command both power supplies ON at the same time, however, the thermal characteristics of the power supply unit with both power supplies ON has not been investigated. The power supplies will then share all loads except the multiplexer load, unless both multiplexer relays are switched to the multiplexer load. If this is done the power supplies will share the multiplexer load as well.

With both power supplies ON, the effective overcurrent shutdown threshold is increased by the degree to which the power supplies share the loads. The effective power supply efficiency is decreased

To: L. O'Connell
From: A. Huber

ORIGINAL PAGE IS
OF POOR QUALITY

HS 236-7711
Page 3

F3867

since the load power remains the same, but there are additional losses associated with the second supply. The temperatures within the power supply unit would be expected to increase because of the additional loads of the second supply.

The above concludes the report describing the power supply failure involving the 908307-2 relay. The power supply is the only assembly that uses 908307-2 relays.

Andrew E. Huber

ANDREW E. HUBER

AEH:snc

(4)

F 3867

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 1. PRIMARY (OR REDUNDANT) POWER SUPPLY
ON/OFF RELAY COMMAND STRUCTURE (CONCEPTUAL)

F 3867

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 2. MULTIPLEXER COMMAND RELAY STRUCTURE
(ONE POWER SUPPLY)




FIGURE 3. PRIMARY/REDUNDANT MULTIPLEXER RELAY CONTACT
CONFIGURATION

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER

F3867

AVOID VERBAL ORDERS

TO L. O'CONNELL

DATE 11-9-81

FROM A. HUBER

SUBJECT POWER SUPPLY
RELAY FAILURE
(REF: F3867)

NO OVERSTRESS OCCURRED AS A RESULT OF THE
POWER SUPPLY OFF CMD RELAY FAILURE.

REF: HS 236-7711 (DATED 11-6-81)

A. Huber

CC: L. ALTMAN

SBRC FORM 14-0312

HUGHES

INTERDEPARTMENTAL CORRESPONDENCE



F 3867

TO: E.F. Carle
ORG: 44-29

CC:

ORIGINAL PAGE IS
OF POOR QUALITY

DATE: 10 December 1981
REF. 7611.42/502

SUBJECT: SEM Analysis of Teledyne
Relay, HAC P/N 908307-2,
S/N 7364

FROM: P.R. Catizone
ORG. 76-11-42

BLDG. 6
LOC. CC

MAIL STA. C136
EXT. 7619

INTRODUCTION

This relay failed after vibration in the Thematic Mapper flight unit. It saw 28 +2 V in a 6mS pulse but did not transfer. It passed gross and fine leak tests. It went through vibration tests as per CDU 0069L and passed all but two where it required 18.7 and 18.2 volts to actuate as compared to the minimum of 14.7. The relay was delidded and inspected visually at Teledyne where it was determined that one of the guide pins was adjusted too high and not allowing enough play in the socket of the armature. A SEM analysis was done to look for any wear and/or material transfer at points of moving contact.

RESULTS

Upon visual inspection of the delidded relay, one could see two salient points. First of all the armature did not touch the core shank in all places (see Figure 1). In fact, the two were only in contact over a small area. Also, the right guide pin (as viewed in Figure 1) was set higher than the left. Although it may be difficult to see this in the picture, it was clearly visible with the part at hand under a microscope. This was in agreement with the visual inspection done at Teledyne. This point, together with an apparent bowing of the armature and unevenness of the core shank, is the cause of the mismatch between the two.

A view of the armature sockets under SEM revealed excessive wear along the top of the right socket (see Figure 2). Note that the socket in Figure 2 is upside down compared to the assembled relay in Figure 1. The left socket did not show nearly as much wear on the top although looked virtually the same on the sides as the right socket. This is in good agreement with the high adjustment of the guide pin and lack of play in the right side observed before dismantlement. The guide pins themselves showed no irregular surface disturbances or material transfer, so apparently the smearing of plating in the sockets is just a result of the pins rubbing and bumping, not cold welding or similar type problem.

A look at the pivot edge side of the armature showed a groove worn in (Figure 3) with most of the wear near the area that appeared in contact with the core shank (see Figure 1). A close-up of this area is shown in Figure 4. Although no nickel from the plating of the core shank was found transferred to the armature, material from the armature was found along the pivot edge of the core shank. The armature itself consists of an iron core with successive layers of copper, palladium and a thin layer of gold plating. An examination of the core shank in the area that corresponds with the groove area shown in Figure 4 revealed much transfer of gold, palladium and copper from the armature (see Figures 5 and 6). This

F 3867

ORIGINAL PAGE IS
OF POOR QUALITY

Page 3
IDC




FIGURE NO. 1

Picture of delidded relay showing uneven matching between armature and core shank. The two are only in contact where the arrow indicates. Note also that the right guide pin is higher than the left.

MAGNIFICATION 10X




FIGURE NO. 2

Right socket showing smearing due to high guide pin.

MAGNIFICATION 210X

F 3867




FIGURE NO. 3

View of armature actuator showing groove worn in due to pivot action against core shank.

MAGNIFICATION 22X

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE NO. 4

Close up of area marked by arrow above. This is the area that appears in contact with the core shank in Figure 1.

MAGNIFICATION 100X

F3867

Page 5
IDC



FIGURE NO. 5

Close up of pivot edge of core shank in area that appeared in contact with the armature (see Figure 1). The bright splotches are gold plating from the armature.

MAGNIFICATION 1100X

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE NO. 6

EDX of pivot edge above. Note that gold, palladium and even copper have been transferred to the core shank which is iron with electroless nickel plating.

12

ORIGINAL PAGE IS
OF POOR QUALITY

F3867

Page 6
IDC



FIGURE NO. 7
View of end of spring
MAGNIFICATION 106X




FIGURE NO. 8
Close up of spring from area
marked by arrow above.
Light flakes are gold.
MAGNIFICATION 1060X

ORIGINAL PAGE IS
OF POOR QUALITY

Page 7
IDC

F3867




FIGURE NO. 9

EDX of a light area in
Figure 6 showing presence
of gold. The base metal
of the spring is an Fe-
Cr-Ni alloy.




FIGURE NO. 10

Close up of spring contact
area on armature.

MAGNIFICATION 510X

ORIGINAL PAGE IS
OF POOR QUALITY

F3867

Page 8
IDC




FIGURE NO. 11

View of the right movable
contact showing the area
that hits the lower
stationary contact. The
other three surfaces are
very similar.

MAGNIFICATION 100X




FIGURE NO. 12

View of the lower stationary
contact that matches with
the movable contact above.
The arrows point to two
lines of surface disturbances.

MAGNIFICATION 100X

ORIGINAL PAGE IS
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER
A Subsidiary of Hughes Aircraft Company
INTERNAL MEMORANDUM

F3867

TO: L. O'Connell

CC: See Distribution List DATE: 6 November 1981

REF: HS236-7711
REAH 81/57

FROM: A. Huber

SUBJECT: Power Supply
908307-2 Relays
(FR: F3867)

BLDG. B11 MAIL STA. 102
EXT. 6246

FR: F3867, dated November 2, 1981

Following acceptance test vibration of the Flight Modal power supply, test of the power supply revealed that the power supply could not be commanded to the OFF state. It was verified by measuring coil current to the relay that the command to the OFF relay (A24-K5) was proper (+28V pulse for 6ms). The power supply cover was then removed and the miniswitcher board instrumented to investigate the failure. Subsequent testing found that the relay then functioned; the audible sound of relay contact transfer could be heard. (This sound was not present during earlier testing.) The relay (9080307-2, Teledyne part no. 412-6111, data code 7613, serial no. 183) was removed and sent to Teledyne for failure analysis.

There are a total of eight 908307-2 relays in the power supply: four each in the primary and redundant supplies. Each of the four relays within a given power supply performs one of the following functions:

- (a) turns the supply ON (relay 1)
- (b) turns the supply OFF (relay 2)
- (c) applies 30V to the multiplexer and removes 30V from the parasitic mux load (relay 3)
- (d) applies 30V to the parasitic mux load and removes 30V from the multiplexer.

Figure 1 illustrates the circuitry associated with the two relays that turn a given power supply (primary or redundant) to the ON or OFF states. The 908307-2 relays are non-latching relays which momentarily (6 ms) apply signal ground to the input of 30 ms single shots. The single shots, in turn, apply voltage to the first of two high-current (power) relays to apply or remove bus voltage to power supply circuitry.

There are two power relays in series. The second power relay has associated with it a 10 ohm power resistor. This resistor limits the inrush current. When the voltage at the 10 ohm resistor reaches +18.5, the contacts of the second power relay close, thereby shorting the resistor. The power supply is then fully operational. The second power relay opens and closes as a function of line voltage (+18.5V threshold), controlled by voltage sensing circuitry within the power supply.

Once a power supply has been commanded to the ON state, the contacts of the first power relay can only be opened by three events:

To: L. O'Connell
From: A. Huber

ORIGINAL PAGE IS
OF POOR QUALITY

HS 236-7711
Page 3

F3867

since the load power remains the same, but there are additional losses associated with the second supply. The temperatures within the power supply unit would be expected to increase because of the additional loads of the second supply.

The above concludes the report describing the power supply failure involving the 908307-2 relay. The power supply is the only assembly that uses 908307-2 relays.

Andrew E. Huber

ANDREW E. HUBER

AEH:snc

F 3867

ORIGINAL PAGE IS
OF POOR QUALITY




FIGURE 1. PRIMARY (OR REDUNDANT) POWER SUPPLY
ON/OFF RELAY COMMAND STRUCTURE (CONCEPTUAL)

ORIGINAL PAGE IS
OF POOR QUALITY

F3867




FIGURE 2. MULTIPLEXER COMMAND RELAY STRUCTURE
(ONE POWER SUPPLY)




FIGURE 3. PRIMARY/REDUNDANT MULTIPLEXER RELAY CONTACT
CONFIGURATION

ORIGINAL PAGE IS
OF POOR QUALITY

F3867

DISTRIBUTION:

ALTMAN, L.	B11/39
BANACH, J. A.	B12/58
BARNETT, G. C.	B11/102
CARLE, F.	SC S1/D339
ENGEL, J. L.	B11/79
FREUDENSTEIN, W. R.	B12/58
MORRISON, D. L.	B11/40
OXLEY, S.	B11/79
PHILLIPS, F. R.	B11/79
WOLTHAUSEN, L. H.	B12/23
Data Bank (8)	

F 3867

AVOID VERBAL ORDERS

TO MR. O'CONNELL

DATE 11-9-81

FROM A. HUBER

SUBJECT POWER SUPPLY
RELAY FAILURE
(FR: F3867)

NO OVERSTRESS OCCURRED AS A RESULT OF THE
POWER SUPPLY OFF CMD RELAY FAILURE.

REF: HS 236-7711 (DATE 11-6-81)

A. Huber

CC: L. ALTMAN

SBRC FORM 14-0312

ORIGINAL PAGE IS
OF POOR QUALITY

11

HUGHES

ORIGINAL PAGE IS OF POOR QUALITY

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

F 4831

HUGHES AIRCRAFT COMPANY SPACE AND COMMUNICATIONS GROUP EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER HS236	2. GLA E330	3. MODEL FLIGHT	4. TIME OBSERVED	5. DATE OBSERVED MO 4 DA 28 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART				
EQUIPMENT IDENTIFICATION:				
7. SUBSYSTEM	NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT Power Supply (PLT)		50869	004	HAC
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
11. OTHER				
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM				
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ ° _____ ° <input type="checkbox"/> THERMAL VAC _____ HRG AT _____ <input type="checkbox"/> EMC/RR <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER				
14. DESCRIPTION OF FAILURE CENTER TAP CURRENT IN MINI PRIMARY WINDING OF XFMR INDICATES LAMP OF PULSED CURRENT; S/B 200 MA PULSES AT CHK-OUT W/MAX. BFD SUPPLY TURNED "OFF"				
15. TEST PROCEDURE TS 16606	16. ORIGINATOR J. Gilliam	ORG 41-33	DATE 4-29-81	17. CONTINUATION SHEET USED <input type="checkbox"/>
18. VERIFICATION AND FAILURE ANALYSIS PROBLEM IS A WIRING ERROR AND WITH NO COMPONENT STRESSES. FAILURE ANALYSIS ATTACHED. CONNECTOR MADE TO WIRING END OF WINDING L2.	19. FAILED ITEM NAME AND PART NUMBER NONE			
20. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE MISS WIRE: FROM P6-7 TO L2-E2 7/8 P6-7 TO L2-E1 RETEST PER TS 16606 PARA I	21. AUTHORIZATION J. Gilliam	ORG 41-33	DATE 4-30-81	22. CONTINUATION SHEET USED <input type="checkbox"/>
23. REWORK/RETEST ACTION TAKEN WIRE FROM P6-7 TO L2-E2 7/8 P6-7 TO L2-E1 RETESTED PER TS 16606 PARA I	24. USE REWORK (EITS) 5-491			
25. LIST ALL PARTS REPLACED PART NUMBER	CMT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
PROBABLE DEFECT	ANALYSIS NUMBER			
27. REWORK BY ELISA BECKER	ORG 41-33	DATE 4-30-81	28. RETESTED BY Don Crawford	ORG 41-33
DATE 4-29-81	29. CONTINUATION SHEET USED <input type="checkbox"/>			
30. CAUSE AND CORRECTIVE ACTION CAUSE: WIRING ERROR. C/A: OPERATOR AND WIRE CHECKER INSTRUCTED TO PHYSICALLY TRACE WIRE TO TERMINATION POINT IF POSSIBLE. CHECK WIRING TO WIRE LIST 53666 FOR CORRECT TERMINATION.	31. CONTINUATION SHEET USED <input type="checkbox"/>			
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION				
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> WIRING ERROR <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
36. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	37. RESPONSIBLE ENGINEER G. Benson	ORG 41-33	DATE 7/21/81	38. SPACECRAFT TEST ENGINEER J. Gilliam
39. RELIABILITY Don Perkins	ORG 51-41	DATE 7-23-81	40. CUSTOMER OR SUPPLIER HP	DATE 2261 510727

7/21/81

HUGHES

ORIGINAL PAGE IS OF POOR QUALITY

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT

F 4832

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER <i>Thermal Mapper H5236</i>		2. JLA <i>E330</i>	3. MODEL <i>FLIGHT</i>	4. TIME OBSERVED	5. DATE OBSERVED <i>MO 4 DA 30 YR 81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT <i>Power Supply (PLT)</i>		<i>50869</i>	<i>004</i>	<i>HAC</i>	
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <i>MAXI-PWB</i>		<i>51590</i>	<i>002</i>	<i>HAC</i>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> MIS FOR <input type="checkbox"/> FIX TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>SYNC PULSE NOT PRESENT MAXI-BED.</i>					
15. TEST PROCEDURE <i>TS 1660G</i>					
16. VERIFICATION AND FAILURE ANALYSIS <i>WIRE & Error on MAXI-BED, A23 J2-16 to WIRE LIST PAD, 3/8 A23 J2-16 to A23-E36. THERE WERE NO COMPONENTS STRESSED. NO COMPONENTS STRESSED. FAILURE ANALYSIS NONE</i>		18. ORGANIZATION <i>ELSEG</i>	19. ORG <i>4-33</i>	20. DATE <i>4-30-81</i>	17. CONTINUATION SHEET USED <input type="checkbox"/>
21. FOLLOWING REWORK/RETEST REQUIRED <i>ATTACHED. REWIRE PER WIRE LIST 53666</i>					
22. REWORK/RETEST NOT REQUIRED BECAUSE <i>RETEST PER TS 1660G PARA VI</i>					
23. REWORK/RETEST ACTION TAKEN <i>REWIRE PER WIRE LIST 53666</i>					
24. USE ALL PARTS REPLACED					
PART NUMBER	CKT SYM.	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
27. REWORK BY <i>ELAISA BECKER</i>		28. RETESTED BY <i>DEL COMBER</i>	29. ORG <i>4-33</i>	30. DATE <i>4-30-81</i>	31. CONTINUATION SHEET USED <input type="checkbox"/>
32. CAUSE AND CORRECTIVE ACTION <i>CAUSE: WIRING ERROR AND INSPECTION ERROR. CIA INSTRUCTED ASSEMBLER AND WIRE CHECK INSPECTOR TO FOLLOW WIRE TERMINATIONS AS DEFINED ON DWG 53666 (WIRE LIST)</i>					
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> WIRING ERROR <input type="checkbox"/> FAILURE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		35. FAILURE CLASSIFICATION <input type="checkbox"/> UNKNOWN <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
36. RESPONSIBLE ENGINEER <i>E. Benson</i>		37. ORG <i>4-33</i>	38. DATE <i>7/21/81</i>	39. SPACER BY SYSTEM ENGINEER <i>E. Benson</i>	40. ORG <i>2261</i>
41. RESPONSIBILITY <i>A. Perlman</i>		42. ORG <i>51-41</i>	43. DATE <i>7-23-81</i>	44. CUSTOMER OR SUPPLIER	45. DATE <i>810727</i>

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4833

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. QLA 6330	3. MODEL FLIGHT	4. TIME OBSERVED	5. DATE RECEIVED MO 5 DA 4 YR 81
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER
8. UNIT POWER SUPPLY (PLT-SN-4)		50869	4	HAC	
<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		MAXI-PWB	51590	2	HAC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> M/N TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE MAXI-SWITCHER CHECKOUT-REUNDANT. OBSERVED NO BASE DRIVE ON ONE BASE TO POWER TRANSISTORS DURING ATTEMPT TO PHASE UP PULSE WIDTH ON MAXI-PWB. NO LOAD CONDITION.					
15. TEST PROCEDURE TS 16606		16. OPERATOR G. BENSON	17. DATE 4-22-81	18. CONTINUATION SHEET USED	
19. VERIFICATION AND FAILURE ANALYSIS ENGINEERING TESTS INDICATE TRANSISTOR Q17 ON A23 (51590 SN-7) FAILED - OPEN EMITTER. SUBMIT COMPONENT FOR FAILURE ANALYSIS. COMPONENT STRESS ANALYSIS OBTAINED.					
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REPLACE Q17 & Q18 (OVERSTRESS) SUBMIT TO PARTS. RETEST PER TS-16606. BOARD FOR PART.					
21. REWORK/RETEST ACTION TAKEN RETEST PER TS 16606 PAGE II REMOVE AND REPLACE Q17 & Q18. RETEST.					
22. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
908801-1	Q17	7417	MOTOROLA		
23. REWORK BY ELAISA BECKER ORG 41-33 DATE 5-8-81					
24. CAUSE AND CORRECTIVE ACTION CAUSE: OPEN BASE LEAD IN TRANSISTOR Q17 PER PAR 8931. PROBABLE INDUCED FAILURE DURING SURFACE C/P OR UNIT G/O TEST WHICH APPLIED HIGH CURRENT SOURCE TO BASE OF Q17. INADEQUATE TEST SET-UP. G/A: INSTRUCTED TECHNICIAN TO HAVE SECOND TECHNICIAN VERIFY TEST SETUP BEFORE VOLTAGE APPLIED.					
25. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT <input type="checkbox"/> UNKNOWN					
26. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL CLASSIFICATION <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY					
27. RESPONSIBLE ENGINEER G. BENSON ORG 41-33 DATE 4/21/81		28. SPACECRAFT SYSTEM ENGINEER J. L. ... ORG 2261 DATE 810727		29. RELIABILITY G. Beckman ORG 51-41 DATE 7-23-81	

[Handwritten signature]
4/27/81

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

ORIGINAL PAGE IS
OF POOR QUALITY
SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4834

PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. GL E330	1. MODEL FLIGHT	4. TIME OBSERVED 2 10:00 AM	5. DATE OBSERVED MO 5 DA 9 YR 81		
6. HAZARD LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION:							
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER		
8. UNIT POWER SUPPLY (PLT SW-4)		50869	4	HAC			
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY							
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
11. OTHER							
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input type="checkbox"/>							
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ <input type="checkbox"/> THERMAL VAC _____ HAS AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER _____							
14. DESCRIPTION OF FAILURE CENTER TAP CURRENT IN THE MAXI IS EXCEEDING 15 AMPS WITH NO LOAD ON MAXI REDUNDANT. OCCURRED DURING CHECKOUT OF REDUNDANT MAXI-LANDED BUFLER STAGE.							
15. TEST PROCEDURE TS-16606		16. ORIGINATOR M.L.	17. CONTINUATION SHEET USED <input type="checkbox"/>	18. ORG 41-33	19. DATE 5-11-81		
18. VERIFICATION AND FAILURE ANALYSIS WIRE CONNECTED (SOLDERED) TO T2-E11 FROM T4-E1 IS MAGNET WIRE AND THIS MAGNET WIRE WAS PUSHED UP AGAINST T2-E14, BREAKING MAGNET WIRE INSULATION PRODUCING A SHORT ACROSS PRIMARY OF T2 & T6. NO CRACKS WERE OVER SYSTEM - SEE ATTACHMENT.							
19. FAILED ITEM NAME AND PART NUMBER NONE							
20. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest NOT required because WIRE CAN BE MOVED AWAY FROM ADJACENT TERMINAL. WIRE WAS ROUTING TO EXISTING SHORTING HAZARDOUS PER WORKMANSHIP RETEST PER TS-16606 W/TI STANDARDS.							
21. AUTHORITY G. Benson							
22. REWORK/RETEST ACTION TAKEN REWORK NOT REQUIRED BECAUSE WIRE ROUTING WAS MOVED AWAY FROM ADJACENT TERMINAL WITHOUT RESOLDERING CONNECTION. ACCOMPLISHED RETEST PER TS-16606 W/TI							
23. USE ALL PARTS REPLACED		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER
NONE							
27. REWORK BY N/A							
28. RETESTED BY D.L. Crawford							
29. CAUSE AND CORRECTIVE ACTION CAUSE: OPERATOR ROUTED WIRE TOO CLOSE TO ADJACENT TERMINALS; THEREFORE RESULTING IN A SHORT. C/A: WIRE RE-ROUTED AWAY FROM TERMINAL. OPERATOR INSTRUCTED TO FOLLOW NORMAL WORKMANSHIP STANDARDS TO AVOID HAZARDOUS WIRE ROUTING.							
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION HAZARDOUS WIRE ROUTING							
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> CRITICAL <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROCEDURE <input checked="" type="checkbox"/> ASSY/PAD ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> MAJOR <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> MINOR							
32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE							
33. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY							
37. RESPONSIBLE ENGINEER G. Benson		41-33	DATE 7/21/81	38. SPACECRAFT SYSTEM ENGINEER J. R. ...			
38. RELIABILITY J. R. ...		57-41	DATE 7-23-81	39. ACCEPTOR OR SUPPLIER M.L.			

7/31/81

ORIGINAL PAGE IS
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

F 4835

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. OLA E330	3. MODEL FLT	4. TIME OBSERVED 1:30 PM	5. DATE OBSERVED MO 5 DA 9 YR 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:						
7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER	
8. UNIT POWER SUPPLY (FLT SN-4)			50869	4	HAC	
<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		MAIN-PIV3	51619	2	HAC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		11. OTHER				
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS		
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP _____ AXIS FOR _____	<input type="checkbox"/> THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> OTHER		
14. DESCRIPTION OF FAILURE TRY TO TURN MAXI UP BUT IT ONLY TURNS ON A LITTLE, BUT WILL NOT CONTINUE TO PHASE-UP. (REDUNDANT) OCCURRED DURING CHECKOUT OF REDUNDANT MAIN-INVERTER POWER STAGE.						
15. TEST PROCEDURE TS16606		PARA VI	16. ORIGINATOR RELIANCE	ORG 41-33	DATE 5-9-81	
18. VERIFICATION AND FAILURE ANALYSIS WRONG BASE TO EMITTER VALUE FOR A24R58, WAS 180K 5% 1/4W, SHOULD BE 5.1K 5% 1/4W - NO COMPONENTS WERE OVER STRESSED - SEE ATTACHMENT.		19. FAILED ITEM NAME AND PART NUMBER NONE		17. CONTINUATION SHEET USED		
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		INSTALL PER POINT A24R58 5.1K 5% 1/4W. RETEST PER TS16606 PARA VI.				
21. AUTHORIZATION CLYDE		ORG 41-33	DATE 5-9-81	22. CONTINUATION SHEET USED		
23. Rework/Retest Action Taken INSTALL PER POINT A24R58 5.1K 5% 1/4W. RETEST PER TS16606 PARA VI		24. SA REPAIR 5/13/81		25. SA TEST S23		
26. LIST ALL PARTS REPLACED						
PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	
27. Rework by LAISA BECKER						
ORG 41-33	DATE 5-12-81	28. Retested by DEL CARREARDY		ORG 41-33	DATE 5-12-81	
29. CAUSE AND CORRECTIVE ACTION CAUSE: WRONG RESISTOR VALUE INSTALLED FOR A24R58. CORRECTIVE ACTION: ASSEMBLER AND INSPECTOR INSTRUCTED TO FOLLOW DRAWING CAREFULLY AND VERIFY CORRECT PART IS BEING INSTALLED.						
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION						
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input checked="" type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	33. UNKNOWN DEFECT CODE	
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR SAFETY	
37. RESPONSIBLE ENGINEER G. BENSON		ORG 41-33	DATE 7/21/81	38. SPACECRAFT SYSTEM ENGINEER RELIANCE		
39. RECALLABILITY G. KELVIN		ORG 51-4	DATE 7-23-81	39. TEST CENTER OR SUPPLIER D.R.		

HUGHES

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F 4836

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
61 SEGUNDO, CALIFORNIA

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. GLA E330		3. MODE FLIGHT		4. TIME OBSERVED 11:00 AM		5. DATE OBSERVED NOV 5 DA 13 YR 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SUBSYSTEM UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MECAM		<input type="checkbox"/> CARD <input type="checkbox"/> PARI			
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER									
7. SUBSYSTEM POWER SUPPLY 50869 4 HAC									
8. UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
9. <input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD									
10. OTHER									
11. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM									
12. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION AXIS FOR MIN TYPE <input type="checkbox"/> OTHER									
13. DESCRIPTION OF FAILURE WHILE UNIT WAS FUNCTIONING AT 35 VOLTS BUS IN OUTGAS MODE, FOR ABOUT 4 MINUTES, IT SHUT IT'S SELF "OFF" AND COULD NOT BE COMMUNED W. PRIMARY SIDE FAILED (CONDUCTANCE-OK)									
14. TEST PROCEDURE TS 16603 PARA 5.11.6 OPERATOR R. BECKER/BEVON ORG 4-33 DATE 5-13-81 CONTINUATION SHEET USED									
15. VERIFICATION AND FAILURE ANALYSIS CR3 IN 51566 ASSY & Q8 ON CHASSIS FAILED DURING TEST. DOMINANT FAILURE ANALYSIS ATTACHED.									
16. FOLLOWING REWORK/RETEST REQUIRED REWORK: INCORPORATE E.O. 2046A, ALL (8) DIODES IN BOTH A3 & A4 ASSY. 51566 CR1 THEN CR2, REPLACE CHASSIS TRANSISTORS Q5 THEN Q8. RETEST TS 16603 PAGE 5.11.6									
17. REWORK/RETEST ACTION TAKEN REWORK: INCORPORATE E.O. 2046A, INSTALL NEW DIODES IN BOTH A3 & A4 ASSY. 51566 CR1 THEN CR2, REPLACE CHASSIS TRANSISTORS Q5 THEN Q8. RETEST: TS 16603 5.11.6									
18. LIST ALL PARTS REPLACED									
PART NUMBER CXT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER									
908736-2 Q8 9C390505A 7952 CENTRAL SEMICONDUCTOR									
908736-3 CR3 7902HE SEATECH									
19. REWORK BY ELIASA BECKER ORG 41-33 DATE 6-15-81 RETESTED BY DELBERT CRAWFORD ORG 41-33 DATE 6-2-81 CONTINUATION SHEET USED									
20. CAUSE AND CORRECTIVE ACTION CAUSE: DESIGN DEFICIENCY IN THERMAL DISSIPATING PATH FOR DIODES ON ASSY 51566.									
21. CORRECTIVE ACTION C/A: REWORKED SUBASSY 51566 TO IMPROVE THERMAL PATH. TEMPERATURE TESTS AFTER REWORK INDICATED ACCEPTABLE 140°F MAX CASE TEMP. AT STEADY-STATE (FOOTNOTED).									
22. DOCUMENT IMPLEMENTING CORRECTIVE ACTION E.O. 2046A EFFECTIVITY SW 18 UP									
23. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT									
24. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
25. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY									
26. RESPONSIBLE ENGINEER E. SCARSON ORG 41-33 DATE 7/17/81									
27. SPACECRAFT SYSTEM ENGINEER R. BECKER ORG 2561 DATE 8/10/81									
28. RELEASING AUTHORITY R. BECKER ORG 57-41 DATE 10/20/81									
29. COS ZONE OR SUPPLIER 41-33									

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

F 4837

ORIGINATOR	1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. GLA E330	3. MODEL FLIGHT	4. TIME OBSERVED 2:00PM	5. DATE OBSERVED MO 5 DA 20 YR 81		
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
	EQUIPMENT IDENTIFICATION:							
	7. SUBSYSTEM		NAME		P. RT NUMBER		MANUFACTURER	
	8. UNIT POWER SUPPLY				50869		4 HAC	
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY							
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
	11. OTHER							
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ <input type="checkbox"/> THERMAL VAC _____ HRG AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER							
	14. DESCRIPTION OF FAILURE WHEN SYNC WAS TURNED "ON", UNIT WOULD NOT SYNC.							
	15. TEST PROCEDURE TS 16603							
	16. VERIFICATION AND FAILURE ANALYSIS SYNC SIGNAL WAS NOT GOING FROM MAIN BED TO MAIN BED, BECAUSE INTER-CONNECT CABLE DEVELOPED A SHORT AT THE SPICE OF THE CONDUCTOR AND SHIELD, WHICH IN TURN STRESSED A24-Q6 TRANSISTOR.							
	ENGINEERING EVALUATION	17. CONTINUATION SHEET USED						
		18. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE						
		REWORK SPICE BETWEEN CONNECTORS & REPLACE A24-Q6 P3-24 conductor to align to P6-22 and REWORK SHIELD P3-12 shield to align to P6-10. RETEST TS 16603, PARA 5.11.2						
		19. REWORK/RETEST ACTION TAKEN REWORK SPICE BETWEEN CONNECTORS P3 AND P6 AS MENTIONED IN DETAIL IN SECTION 20 & REWORK A24-Q6. RETEST PER TS 16603 PARA 5.11.2						
20. LIST ALL PARTS REPLACED								
21. CAUSE AND CORRECTIVE ACTION CAUSE: SPICE IN SHIELDED WIRE DEVELOPED SHORT DUE TO FLEXURE OF MAIN & MAIN PWB. CORRECTIVE ACTION: SECURE WIRING BETWEEN MAIN & MAIN PWB IN BUNDLES TO REDUCE STRESS BUILDUP IN SPICE DUE TO LOCAL FLEXURE. REFER TO BVD DATED 11/2/81								
22. DOCUMENT IMPLEMENTING CORRECTIVE ACTION (COPY ATTACHED)								
23. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> WFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSEMBLY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> SAFETY <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT								
24. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE								
25. RESPONSIBLE ENGINEER J. JENSON								
26. DATE 7/30/81								
27. RELIEF DATE 5/12/81								

[Handwritten signature]
10/22/81



SPACE AND COMMUNICATION GROUP
EQUIPMENT CHECKOUT
FAILURE REPORT
CONTINUATION SHEET

ORIGINAL PAGE IS
OF POOR QUALITY

F 4837 CONT. SHEET
PR SERIAL NO. LETTER

* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON
IDENTIFY ENTRIES BY REFERENCING PR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL PR
CONTINUATION
SHEET(S) USED


Responsible manufacturing supervisor has been informed by the REA as to the
proper workmanship methods to use to obtain proper wire dressing on future units.


Shaw 10/20/71

①

FAILURE REPORT # F4837

There was a shielded wire short, which put the center conductor at return ground potential. This short was in the inter-connecting harness, from MINI-Sw. to the MAXI-Sw. that carries the "sync signal"





AVOID VERBAL ORDERS

ORIGINAL PAGE IS
OF POOR QUALITY




TO	R. S. WILKERSON	SOURCE CODE	BLDG.	M/S	EXT.
FROM	G. BENSON	41 133 130	512	V329	8-0879
SUBJECT	SPICED WIRES ON FIT POWER SUPPLY.				DATE
					11/20/01

REFERENCE FAILURE REPORT # F 4837

ORIGINAL SPICE WAS INSTALLED PER AUTHORITY GRANTED UNDER DEVIATION D-068 "ACCEPTABILITY OF SPICED WIRES" APPLICABLE TO BOTH PROTOFLIGHT (SA-3) AND FLIGHT (W-4). WIRING WAS SECURED BY HARNESS TIE TO REDUCE FLEXURE DURING TEST. QA INSPECTED AND APPROVED ALL REWORK OPERATIONS (NAC/QA/BFOA)

G. BENSON
SIGNATURE

15 CS APR 79



FAILURE REPORT # F4837

A24-Q6 908839-1 (2N2222A) has a collector current maximum of 800 ma. Transistor Q6 base current was 5.6 ma with a collector current of 0.5 amps giving a beta of 89. Transistor Q6 is the only component in the 0.5 amp path that was overstressed, due to 12 volts at its collector and a current of 0.5 amps which is 6 watts dissipation before its emitter opened.


The diodes CR47 & CR48 of the MARI-Sw. (A23) 908702-2 (1N6081); these diodes are rated @ 2 amps @ 25° Centi ambient. Each diode carried 0.5 amps every half cycle for 70 milliseconds, which is insufficient time for the diode to heat up. Besides if the leads are at 70° Centi the diode can carry 12.0 amps ^{with} no stress to diodes.

The following two pages have a picture indicating the collector voltage on top trace @ 2V/DIV., Emitter current is the bottom trace @ 1amp/DIV. These pages also include the analysis of the choke L2 & the transformer T8, which indicated that the temperature rise in the wire of each component didn't exceed 0.05 degrees Fahren.

Conclusion is all components are all right but Q6 must be replace.

ORIGINAL PAGE IS
OF POOR QUALITY

FAILURE REPORT # F4837
(3)



2N2222

V_{CE} 2V/DIV

I_E @ 1A/cm

t=0

Wire size
XFMR #26 R = .225 Ω (XFMR 53563 (T8))

Choke #28 R = 1.05 Ω (CHOKE 53541 (L2))

Wire
XFMR #26 is 40.81 Ω / 10³ ft, .7692 # / 10³ ft

$$\frac{.7692 \text{ #/10}^3 \text{ ft}}{40.81 \Omega / 10^3 \text{ ft}} \times .225 \Omega = 4.24 \cdot 10^{-3} \text{ lbs/winding}$$

Choke #28 is 64.90 Ω / 10³ ft, .4837 # / 10³ ft

$$\frac{.4837 \text{ #/10}^3 \text{ ft}}{64.90 \Omega / 10^3 \text{ ft}} \times 1.05 \Omega = 7.826 \cdot 10^{-3} \text{ lbs/choke}$$

ORIGINAL PAGE IS
OF POOR QUALITY

FMLUBB REPORT
F4837

Dissipation

$$\text{XFMR } I^2 \cdot R \cdot \text{duty} \\ (.5A)^2 \cdot .225 \cdot \frac{1}{2} = 28.13 \text{ mW}$$

Choke

$$(.5A)^2 \cdot 1.05 \cdot 1 = 262.5 \text{ mW}$$

XFMR

$$\Delta t = \frac{3.416 \times 28.13 \cdot 10^{-3} \text{ W} \times 100 \cdot 10^{-3} \text{ sec} \times \frac{1 \text{ hr}}{3600 \text{ sec}}}{4.24 \cdot 10^{-3} \text{ lb} \times .092 \frac{\text{BTU}}{\text{LB } ^\circ\text{F}}}$$

$$\Delta t = 6.84 \cdot 10^{-3} \text{ } ^\circ\text{F}$$

Choke

$$\Delta t = \frac{3.416 \times 262.5 \cdot 10^{-3} \text{ W} \times 100 \cdot 10^{-3} \text{ sec} \times \frac{1 \text{ hr}}{3600 \text{ sec}}}{7.826 \cdot 10^{-3} \text{ lb} \times .092 \frac{\text{BTU}}{\text{LB } ^\circ\text{F}}}$$

$$\Delta t = 34.6 \cdot 10^{-3} \text{ } ^\circ\text{F}$$

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.4
MAINFRAME/ TOP MECHANICAL ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

2.4.1

2.4.1 Mainframe / Top Mechanical Assembly

2.4.1.1

No Performance data was taken at the subsystem level on this subsystem.

2.4.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.4.2
Acceptance Data

2.4.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.4.2.1
Configuration Lists

The "as built" configuration list for the Mainframe
and top mechanical assembly is included in the listing
for the overall system.

ORIGINAL PAGE IS
OF POOR QUALITY

Listing of Liens

There were no liens recorded against the
Mainframe/Top Mechanical Assembly.

ORIGINAL PAGE IS
OF POOR QUALITY

SECTION 2.5
AFT OPTICS ASSEMBLY

ORIGINAL PAGE IS
OF POOR QUALITY

2.5.1 Aft Optics Assembly

2.5.1.1

No performance data was taken at the subsystem level on this subsystem.

2.5.2

ORIGINAL PAGE IS
OF POOR QUALITY

2.5.2
Acceptance Data

2.5.2.1

ORIGINAL PAGE IS
OF POOR QUALITY

2.5.2.1
Configuration Lists

AS-BUILT CONFIGURATION LIST

AFT OPTICS ASSY

P/N 51512, S/N 003, FLIGHT

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	51512	AFT OPTICS ASSY	D + 3646A 3896A 3925A 3959A 4134A	D + 3646A 3896A 3925A 3959A 4134A	D + 3646A 3896A 3925A 3959A 4134A	003
2	50795	SILICON FOCAL PLANE ASSY	H + 3934A 3968A 3982A W-126	H + 3934A 3968A 3982A W-126	H + 3934A 3968A 3982A W-126	201
2	50843	AFT OPTICS SUPPORT	G	G	G	
2	51030	SCAN LINE CORRECTOR ASSY	E + 1012A 3823A 3956A	E + 1012A 3823A 3956A	E + 1012A 3823A 3956A	004
3	50820	TORQUE MOTOR, SLC	C	C	C	003
3	51035	MIRROR NO. 2, SLC	C	C	C	003
3	51037	MIRROR NO. 1, SLC	C	C	C	106
3	51040	FRAME ASSY-SLC	D	D	D	004
3	51887	TEMPERATURE SENSOR ASSY-SLC	B + 8689-N	B	B	401
2	51343	BLACKBODY & MOUNT ASSY	C	C	C	003
3	51346	BLACKBODY ASSY	D + 3906A	D + 3906A	D + 3906A	003
2	51364	TERMINAL BOARD ASSY	B	B	B	
2	51482	SHIM	B	B		

ORIGINAL PAGE IS
OF POOR QUALITY

N-REPRESENTS A NON-MANDATORY CHANGE


IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
2	51485	PRIME FOCAL PLANE ASSY	D	D	D	002
2	51495	CENTER BAFFLE ASSY	C	C	C	003
3	52733	BAFFLE ASSY, B3	C + 3942A W-139 W-143	B + 3942A W-139 W-143	B + 3942A W-139 W-143	003
W-143 waives planning for EO 8842 which when incorporated raised dwg from B to C.						
2	51496	CALIBRATION LIGHT SOURCE ASSY	D + 3960A 4170A	D + 3960A 4170A	D + 3960A 4170A	003
3	51497	LAMP SOURCE ASSY	B	B	B	044 069 113
3	51546	LIGHT SOURCE ASSY	D	D	D	001 002 003
3	52959	THERMISTOR ASSY	C	C	C	202
2	52249	REDUNDANT/RESTORE SHUTTER ASSY	F + D-134	F + D-134	F + D-134	003
3	52077	SHUTTER ARM ASSY-RED/RESTORE SHUTTER ASSY	C	C	C	003
3	52083	POSITION INDICATOR PICKOFF ASSY-RED/RESTORE SHUTTER	C	C	C	203 204 205
2	52500	CAL/RESTORE FAILSAFE ASSY	B + 1040A 2054A 3980A	B + 1040A 2054A 3980A	B + 1040A 2054A 3980A	003
3	51269	HEATER LINK ASSY	E + 3790A	E + 3790A	E + 3790A	003
2	52544	CAL/RESTORE SHUTTER ASSY	C + 3742A 3969A 3984A 4040A	C + 3742A 3969A 3984A 4040A	C + 3742A 3969A 3984A 4040A	003 PER NCMR 299682


ORIGINAL PAGE IS
OF POOR QUALITY

TRD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	52345	SHUTTER ARM ASSY-CAL/RESTORE SHUTTER ASSY	C + 9163 3871A 3940A 3958A 3992A 4017A W-139 W-141	C + 9163 3871A 3940A 3958A 3992A 4017A W-139 W-141	C + 9163 3871A 3940A 3958A ***** 4017A W-139 W-141	003
				*****W-141 waives missing planning for screw trim operation per EO 3992A		
4	51898	CAL/RESTORE FLAG ASSY	C	C	C	003
3	53517	CAL/RESTORE MOTOR ASSY	B + 3306A 3979A	B + 3306A 3979A	B + 3306A 3979A	002
4	52083	POSITION INDICATOR PICKOFF ASSY-CAL/RESTORE SHUTTER	C	C	C	201 202 206 207
4	52446	PWB ASSY, SHUTTER LED DRIVER	A + 7155 7498 7713 9359	A + 7155 7498 7713 9359	A + 7155 7498 7713 9359	101
2	52755	CABLE HARNESS, SLC, CAL LAMP, CENTER BAFFLE HEATER	C + 3614A	C + 3614A	C + 3614A	201
2	53285	CABLE HARNESS, FOCAL PLANE LED/ TELESCOPE BASEPLATE	B + 3694A	B + 3694A	B + 3694A	201
3	52753	THERMISTOR BLOCK ASSY	D + 3794A W-139	D + 3794A W-139	D + W-139	201
				*****W-139 waives conformal coat change as required per EO 3794A		
2	53649	CABLE ASSY MAIN & REDUNDANT SHUTTER	B + 8787 3695A	B + 8787 3695A	B + 8787 3695A	201
3	51787	THERMISTOR BLOCK ASSY	D + W-140	D + W-140	D + W-140	201

ORIGINAL PAGE IS
OF POOR QUALITYORIGINAL PAGE IS
OF POOR QUALITY

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEP. REVISION	AS-BUILT REVISION	SERIAL NUMBER
2	53694-1	BRACKET, CONNECTOR	B	B	B	003 004
2	53694-2	BRACKET, CONNECTOR	B	B	B	003 004
2	53883	BAFFLE, PRIMARY	A	A	A	
2	54218	SHUTTER STOP ASSY	A	A	A	003
2	54360	WASHER, FLAT	A	A	A	
2	54361	SCREW, RELIEVED	A	A	A	
2	54362	WASHER, FLAT	A	A	A	
2	54363	PIN, DOWEL	A	A	A	
2	54504	GROUND WIRE	A	A	A	201 202 203
2	54511	SPACER	A	A	A	
2	54562	SHIM	A + 3771A	A + 3771A	A + 3771A	

 3-12-82
Quality Assurance


Configuration Management Office

ORIGINAL PAGE IS
OF POOR QUALITY

2.5.2.2

Listing of Liens

**ORIGINAL PAGE IS
OF POOR QUALITY**

AFT OPTICS ASSEMBLY

P/N 51512

FLIGHT

ORIGINAL PAGE IS
OF POOR QUALITY

Failure Reports Number

<u>Open</u>	<u>Closed</u>
S8128	F0554
S8129	S8361
	S8362
	S8378
	S8387
	S8469
	S8130

Deviations

Waivers

D-134	
-------	--

AFT OPTICS ASSY.
P/N 51512

ORIGINAL PAGE IS
OF POOR QUALITY

FLIGHT	PROTOFLIGHT	ENGINEER	LTM
Failure Report No.	Failure Report No.	Failure Report No.	Failure Report No.

Open	Closed	Open	Closed	Open	Closed	Open	Close
S8128	F0554		F0569		F0506		
S8129			F0570		F0524		
	S8130		F1730		F0540		
	S8361		F1738				
	S8362		F1743				
	S8378		F1750				
	S8387		F1751				
	S8469		F1758				
			F2364				
			F2381				
			F2386				
			F2658				
			F2659				
			F2687				
			S8005				
			S8086				
			S8087				
			S8088				

ORIGINAL PAGE IS
OF POOR QUALITY



SPACE AND COMMUNICATION GROUP
FAILURE REPORT

F 0554

1. PROGRAM NAME AND NUMBER TM H5-236		2. CLAS F330	3. MODEL F-1	4. TIME OBSERVED	5. DATE OBSERVED MO 2 DA 9 YR 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> AIRCRAFT <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
8. EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT		AET OPTICS ASST		51912	003
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		SCAN LINE CORRECTOR		51030	003 S/N 002
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROGRESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> VIBRATION <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/EMI <input type="checkbox"/> VIBRATION					
14. DESCRIPTION OF FAILURE SLC FUNCTIONAL TEST, AFR 91512 OPERATION 17300, PIN STOP, & TO12 RESISTANCE SHOULD BE 4 KΩ ±20% RESISTANCE MEASURES 5.7 KΩ					
16. TEST PROCEDURE		18. ORIGINATOR W. Bahinski	19. DATE 12-25 12/8/82	20. CONTINUATION SHEET USED	
18. VERIFICATION AND FAILURE ANALYSIS 5.7 KΩ INDICATES RESISTOR IS IN CIRCUIT BUT THERMISTOR IS NOT. VISUAL INSPECTION VERIFIES LOOSE WIRE ON TERMINAL. VISUAL INSPECTION SHOWED S/N 002 SLC IN AOB. S/B S/N 004.					
20. FOLLOWING REWORK/RETEST REQUIRED REMOVE SLC S/N 002 AND INSTALL S/N 004 REPAIR LOOSE WIRE ON S/N 002					
21. AUTHORIZATION W. Bahinski ORG 122-35 DATE 13-5-82 22. CONTINUATION SHEET USED					
23. REWORK/RETEST ACTION TAKEN SLC 002 REMOVED. S/N 004 INSTALLED. RETEST TO TP 16659 Rev. D. LOOSE WIRE ON SLC RESOLDERED					
24. 24.1A REWORK					
24. 24.2A RETEST					
25. LIST ALL PARTS REPLACED					
PART NUMBER	QTY	S/N	PART LOT NO.	DATE CODE	DEFECT
51030					WRONG S/N UNIT
27. REWORK BY ORG DATE 28. RETEST BY ORG DATE 29. CONTINUATION SHEET USED					
30. CAUSE AND CORRECTIVE ACTION POOR WORKMANSHIP ON S/B S/N 002 (LOOSE WIRE) CAUSE OF INSTALLATION OF WRONG S/N SLC THE DISCREPANCIES HAVE BEEN BROUGHT TO THE ATTENTION OF ALL PERSONNEL INVOLVED IN PLANNING AND FABRICATION TO ELIMINATE SIMILAR ERRORS IN THE FUTURE. PRODUCTION CONTROL ASSEMBLY AND QUALITY CONTROL					
31. 31.1B CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input checked="" type="checkbox"/> MFG. PROCEDURES <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER W. Bahinski ORG 122-35 DATE 13-5-82		38. SPACECRAFT SYSTEM ENGR. W. Bahinski ORG 122-41 DATE 13/5/82			
39. RELIABILITY W. Bahinski ORG 151-41 DATE 13-5-82		40. CUSTOMER OR SUPPLIER W. Bahinski ORG 151-41 DATE 13/5/82			

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
25, LEGUONDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8130

1. PROGRAM NAME AND NUMBER <i>PL 1162</i>		2. CLA		3. MODEL <i>FLY 1</i>		4. TEST OBSERVED <i>1900</i>		5. DATE OBSERVED <i>MO 4 DA 13 YR 92</i>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> ESCAL		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER									
7. SUBSYSTEM									
8. UNIT <i>AMP SOURCE ASSEMBLY, Colib Light</i> <i>51497</i>									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> ESCAL <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEMS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> INTERNAL VIB <input type="checkbox"/> HUMIDITY <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AND FOR <input type="checkbox"/> ICR TYPE <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <i>Col Lamp 2 is drawing 109.4 mA. and should draw 108 mA. also Col Lamp 3 is drawing 110.1 mA and should draw 108 mA.</i>									
15. TEST PROCEDURES <i>73201-532</i> <i>5.2.2.1</i> <i>Reference</i> <i>PLR 44-92</i> <input type="checkbox"/> CONTINUATION SHEET USED									
16. VERIFICATION AND FAILURE ANALYSIS <i>PROBLEM WAS A SOFTWARE TOLERANCE BASE DISCREPANCY. CHANGES WERE REQUIRED TO CHANGE COEFFICIENTS IN DATA BASE 223</i>									
17. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>SOFTWARE CHANGES ARE REQUIRED.</i>									
18. AUTHORIZATION <i>E.C.R 972732 TO CHANGE COEFFICIENTS WAS REFLECTED.</i>									
19. REWORK/RETEST ACTION TAKEN <i>RETURNED TO 104.4 mA FOR COL LAMP 2, 106.4 mA FOR COL LAMP 3.</i>									
20. LIST ALL PARTS REPLACED PART NUMBER CITY YES PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER									
21. REWORK BY ORG DATE 22. RETESTED BY ORG DATE 23. CONTINUATION SHEET USED									
24. CAUSE AND CORRECTIVE ACTION <i>CAUSED BY USING INCORRECT COEFFICIENTS IN DATABASE.</i> <i>DATABASE UPDATED BY E.C.R 972732</i>									
25. DOCUMENT IS/IS NOT CORRECTIVE ACTION <i>E.C.R 972732 (COPY ATTACHED)</i>									
26. BASIC CAUSE OF VIBRATION FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP									
27. FAILURE TYPE <input checked="" type="checkbox"/> PRESENTATION <input type="checkbox"/> INTERMITTENT <input type="checkbox"/> REPEATED									
28. RESPONSIBLE ENGINEER <i>Chasment</i> <i>51497-7-0</i> <i>5/10/92</i> <i>41182</i>									

SOFTWARE

ORIGINAL PAGE IS OF POOR QUALITY

ENGINEERING CHANGE REQUEST

HUGHES

CODE IDENT 82877

ECR NO. 58130 972732

SHEET 1 OF SHEETS

REQUEST

PROGRAM Thematic Mapper	SYS/EQUIP NAME OR DES TLM Data Bases CONF 2,3	CONTROL ITEM NAME & NO. coefficient changes on Cal Imp Crnts	SPECIFICATION/DWG NO.(S)
----------------------------	--	---	--------------------------

DESCRIPTION OF PROBLEM

Changes need to be performed on the Cal Imp Crnt coefficients in the telemetry data Bases 2 & 3. for FI work.

PROPOSED SOLUTION

Parameter	old value	New Value
81	.671769	.6694
82	.710553	.6694
84	.710553	.6694

REQUESTED BY <i>Ron Henge</i>	EXT 6265	BLDG, FLS B7/40	ORG CODE 22-41	DATE 9/20/82	URGENCY ASAP
APPROVED <i>KW Hubbard</i>	6168	01/10	22-41	5/13/82	RECM EFF 51065 SN
APPROVED <i>W.D. Adams</i>	6293	B7/39	51-41	5/13/82	003 & SUBQ

DISPOSITION

<input checked="" type="checkbox"/> ACCEPTED	REASON FOR REJECTION	DATE RECD IN ECC	SCH REPLY DATE	ADVANCE <input type="checkbox"/>
<input type="checkbox"/> REJECTED				

CHANGE CLASS <input type="checkbox"/> I <input checked="" type="checkbox"/> IIA <input type="checkbox"/> IIB	SPECIFICATION OF CONTROL ITEM	RESP SPEC ACT. OR RESP ENGRG ACT.	ECA NUMBER
DOCUMENT NO.(S) FOR IIB CHANGE			

ORG CODE	DATE	ORG CODE	DATE	RESP ENGRG ACT.	ORG CODE	DATE
				<i>Ron Henge</i>	22-03	5-20-8
				<i>W.D. Adams</i>	22-41	4/20/82

CLASS IIB RELEASE AUTHORIZATION

CHANGE EFFECTIVITY	CONTRACT NO.	MANUFACTURING	DATE
DISPOSITION OF ITEMS	CUSTOMER	ENGRG CHANGE CTR	DATE
		<i>W.D. Adams</i>	5-25-82

T. J. Adams 5/24/82

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8361

1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. GLA	3. MODEL F-1	4. TIME OBSERVED 11:00	5. DATE OBSERVED MO 1 DA 6 YR 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME P.W.T. NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT					
9. ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input checked="" type="checkbox"/> REDUNDANT/RESERVE SWITCHES P.W.T. NUMBER 52249 S/N 003 MANUFACTURER SRRC					
10. MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> ENG/RR <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR MIN TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE SHUTTER NATURAL PERIOD HAS CHANGED - IS PRESENTLY OUT OF SPEC. WAS 143.17, IS 143.56 171.					
15. TEST P. NO. 14295314 PARA 10 ORIGINATOR W. BALINSKI ORG 22-35 DATE 82-1-6 17. CONTINUATION SHEET USED <input type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS SHUTTER DOES NOT EXHIBIT SENSITIVITY TO MOUNTING SCREEN TORQUE - NO OTHER CHANGES HAVE BEEN MADE SINCE MOTOR PERIOD WAS IN SPEC. CHANGE IS ASSUMED TO BE RESULT OF DRIFT DURING FIRST FEW HOURS OF OPERATION.					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE RETRIM INERTIA TO LOWER NATURAL PERIOD TO WITHIN SPEC.					
20. AUTHORIZATION W. Balinski ORG 22-35 DATE 82-1-6 22. CONTINUATION SHEET USED <input type="checkbox"/>					
21. REWORK/RETEST ACTION TAKEN INERTIA TRIM WEIGHTS CHANGED IN ORDER TO LOWER SHUTTER INERTIA 24. ORG 22-35 DATE 82-1-6 27. CONTINUATION SHEET USED <input type="checkbox"/>					
23. LIST ALL PARTS REPLACED PART NUMBER CKT JYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER					
27. REWORK BY MS [Signature] ORG 22-74 DATE 1-9-82 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED <input type="checkbox"/>					
30. CAUSE AND CORRECTIVE ACTION DRIFT DURING FIRST FEW HOURS OF SHUTTER OPERATION IS APPARENT CAUSE OF SHIFT IN PERIOD. SHUTTER ASSY PLANNING WILL BE MODIFIED TO INCLUDE 12 HOURS RUN IN TO STABILIZE MOTOR NATURAL PERIOD. PLANNING HAS BEEN CHANGED ON AHR (ATTACHED) OPER 7800 SIC# 22-74.					
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION AHR DIED 6-30-80/SUPPLEMENT 1-6-82					
32. BASIC USE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input checked="" type="checkbox"/> UNKNOWN DEFECT CODE					
33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
34. RESPONSIBLE ENGINEER W. Balinski ORG 22-41 DATE 82-1-20 35. SPACECRAFT SYSTEM ENGINEER [Signature] ORG 22-41 DATE 1/20/82					
36. RELIABILITY [Signature] ORG 22-41 DATE 1-20-82 37. TESTER OR SUPPLIER [Signature] ORG DATE					

167/72

SBRC

ASSEMBLY HISTORY RECORD SUPPLEMENT

SHEET 1 OF

PART NUMBER 52249	SERIAL OR LOT NUMBER 003	GRADING NO. 52249	DRAWING DIVISION F	Q&A SOURCE CODE 22-35	PREPARED BY F. Saucier	SUPPLEMENT NO. 5 TO AIR DATED 6-30-80
ASSEMBLY NAME			APPLICABLE TO	DESIGN APPROVAL <i>W. Balinski</i>	QUALITY APPROVAL <i>W. Balinski</i>	SUPPLEMENT RELEASE DATE 82-1-6
PURPOSE OF SUPPLEMENT - INCORPORATES NEW ASSY DWG REVISION <input type="checkbox"/> OR EOs <input checked="" type="checkbox"/> REWORK <input checked="" type="checkbox"/> ; OTHER <input type="checkbox"/> EXPLAIN Adjust period per dwg. notes 6 & 7 and Spec. 16781 Ref: FR 8361				PRELIMINARY APPROVAL <i>F. Saucier</i>	POSTING APPROVAL <i>W. Balinski</i>	NOTE TO PRODUCTION - UPON RECEIPT, ENTER SUPPLEMENT NO. AND RECEIPT DATE ON FRONT SHEET OF AMB. INITIAL THE ENTRY.

NOTES: 16781 Rev. A EO 8293, 8312, 8666, 3647A
76440 Rev. C EO 2371A, 2968A, 3136A, 3293A, 3658A

OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY			REMARKS
			OPER	INSP	DATE	
		-NOTE- ALL OPERATIONS ARE TO BE PERFORMED IN A CONTROLLED CLEAN AREA SUCH AS A LAMINAR FLOW BENCH, EXCEPT WHEN ENVIRONMENTAL CONDITIONS DUE TO THE NATURE OF THE OPERATION ARE DIFFICULT TO CONTROL: THESE MAY INCLUDE TRANSPORTATION PLATING, SOLDERING, POTTING, MEASUREMENT, PAINTING AND MACHINING. Q.A. SURVEILLANCE IS REQUIRED FOR ALL OPERATIONS NOTED. CLEAN LINT FREE GLOVES FREE FROM ALL CONTAMINANTS MUST BE WORN AT ALL TIMES, EXCEPT WHEN NOTED OTHERWISE. SEQUENCE OF OPERATION MAY NOT BE ALTERED EXCEPT AT THE DISCRETION OF THE REA.				

ORIGINAL PAGE 10
OF POOR QUALITY

58361

GBRC

ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 2

PART NUMBER		SERIAL OR LOT NUMBER	ASSEMBLY NAME	CONTINUATION OF:		
52249		003	Redundant/Restore Shutter Assy.-Aft Optics Assy.-TM	AHR DATED AHR SUPPLEMENT NO. 5		
OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY			REMARKS
			OPER	INSP	DATE	
100	22-74	ASSEMBLE SHUTTER ASSEMBLY TO BALANCE FIXTURE NAS2770-29351	<i>Burd</i>		<i>1/7/82</i>	
200	22-13 22-74	CONNECT SHUTTER MOTOR TO TEST BOX PER SPEC. 16781. PARA 3.9 USE WEAR SAVER 76440-2 AT SHUTTER MOTOR CONNECTOR INTERFACE.	<i>LK</i>		<i>1/7/82</i>	
300	22-13	CHECK PERIOD OF OSCILLATION AND RECORD. <i>Resonant Period = 143.6 ms</i>	<i>LK</i>		<i>1/7/82</i>	
400	22-74	RELEASE TORQUE FROM MOUNTING SCREWS AND ADJUST TO PRE-TORQUE CONDITIONS	<i>Wimmer</i>		<i>1/7/82</i>	

ORIGINAL PAGE IS
OF POOR QUALITY5
8361



ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 3

PART NUMBER		SERIAL OR LOT NUMBER	ASSEMBLY NAME			CONTINUATION OF:	
52249		003	Redundant/Restore Shutter Assy.-Aft Optics Assy. TM			AHR DATED AHR SUPPLEMENT NO. 5	
OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY			REMARKS	
			OPER	INSP	DATE		
500	22-13	CHECK PERIOD OF OSCILLATION AND RECORD. COMPARE WITH RESULT OBTAINED IN OPER. 300 <i>Resonant Period = 143.6 ms</i>	<i>QX</i>		<i>1/7/82</i>		
510	22-74	TORQUE MOUNTING SCREWS TO 11 IN-LB \pm 10%.	<i>Burd</i>		<i>1/9/82</i>		
600	22-74	PERFORM INERTIA TRIM PER DRAWING NOTES 6 & 7 AND SPEC. 16781 REV. <i>A</i> PARA 3.9, 3.10 AND 3.11	<i>Burd</i>		<i>1/9/82</i>	<i>143.06 ms</i>	
700	51-41	QA VERIFY PERIOD	<i>RU</i>	<i>(172)</i>	<i>1/9/82</i>		
800	22-74	ROUTE TO ELECTRONICS AND RUN SHUTTER UNTIL PERIOD IS CONSTANT OVER 12 HOURS (RUN-IN NEED NOT BE CONTINUOUS). <i>Resonant Period Before = 143.07</i> <i>Resonant Period After = 143.07</i>	<i>Burd</i> <i>QX</i>		<i>1/9/82</i> <i>1/13/82</i>		

ORIGINAL PAGE IS
OF POOR QUALITY

5-8361

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8362

ORIGINATOR	1. PROGRAM NAME AND NUMBER THEMATIC MAPPER		2. GLA	3. MODEL F-1	4. TIME OBSERVED 4:00	5. DATE OBSERVED MO 1 DA 18 YR 82	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART						
	EQUIPMENT IDENTIFICATION:						
	7. SUBSYSTEM		NAME	PART NUMBER	S/N	MANUFACTURER	
	8. UNIT AFT OPTICS ASSEMBLY		51512	003			
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY REDUNDANT SHUTTER		52249	003	SBRC		
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
	11. OTHER						
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM						
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ THERMAL VAC _____ HRG AT _____ <input type="checkbox"/> EMC/RR <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER						
	14. DESCRIPTION OF FAILURE SHUTTER NATURAL PERIOD HAS CHANGED - IS PRESENTLY OUT OF SPEC. WAS 143.07 MSEC - IS 143.07 MSEC 143.56						
ENGINEERING EVALUATION	15. TEST PROCEDURE		PARA	16. ORIGINATOR W. Beland	URG	DATE 82-1-18	
	17. CONTINUATION SHEET USED <input type="checkbox"/>						
	18. VERIFICATION AND FAILURE ANALYSIS SHUTTER EXHIBITS SENSITIVITY TO MOUNTING SCREW TORQUE LOOSENING, RETORQUE OF SCREWS DOES NOT, HOWEVER, BRING PERIOD WITHIN SPEC. EXPECT THAT EXCESSIVE TORQUE HAS CAUSED SLIGHT DEFORMATION OF MOTOR HOUSING.						
	19. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE BELIEVE ANY LOADS ON FLEX PIVOTS BY LOOSENING CLAMP SCREW ON FLEX PIVOT. RETAIN INERTIA AS REQUIRED.						
	20. AUTHORIZATION W. Beland		ORG	DATE	21. CONTINUATION SHEET USED <input type="checkbox"/>		
MANUFACTURING AND TEST	22. REWORK/RETEST ACTION TAKEN PER 51512 AHR COMMENT SHEET (DR 7210-7220) LOOSENED AND RETIGHTENED CLAMP SCREW ON FLEX PIVOT. PERIOD NOW 142.95 MSEC. NO FURTHER ACTION REQUIRED (SPEC CALLS FOR 142.9 ±.3 MSEC)		23. LIST ALL PARTS REPLACED		24. CONTINUATION SHEET USED <input type="checkbox"/>		
	PART NUMBER	CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	
	25. CONTINUATION SHEET USED <input type="checkbox"/>						
ENGINEERING/RELIABILITY	26. REWORK BY AS R...		ORG 22-74	DATE 1-19-82	27. RETESTED BY		
	28. CAUSE AND CORRECTIVE ACTION EXCESSIVE FRICTION TORQUE ON ONE OF TWO NUTPLATES CONTRIBUTED TO APPLICATION OF EXCESSIVE CLAMP LOADS ON MOTOR HOUSING. THIS CAN IMPACT A SLIGHT LOAD UPON FLEX PIVOTS, CHANGING DYNAMIC CHARACTERISTICS. NUTPLATES SHOULD BE CHECKED FOR EXCESSIVE TORQUE, REWORKED AS REQUIRED. WORKMANSHIP ERROR OPERATOR		29. THE CLOSURE		30. CONTINUATION SHEET USED <input type="checkbox"/>		
	31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION CAUTION TO USE MORE CARE.						
	32. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/PAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> SECONDARY		34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		
35. RESPONSIBLE ENGINEER W. Beland		ORG	DATE 82-1-20	36. CUSTOMER OR SUPPLIER			
37. RELIABILITY GOOD		ORG SI-41	DATE 1-20-82	38. DATE 22-4 1/20/82			

15782

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8378

ORIGINATOR	1. PROGRAM NAME AND NUMBER TM, HS-236		2. GLA		3. MODEL F1+		4. TIME OBSERVED 11 AM		5. DATE OBSERVED MO Jan DA 19 YR 82		
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER		
	8. UNIT										
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		AFT OPTICS ASSY		51512		003				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD										
	11. OTHER										
	12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/>		
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		TEMP _____ °C AXIS FOR _____ MIN TYPE _____		THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> OTHER _____		
	14. DESCRIPTION OF FAILURE		Resistance Measurements per spec 17068 were too high in some cases. See continuation sheet.								
	15. TEST PROCEDURE 17068		PARA 3.2.2		16. ORIGINATOR E. Aasted		ORG 22-15		DATE 1-20-82		17. CONTINUATION SHEET USED <input type="checkbox"/>
	18. VERIFICATION AND FAILURE ANALYSIS		Sheet 13 measurement - Spec Error - See EO 4075A sheets 10, 11, 12, 14, 15, 16 measurements - Open ground 17 PFA								
19. FAILED ITEM NAME AND PART NUMBER											
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		Repair open ground and remeasure resistance									
21. AUTHORIZATION		ORG Comment sheets, 507A		DATE		17. CONTINUATION SHEET USED <input type="checkbox"/>		22. CA REWORK <input checked="" type="checkbox"/>			
23. REWORK/RETEST ACTION TAKEN		Open ground repaired and remeasured. See Comment sheets, Assy 51512, 1/22 and 1/23/82 & Comment sheets, Assy 50795 1/23/82, 1/24/82 & 1/24/82. (COPIES ATTACHED)									
24. LIST ALL PARTS REPLACED		PART NUMBER		CXT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
25. PROBABLE DEFECT		ANALYSIS NUMBER									
26. REWORK BY		ORG Bill O'Donnell		DATE 1/22-1/23/82		27. RETESTED BY		ORG Bill O'Donnell		DATE 1-22, 1-23-82	
28. CAUSE AND CORRECTIVE ACTION		CAUSE: ITEMS 14.1, 14.2, 14.3, 14.5, 14.6 & 14.7 LISTED ON ATTACHED CONTINUATION SHEET. OPENS WERE CAUSED BY LOOSE SCREWS THAT HOLD THE PFA TO THE AFT OPTICS HOUSING.									
29. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		EO 4075A EFFECTIVE 12/20/82 & S.A.									
30. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE	
31. FAILURE TYPE		<input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		32. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
33. RESPONSIBLE ENGINEER		ORG W. Balinski		DATE 2-19-82		34. SPACECRAFT SYSTEM ENGINEER		ORG W. Balinski		DATE 2-22/82	
35. RELIABILITY		ORG W. Balinski		DATE 2-20-82		36. CUSTOMER OR SUPPLIER		DATE			

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT
CONTINUATION SHEET

FR SERIAL NO. 5 8378
CONTINUATION SHEET LETTER A

*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON
 IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY. ADDITIONAL FR CONTINUATION SHEETS USED

14. The following measurements were too high

	Sheet of Spec 17068	From	To	IS	S/B
14.1	10	C4	WIP30-C4	Checking Cap OPEN	< 500Ω
14.2	11	C4	WIP30-C4	" OPEN	"
14.3	12	"	"	" OPEN	"
14.4	13	"	"	18Ω	< 12Ω
14.5	14	"	"	Checking Cap OPEN	< 500Ω
14.6	15	"	"	" OPEN	"
14.7	16	"	"	" OPEN	"

Released 2/20/82

30. ITEM 14.4 ABOVE.
 Cause: ERROR IN SPEC. 17068.
 SA EO 4275A CORRECTS SPEC. ERROR. (COPY ATTACHED.)
Released 2/20/82

HUGHES

HUGHES AIRCRAFT COMPANY
SPACE AND COMMUNICATIONS GROUP
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP
FAILURE REPORT

ORIGINAL PAGE IS
OF POOR QUALITY

S 8387

1. PROGRAM NAME AND NUMBER TM		2. GLA	3. MODEL Flight	4. TIME OBSERVED 4:00 PM	5. DATE OBSERVED MO 2 DA 12 YR 82
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT		A4 Optic Bulkhead		51512	003
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP _____ ° <input type="checkbox"/> THERMAL VAC _____ HRS AT _____ <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION _____ AXIS FOR _____ MIN TYPE _____ <input type="checkbox"/> OTHER _____					
14. DESCRIPTION OF FAILURE All 10K thermistor readings do not agree with spec. 4K thermistor also does not meet spec.					
15. TEST PROCEDURE 17068		16. PARA 32.2.1	18. ORIGINATOR Joe Kleber	19. ORG 22-13	20. DATE 2/12/82
17. CONTINUATION SHEET USED <input type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS Required values shown in 17068 are valid for TTF only. Measurements were made at 69°F. When adjusted per specification 16117, values were well within prescribed tolerance limits.					
19. FAILED ITEM NAME AND PART NUMBER					
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE see 18 above					
21. AUTHORIZATION					
22. REWORK/RETEST ACTION TAKEN None					
23. CONTINUATION SHEET USED <input type="checkbox"/>					
24. QA REWORK					
25. QA RETEST					
26. LIST ALL PARTS REPLACED		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
None					
27. REWORK BY N/A		ORG	DATE	28. RETESTED BY	ORG
29. CONTINUATION SHEET USED <input type="checkbox"/>					
30. CAUSE AND CORRECTIVE ACTION SPEC. LIMITS WERE NOT STATED FOR TEMPERATURES OTHER THAN 77° EO 446A PROVIDES A METHODOLOGY FOR CALCULATING RESISTANCE VALUES AT TEMPERATURES DIFFERING FROM 77°					
31. FRB CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION EO 446A (EFFECTIVITY 54 007 sup) ATTACHED					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAO ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
36. RESPONSIBLE ENGINEER W. Balawski		ORG 22-35	DATE 2-19-82	37. SPACECRAFT SYSTEM ENGINEER J. Long	DATE 22-41 2/24/82
38. RELIABILITY J. Long		ORG 51-41	DATE 2-24-82	39. REPUTOR OR SUPPLIER H. G.	

2/24/82

END

DATE

FILMED

AUG 5 1983