U.S. Department of Transportation National Highway Traffic Safety Administration

December 5, 2016

Mr. Joshua Chard Director, Corporate and Product Safety Altec Industries Inc. 210 Inverness Center Drive Birmingham, AL 35242

Subject: Cylinder End Gland may Fail and cause Boom to Move

Dear Mr. Chard:

This letter serves to acknowledge Altec Industries Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: ALTEC/AERIAL DEVICE/1995-1999

Mfr's Report Date: November 15, 2016

NHTSA Campaign Number: 16V-835

**Components:** EQUIPMENT

Potential Number of Units Affected: 2,194

## **Problem Description:**

Altec Industries Inc. (Altec) is recalling certain model year 1995-1999 Aerial Device trucks manufactured May 1, 1995, to August 15, 1999 and equipped with Rosenboom Machine and Tool lower boom lift cylinders. The cylinder end gland could fail which could cause uncontrolled boom movement.

## **Consequence:**

Uncontrolled boom movement may increase the risk of injury to the operator or bystanders.

## **Remedy:**

Altec will notify owners, and dealers will inspect the boom, and repair or replace the cylinder, free of charge. The recall is expected to begin January 9, 2017. Owners may contact Altec customer service at 1-205-991-7733.

## Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 16V-835

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

