


KYSOR STYLE REPLACEMENTS

The High-Torque 8901N / 8905N

Long-lasting friction plus our two o-ring shaft combine for ultimate performance




8801X Shaft Design allows for
DUAL SEAL PROTECTION

Urethane O-Ring

Viton® O-Ring

Extended shaft allows for the addition of a urethane o-ring for resilience to motion, and a Viton® o-ring to create a superior air barrier.

- Torque Rated for 30" Fans and Larger
- Redesigned Shaft for Dual Seal Protection
- Superior O-Ring Materials
- Higher Quality Lining
- Truer Air Shaft
- 200,000 Mile – 24 Month Warranty




We Stock REAR-AIR HUBS
Call for Availability

K5 8001N

Reman Use K5 8901N

Front Air

Rebuild with kit # K5 8000SKL




OEM# 1090-07050-01, 1090-08000-01, 1090-09000-01

K5 8005X

Reman Use K5 8905N

Front Air

Rebuild with kit # K5 8000SKL



OEM# 1090-07050-03, 1090-08000-05, 1090-09000-05


K5 8801X

Reman Use K5 8901N

Rear Air

Rebuild with kit # K5 8000SKL

Most common 2003-Present




OEM# 1090-08500-01, 1090-09500-01, 1090-09600-01, 1090-09650-01, 9908500, 9908501



Kysor On/Off Fan Clutches by BorgWarner®

Dependable, durable and easy to maintain. Fewer moving parts combined with the Powerwedge liner equals longer fan clutch life.



K5 1090-09750-01

Rear Air ON/OFF Fan Clutch – 5" Fan Pilot

K5 1090-09650-01

Rear Air ON/OFF Fan Clutch – 2.56" Fan Pilot



K5 8901N

2.56" FAN PILOT
New



K5 8905N

5.00" FAN PILOT
New

DUAL SEAL PROTECTION:

Extended rear-air shaft allows for a second o-ring. This second o-ring is made from urethane which is resistant to wear caused by motion.

A TRUE FAIL-SAFE DESIGN:

Patented Auto Lock feature AUTOMATICALLY ENGAGES the fan clutch when the friction material nears the end of its life, preventing on-the-road failures.

INDUSTRY-BEST WARRANTY:

3 year / 300,000 mile warranty.

8901N OEM# : 8801x, 10900950001, 1090-09500-01, 10900850001, 1090-08500-01, 10900960001, 1090-09600-01, 10900965001, 1090-09650-01, 10900965001B, 1090-09650-01B, 10900960001B, 1090-09600-01B, 9908500, 2509380c91, 2514343C91, 2602141c91, 3415013, 3915592, 85111808, 85108716, 85114233, 85134489, f8hz8a627ua, f8hz-8a627-ua, 9908503, 9908501, 10900950001, 1090-09500-01B, 2501022c91, 65140701, 6514-070-1

8905N OEM# : 10900995001, 1090-09950-01, 10900995001B, 1090-09950-01B, 10900990001B, 1090-09900-01B, 10900990001, 1090-09900-01, 10900975001, 1090-09750-01, 10900975001B, 1090-09750-01B